

City of Fort Pierce

Department of Building & Code Enforcement

Marc Meyers, CBO, Building Official
Peggy Arraiz, Code Compliance Manager



PROPERTY MAINTENANCE INSPECTION REPORT

Property Address: 513 (519) N 13th St. Unit #: A & B

Landmarks / House color: White & light blue trim duplex

Number of Living Units / Rooms: 2 Building Occupied? No

Type of Structure Duplex Describe

Number of Entrances / Exits: 4

Electrical Meter #(s):

Action to be Taken: Days to comply

Inspector: Date Inspected: 1-23-17

For Office Use Only

Case # Parcel ID #: 2409-502-0006-000-4

Any active code cases? Yes Historic?

Active building permits? Permit #:

- 1. Eligible for demolition if repairs aren't made in a timely manner.
- 2. Existing case with fines 13-2096.
- 3. SLCFD reported the address as 519 N 13th St.

EXTERIOR INSPECTION

- 302.3 Sidewalks and driveway are in need of repair
Details

- 302.6 Exhaust vents are hazardous to another property
Details

- 302.7 Accessory structures require maintenance
Details

- 302.9 Graffiti needs to be removed
Details

- 303.1 Swimming pool needs to be maintained
Details

- 303.2 Swimming pool barrier not up to code
Details

- 304.4 Structural members damaged / unsafe
Details

- 304.5 Foundation walls damaged / unsafe
Details

- 304.6 Exterior walls damaged / unsafe
Details

304.7 Roofs & roof drainage damaged / unsafe
Details

304.9 Overhang extensions damaged / unsafe
Details

304.10 Stairways, decks, porches and balconies damaged / unsafe
Details

304.11 Chimneys and towers damaged / unsafe
Details

304.12 Handrails and guards damaged / unsafe
Details

304.13 Window, skylight, doors and door frames damaged / unsafe
Details

304.14 Window insect screens missing / damaged
Details

304.17 Basement window guards missing / damaged
Details

304.18.1 Doors - deadbolt missing / damaged
Details

304.18.2 Windows - locks missing / damaged
Details

INTERIOR INSPECTION

305.2

Structural members damaged / unsafe

Details

305.4

Stairs and walking surfaces damaged / unsafe

Details

305.5

Stair handrails damaged / unsafe

Details

305.6

Interior doors damaged / unsafe

Details

306.1

Handrails not installed / not to code

Details

402.1

Habitable space does not have an approved window

Details

402.2

Common halls / stairway missing required light source

Details

403.2

Bathrooms do not have sufficient ventilation

Details

403.5

Clothes dryer exhaust not installed to code

Details

404.2 -
404.7

Minimum housing requirement violations exist

Details

502.1 Dwelling units not to code (missing bathroom or kitchen facilities)
Details

503.1 Bathroom does not have door / no privacy
Details

504.1 Plumbing not to code
Details

505.1 - 505.3 Water system unsafe / contaminated
Details

506.1 Plumbing system not property connected to sewage system
Details

506.2 Plumbing stack, vent, waste & sewer line damaged / unsafe
Details

602.2 - 602.4 No heating facilities provided / heating facilities not working
Details

603.1 Appliances not installed properly / unsafe
Details

603.4 Safety controls for fuel-burning equipment missing / damaged
Details

605.1 Electrical equipment, wiring and appliances damaged / unsafe
Details

605.2 Receptacles or GFI missing / damaged

Details

605.3 Lighting fixtures missing / damaged

Details

607.1 Duct system damaged / missing / unsafe

Details

702.1 -
702.4 Means of egress blocked / illegally blocked doors

Details

704.1 Fire protection systems missing / damaged

Details

Miscellaneous Information

108.1.1 Unsafe Structure

- Dangerous to life, health, property or safety of the public
- Missing minimum safeguards in case of fire
- Structure contains unsafe equipment
- Structure is damaged / decayed / dilapidated
- Structure has faulty construction / unstable foundation

108.1.2 Unsafe Equipment

- Unsafe boiler or heating equipment
- Unsafe elevator or moving stairway
- Unsafe electrical wiring or device
- Flammable liquid containers or other within structure

108.1.3 Structure unfit for human occupancy

- Structure is unsafe / unlawful / degree of disrepair
- Structure is unsanitary / vermin or rat infested / contains filth
- Structure lacks ventilation / illumination
- Structure lacks sanitary or heating facilities

108.1.3 Unlawful structure

- Structure is occupied by more persons than permitted
- Structure was illegally converted to house more persons than allowed

Details

Submit by Email

Print Form