SEPULVEDA'S AUTO SERVICE #2

3102

813 West 495
San Juan, Texas 78589
(956) 781 - 2787

NAME: Utility Co Credit Jet 2.
DATE: 5-12-08
ADDRESS: LP 887-466
MILEAGE: Unit #
YEAR: 05
MAKE & MODEL: Ford
VIN NUMBER: 1FTPW12595KD33197
TERMS:
PHONE:

MECH.	DESCRIPTION OF WORK PERFORMED	AMOUNT
2	Front Brake Inspection labor	25 00
2	Rear Brake Inspection labor	30 00
3	Disc Resurface	30 00
1	Set spark plugs & wires labor	65 00
1	Oil change labor	10 00
1	Rear parking light	10 00
4	Disc Rotor & Drum labor	[illegible]

Not responsible for loss by fire or theft, or any other damage beyond our control.

I hereby authorize the above repair work to be done with the necessary materials and grant permission to operate the vehicle for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs to vehicle.

Please Sign Below

X [signature] E.S.

Total Labor	215
Total Parts	344 42
Sales Tax	1
TOTAL	559 42

PART NUMBER & DESCRIPTION	PRICE	AMOUNT
E.S. Sanchez		
RECEIVED MAY 21		
Front Brake Pads	109.99	109 99
Wire Set	369	29 52
Spark plugs Motorcraft	6.49	51 92
Front Rotor 45.49	45.49	45 49
Rear Rotor 45.49	45.99	45 99
Front Hub Unit		117 00
10/30 Motor Oil 3.29	3.29	23 03
Oil Filter	3.99	3 99
Miscellaneous		14 56
Shipping on 5-12-08		
MISCELLANEOUS RECEIVABLE		1 00
E. Sanchez on 5-12-08		
100-421-0 Total Parts 0 10-4		344 42

s otherwise regulated by law, the company above hereby disclaims all nties, either express or implied, including any implied warranty of fitness for ular purpose, and neither assumes or authorizes any other person to assume any liability in connection with the sale of said products or services sold or med in above business. NO GOODS HELD AFTER 30 DAYS.

ORM-6A MacDonald Signs & Adv. Alamo, TX 1 - 800 - 847 - 0018

P.O. # 5049 97 607060