SEPULVEDA'S AUTO SERVICE #2

3106

813 West 495
San Juan, Texas 78589
(956) 781 - 2787

QUAN	PART NUMBER & DESCRIPTION	PRICE	AMOUNT
	C2		
	TX 809 184		
	Shipped on 7-8-08		
	GOODS/SERVICES RECEIVED ON		
	Shipped on 7-8-08		
	8-100-621-0342-0010-4264		
	PO-607060		
	Total Parts		

NAME: Hidalgo Co Constable Pct 2 — DATE: 7-8-08

ADDRESS: Lit #2 LP 809184 — MILEAGE: 70292

YEAR	MAKE & MODEL	VIN NUMBER	TERMS	PHONE
01	Ford	1FM 6G 2J		783 4660

MECH	DESCRIPTION OF WORK PERFORMED	AMOUNT
1	New Alternator	348.00
1	labor on work on [illegible]	35.00

Unless otherwise regulated by law, the company above hereby disclaims all warranties, either express or implied, including any implied warranty or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products or services sold or performed in above business. NO GOODS HELD AFTER 30 DAYS.

REPFORM-CA MacDonald Signs & Adv. Alamo, TX 1 - 800 - 847 - 0018

Not responsible for loss by fire or theft, or any other damage beyond our control.

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate the vehicle for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs to vehicle.

Please Sign Below

X [signature]

Total Labor	35.00
Total Parts	348.00
Sales Tax	
TOTAL	383.00