





Pct. #3 Justice of the Peace Center
730 N. Breyfogle Rd
Mission, Tx 78572



Wet Carpet due to water leak








Water in Judge
Luis Garza
Chamber




Water absorbed by the Furniture









Judge Melo Ochoa's
Break Room






Signs of VCT
Buckeling





Water going
out of Bldg.


JUDGE MELO OCHOA'S CHAMBERS

Completely full of water




Judge Melo Ochoa's Office
Wet Carpet








VCT will need replacement; Tile is already buckeling in various areas of the building







VCT Tile coming off as staff was removing the Wet Carpet.

