

Claims

Old American Premium
P.O. Drawer 3267
Brownsville, TX 78520
(956) 574-9787

THE FROST NATIONAL BANK
www.frostbank.com
30-009/1140

61756

4/5/2012

© 2011 INTUIT INC. # 872 1-866-433-8810

PAY TO THE ORDER OF Hidalgo County

\$ **4,430.13

Four Thousand Four Hundred Thirty and 13/100***** DOLLARS

Hidalgo County
Claim#47356

There will be a \$30 fee
for any reissued check

Valid After 90 days
Clara

MEMO Full & Final PD Settlement

⑈061756⑈ ⑆114000093⑆ 800344443⑈

Pronto General Agency/Claims/Old American Premium

61756

Hidalgo County
Funds Held In Escrow:Cash+Cks

Claim#47356

4/5/2012

4,430.13

P2

Frost Claims #800344 Full & Final PD Settlement

4,430.13

PRONTO INSURANCE
BROWNSVILLE
805 MEDIA LUNA ST.
SUITE 401
BROWNSVILLE, TX 78520
(888)224-7740x7038 Fax: (956)547-3480

ESTIMATE OF RECORD

Written By: Javier Cuellar 03/29/2012 09:55 AM
Adjuster:

Insured: Pricilla Ashly Acosta
Owner: Hidalgo County
Address: P.O.Box 1356
Edinburg, TX 78540
Business: (956)318-2644

Claim #47356CV
Policy #
Date of Loss: 03/14/2012
Type of Loss: Liability
Point of Impact: 6. Rear

Inspect Vic's Auto Rebuilder
Location: 610 East Expressway 83
Pharr, TX 78577

Business: (956)787-3561
REPAIR_SHOP

Repair VIC'S AUTO REBUILDER
Facility: 610 East Expressway 83
Pharr, TX 78577

Business: (956)787-3561
Days to Repair
License #

2012 CHEV C1500 4X2 SILVERADO EXT WORK 8-4.8L-FI 4D SHORT White Int:Black
VIN: 1GCRCP EA2CZ227098 **Lic:** 1121146 TX **Prod Date:** 02/2012 **Odometer:** 413

Condition: Good

Air Conditioning	Tilt Wheel	Cruise Control
Intermittent Wipers	Message Center	Tinted Glass
Dual Mirrors	Clear Coat Paint	Power Steering
Power Brakes	AM Radio	FM Radio
Stereo	Search/Seek	Anti-Lock Brakes (4)
Driver Air Bag	Passenger Air Bag	Head/Curtain Air Bags
Front Side Impact Air Bag	Traction Control	Stability Control
Recline/Lounge Seats	Rear Step Bumper	Automatic Transmission
Overdrive	Styled Steel Wheels	

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
1		REAR BUMPER				
2	Repl	Bumper assy 1/2 ton w/o reverse sensor	1	786.00	1.1	
3#	Rpr	RT/rear frame rail end			1.0	F
4#	Rpr	LT/rear frame rail end			1.0	
5		PICK UP BOX				
6	Repl	Spare carrier 1/2 ton	1	183.34	0.4	
7	Repl	Guide tube	1	21.23		
8	Repl	Case	1	7.22	Incl.	
9	Repl	LT Outer panel Chevrolet	1	609.54	11.5	3.1
10		Add for Clear Coat				1.2
11	Repl	LT Stone guard front Chevrolet	1	22.00	0.2	

ESTIMATE OF RECORD

2012 CHEV C1500 4X2 SILVERADO EXT WORK 8-4.8L-FI 4D SHORT White Int:Black

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
12	Repl	LT Stone guard rear Chevrolet	1	20.74	0.2	
13	R&I	R&I box assy			2.5	
N 14*	Rpr	RT Side panel Chevrolet			<u>1.0</u>	<u>1.5</u>
15		Overlap Major Non-Adj. Panel				-0.2
16*		Add for Clear Coat				<u>0.8</u>
17	Repl	RT Stone guard front Chevrolet	1	23.11	0.2	
18	Repl	RT Stone guard rear Chevrolet	1	22.19	0.2	
19		REAR LAMPS				
20	R&I	RT Combo lamp assy Chevrolet all			0.3	
21	R&I	LT Combo lamp assy Chevrolet all			Incl.	
22		CAB				
23*	Rpr	<u>LT Uniside Corner panel assy</u>			s <u>1.5</u>	<u>1.5</u>
24		Overlap Major Non-Adj. Panel				-0.2
25		Add for Clear Coat				0.3
26#	Algn	Exhaust tail pipe			0.5	
27		FRONT BUMPER				
28		O/H front bumper			2.1	
29	Repl	Bumper primed	1	413.80	Incl.	1.4
30		Add for Clear Coat				0.6
31	Repl	RT Inner bracket	1	106.54	Incl.	
32	Repl	Air deflector w/o Z71	1	184.32	Incl.	
33#	Rpr	Set-Up and Measure			2.0	
34#	Rpr	Pull and align rear frame rails			2.0 F	
35#	Subl	Haz-Waste	1	3.00 X		
Subtotals ==>				2403.03	27.7	10.0

Line 14 : Repair right rear lower damage and partial refinish with full clear coat.

 Estimate Notes:
 Damage to rear bumper, left/right rear quarter panels, left corner cab, rear frame rail ends and front bumper.
 Vehicle is not driveable.

 Prior Damage Notes:
 No prior damage found at time of initial inspection.
 Vehicle is not driveable.

03/29/2012 at 09:55 AM
104726

47356CV
28t203jb

ESTIMATE OF RECORD

2012 CHEV C1500 4X2 SILVERADO EXT WORK 8-4.8L-FI 4D SHORT White Int:Black

Parts			2400.03
Body Labor	24.7 hrs @ \$ 40.00/hr		988.00
Paint Labor	10.0 hrs @ \$ 40.00/hr		400.00
Frame Labor	3.0 hrs @ \$ 46.00/hr		138.00
Paint Supplies	10.0 hrs @ \$ 28.00/hr		280.00
Sublet/Misc.			3.00

SUBTOTAL			\$ 4209.03
Sales Tax	\$ 2680.03 @ 8.2500%		221.10

TOTAL COST OF REPAIRS			\$ 4430.13

TOTAL ADJUSTMENTS			\$ 0.00
NET COST OF REPAIRS			\$ 4430.13

ESTIMATE OF RECORD

2012 CHEV C1500 4X2 SILVERADO EXT WORK 8-4.8L-FI 4D SHORT White Int:Black

NO SUPPLEMENTS WILL BE PAID WITHOUT WRITTEN AUTHORIZATION FROM PRONTO GA APPRAISER OR ADJUSTER.

All requests for supplements must be made to both this appraisal company and supplementrequest@prontoinsurance.com. No supplements will be paid or honored without prior written acceptance and/or consent by Pronto Insurance. No Supplements will be considered unless the vehicle is under repair at a shop. If the shop does not have access to email, the shop must fax the request to (956) 547-3481. The subject line must state "Supplement Request" and include the claim number and the vehicle owner's name.

We will not accept any supplement requests by telephone from the vehicle owner or a shop. All supplement requests must be made by email or fax.

THIS APPRAISAL IS NOT AN AUTHORIZATION TO REPAIR. THIS IS NOT A NOTICE OR AGREEMENT OF SETTLEMENT OR PAYMENT. ANY REPAIR MUST BE PRE-AUTHORIZED BY THE REGISTERED VEHICLE OWNER.

FAILING TO PRESENT THIS ESTIMATE TO THE REPAIRING PERSON OR FACILITY PRIOR TO AUTHORIZATION TO REPAIR MAY RESULT IN ADDITIONAL EXPENSES TO THE VEHICLE OWNER. REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER.

ALL REPLACEMENT PARTS AS LISTED ON THE APPRAISAL ARE REPRESENTED TO BE OF LIKE, KIND AND QUALITY AND WILL HAVE A WARRANTY EQUAL TO, OR GREATER TO THAT OF THE PARTS BEING REPLACED. ALL PARTS LISTED ON THIS APPRAISAL ARE REPRESENTED TO BE EQUAL OR BETTER IN QUALITY, FUNCTION, FIT, SAFETY AND CORROSION PROTECTION AS THE PART OR PARTS THEY REPLACE. PRONTO HAS IDENTIFIED THE REPLACEMENT PART OR PARTS LISTED IN THIS ESTIMATE AS CERTIFIED AND VALIDATED AS REPLACEMENT PARTS.

THE VEHICLE OWNER MAINTAINS THE RIGHT TO REPAIR VEHICLE WITH A REPAIR PERSON OR REPAIR FACILITY OF THEIR CHOICE. THE VEHICLE OWNER MAINTAINS THE RIGHT TO CHOOSE THE PARTS TYPE, MATERIAL COST AND LABOR COSTS IN THE REPAIR OF THEIR VEHICLE. HOWEVER, PRONTO HAS THE RIGHT TO PAY NO MORE THAN REASONABLE AMOUNTS FOR PARTS COSTS, MATERIAL COSTS AND LABOR COSTS.

ESTIMATE OF RECORD

2012 CHEV C1500 4X2 SILVERADO EXT WORK 8-4.8L-FI 4D SHORT White Int:Black

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DR1GH07, CCC Data Date 03/01/2012, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as RECOR. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries. Some 2012 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The Pathways estimator has a complete list of applicable vehicles. Part numbers and prices should be confirmed with the local dealership. The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced. SYMBOLS FOLLOWING PART PRICE: m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category. SYMBOLS FOLLOWING LABOR: D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories. OTHER SYMBOLS AND ABBREVIATIONS: Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. Comp Repl=Competitive Replacement (part). D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Qual Recy=Quality Recycled (part). Qual Repl=Quality Replacement(part). Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC Pathways - A product of CCC Information Services Inc. The following is a list of abbreviations that may be used in CCC Pathways that are not part of the MOTOR CRASH ESTIMATING GUIDE: BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA=National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

61755

Claims
Old American Premium
P.O. Drawer 3267
Brownsville, TX 78520
(956) 574-9787

THE FROST NATIONAL BANK
www.frostbank.com
30-009/1140

4/5/2012

PAY TO THE ORDER OF Hidalgo County.

\$ **606.21

Six Hundred Six and 21/100***** DOLLARS

Hidalgo County.
Claim#47356

There will be a \$30 fee
for any reissued check

Chia M
Void After 90 days
MP

MEMO

Full & Final PD Settlement

⑈061755⑈ ⑆114000093⑆ 800344443⑈

Pronto General Agency/Claims/Old American Premium

61755

4/5/2012

Hidalgo County.
Funds Held In Escrow:Cash+Cks

Claim#47356

606.21

Frost Claims #800344 Full & Final PD Settlement

606.21

© 2011 INTUIT INC. # 872 1-800-433-8810

PRONTO INSURANCE
BROWNSVILLE
805 MEDIA LUNA ST.
SUITE 401
BROWNSVILLE, TX 78520
(888)224-7740x7038 Fax: (956)547-3480

ESTIMATE OF RECORD

Written By: Javier Cuellar 04/04/2012 03:47 PM
Adjuster:

Insured: PR1973161-20	Claim # 47356CV1
Owner: Hidalgo County	Policy #
Address: Hidalgo County Precint 4 1051 Do 1051 Doolittle Rd Edinburg, TX 78541	Date of Loss: 03/14/2012
Business: (956)383-3112	Type of Loss: Liability
	Point of Impact: 6. Rear
Inspect Hidalgo County Precint 4 1051 Do	Business: (956)383-3112
Location: 1051 Doolittle Rd Edinburg, TX 78541	HOME

Repair NO SHOP SELECTED.
Facility:

Days to Repair
License #

2004 FORD F150 4X2 HERITAGE SUPERCAB 8-4.6L-FI 4D SHORT White Int:Grey
VIN: 2FTRX17W74CA88918 **Lic:** 876629 TX **Prod Date:** 05/2004 **Odometer:** 89072

Condition: Poor		
Air Conditioning	Intermittent Wipers	Dual Mirrors
Clear Coat Paint	Power Steering	Power Brakes
AM Radio	FM Radio	Stereo
Cassette	Anti-Lock Brakes (4)	Driver Air Bag
Passenger Air Bag	4 Wheel Disc Brakes	Cloth Seats
Bucket Seats	Rear Step Bumper	Automatic Transmission
Overdrive	Styled Steel Wheels	

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
1		REAR BUMPER				
N 2*	Repl	LKQ Bumper painted +25%	1	437.50	<u>0.8</u>	<u>1.1</u>
3		Add for Clear Coat				0.4
4#	Subl	Haz-Waste	1	3.00 X		
Subtotals ==>				440.50	0.8	1.5

Line 2 : LKQ rear bumper assy located at LKQ Central Zone-3, 1-866-557-2677
Suppliers Part Description: Bumper Assy, Rr 4DR,GRY,REBAR HITCH
ONLY,NEW STYLE STYLESIDE TOW PKG W/O PRK

04/04/2012 at 03:53 PM
104726

47356CV1
28t2031f

ESTIMATE OF RECORD

2004 FORD F150 4X2 HERITAGE SUPERCAB 8-4.6L-FI 4D SHORT White Int:Grey

Estimate Notes:

Rear bumper damage.
Vehicle is driveable.

Prior Damage Notes:

Minor dents and paint scratches.

Parts		437.50
Body Labor	0.8 hrs @ \$ 38.00/hr	30.40
Paint Labor	1.5 hrs @ \$ 38.00/hr	57.00
Paint Supplies	1.5 hrs @ \$ 26.00/hr	39.00
Sublet/Misc.		3.00

SUBTOTAL		\$ 566.90
Sales Tax	\$ 476.50 @ 8.2500%	39.31

TOTAL COST OF REPAIRS		\$ 606.21

TOTAL ADJUSTMENTS		\$ 0.00
NET COST OF REPAIRS		\$ 606.21

04/04/2012 at 03:53 PM
104726

47356CV1
28t2031f

ESTIMATE OF RECORD

2004 FORD F150 4X2 HERITAGE SUPERCAB 8-4.6L-FI 4D SHORT White Int:Grey

NO SUPPLEMENTS WILL BE PAID WITHOUT WRITTEN AUTHORIZATION FROM PRONTO GA APPRAISER OR ADJUSTER.

All requests for supplements must be made to both this appraisal company and supplementrequest@prontoinsurance.com. No supplements will be paid or honored without prior written acceptance and/or consent by Pronto Insurance. No Supplements will be considered unless the vehicle is under repair at a shop. If the shop does not have access to email, the shop must fax the request to (956) 547-3481. The subject line must state "Supplement Request" and include the claim number and the vehicle owner's name.

We will not accept any supplement requests by telephone from the vehicle owner or a shop. All supplement requests must be made by email or fax.

THIS APPRAISAL IS NOT AN AUTHORIZATION TO REPAIR. THIS IS NOT A NOTICE OR AGREEMENT OF SETTLEMENT OR PAYMENT. ANY REPAIR MUST BE PRE-AUTHORIZED BY THE REGISTERED VEHICLE OWNER.

FAILING TO PRESENT THIS ESTIMATE TO THE REPAIRING PERSON OR FACILITY PRIOR TO AUTHORIZATION TO REPAIR MAY RESULT IN ADDITIONAL EXPENSES TO THE VEHICLE OWNER. REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER.

ALL REPLACEMENT PARTS AS LISTED ON THE APPRAISAL ARE REPRESENTED TO BE OF LIKE, KIND AND QUALITY AND WILL HAVE A WARRANTY EQUAL TO, OR GREATER TO THAT OF THE PARTS BEING REPLACED. ALL PARTS LISTED ON THIS APPRAISAL ARE REPRESENTED TO BE EQUAL OR BETTER IN QUALITY, FUNCTION, FIT, SAFETY AND CORROSION PROTECTION AS THE PART OR PARTS THEY REPLACE. PRONTO HAS IDENTIFIED THE REPLACEMENT PART OR PARTS LISTED IN THIS ESTIMATE AS CERTIFIED AND VALIDATED AS REPLACEMENT PARTS.

THE VEHICLE OWNER MAINTAINS THE RIGHT TO REPAIR VEHICLE WITH A REPAIR PERSON OR REPAIR FACILITY OF THEIR CHOICE. THE VEHICLE OWNER MAINTAINS THE RIGHT TO CHOOSE THE PARTS TYPE, MATERIAL COST AND LABOR COSTS IN THE REPAIR OF THEIR VEHICLE. HOWEVER, PRONTO HAS THE RIGHT TO PAY NO MORE THAN REASONABLE AMOUNTS FOR PARTS COSTS, MATERIAL COSTS AND LABOR COSTS.

Recycled Part Costs based on information provided by Car-Part.com. For assistance, call CCC at 800-637-8511.

ESTIMATE OF RECORD

2004 FORD F150 4X2 HERITAGE SUPERCAB 8-4.6L-FI 4D SHORT White Int:Grey

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DE2MA97, CCC Data Date 03/01/2012, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as RECOR. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries. Some 2012 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The Pathways estimator has a complete list of applicable vehicles. Part numbers and prices should be confirmed with the local dealership. The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced. SYMBOLS FOLLOWING PART PRICE: m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category. SYMBOLS FOLLOWING LABOR: D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories. OTHER SYMBOLS AND ABBREVIATIONS: Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. Comp Repl=Competitive Replacement (part). D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Qual Recy=Quality Recycled (part). Qual Repl=Quality Replacement(part). Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC Pathways - A product of CCC Information Services Inc. The following is a list of abbreviations that may be used in CCC Pathways that are not part of the MOTOR CRASH ESTIMATING GUIDE: BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA=National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

04/04/2012 at 03:53 PM
104726

47356CV1
28t203lf

ESTIMATE OF RECORD

2004 FORD F150 4X2 HERITAGE SUPERCAB 8-4.6L-FI 4D SHORT White Int:Grey

RECYCLED PART SUPPLIERS

Line	Line Description		Price
2	LKQ Bumper painted +25%	Stock No.: 10D010	\$ 437.50
	DELUXE AUTO PARTS - KOLT	(800)654-3589	
	230 OMAHA ST.	GLENN STANFORD	
	CORPUS CHRISTI, TX 78408		