

L & G Engineering Laboratory

Construction Material Testing Geotechnical Engineering

INVOICE

Invoice Date: 08/16/2012
Invoice No: 12-8-000002

Page 1 of 1

2100 W. Expressway 83
Mercedes, TX 78570
Office (956) 565-0760 Fax (956) 565-6746

Client Address: Hidalgo County Sheriff's Office
Mr. Juan Tapia
P.O. Box 1228
711 El Cibolo Rd.
Edinburg, TX. 78540

Account No.: L211
Project No: L2111201
Project Desc.: Sheriff's Office Sub-Station Contract No.
C-11-032C-10-11

Due Date: UPON RECEIPT
Budget/Remaining: \$48,239.46 / \$4,974.10
PO: 666659

===== Invoice Summary by Billing Code =====

	<u>Unit Rate</u>	<u>Qty</u>	<u>Extension</u>
920:92034 - Comp. Strength of Cyl. Specimen	\$15.22	4.00	\$60.88
940:94047 - Eng. Tech. (Concrete / Lab)	\$58.41	1.00	\$58.41
940:94054 - Engineering Specialist	\$114.30	0.25	\$28.58
940:94055 - Engineer / P.E.	\$152.47	0.25	\$38.12
950:95061 - Test Report	\$22.56	1.00	\$22.56
Total for this Invoice:			\$208.55

===== Invoice Detail by Report =====

<u>Report No.</u>	<u>Sampled</u>	<u>Qty</u>	<u>Billing Code</u>	<u>Unit Type</u>	<u>Unit Rate</u>	<u>Extension</u>
R146-28	07/16/2012	4.00	920:92034 - Comp. Strength of Cyl. Specimen	Each	\$15.22	\$60.88
R146-28	07/16/2012	1.00	940:94047 - Eng. Tech. (Concrete / Lab)	Each	\$58.41	\$58.41
R146-28	07/16/2012	0.25	940:94054 - Engineering Specialist	Hour	\$114.30	\$28.58
R146-28	07/16/2012	0.25	940:94055 - Engineer / P.E.	Hour	\$152.47	\$38.12
R146-28	07/16/2012	1.00	950:95061 - Test Report	Each	\$22.56	\$22.56
Report Number R146-28 for a Subtotal of:						\$208.55
Total for this Invoice:						\$208.55

P.O. #: 666659

Invoice Received By:

J. Tapia on: 8-21-12

Good/Services Received By:

J. Tapia on: 8-16-12


2-1336-423-00-280-03650-720

Super Admin

REMIT TO: 2100 W. Expressway 83
Mercedes, TX 78570
Office (956) 565-0760 Fax (956) 565-6746

PAST DUE BALANCES SUBJECT TO 1.5% SERVICE CHARGE PER MONTH
PLEASE REFERENCE INVOICE NUMBER WITH PAYMENT

W
8/21/12



L&G Engineering Laboratory

Construction Material Testing
Geotechnical Engineering

August 16, 2012

Mr. Juan Tapia
Hidalgo County Sheriff's Office
P.O. Box 1228
711 El Cibolo Rd.
Edinburg, TX. 78540

RE: Hidalgo County Sheriff's Office Substation

Dear Mr. Tapia:

Included for your use with this letter is test report **R146-28** for **28-day Compressive Strength Testing** performed on the above referenced project. Unless otherwise noted, all test results meet or exceed requirements.

L&G Engineering Laboratory appreciates the opportunity to serve your material testing needs on this project and we look forward to working with you in the future.

If you have any questions, feel free to contact me at 956-565-0760.

Sincerely,

Ricardo A. Gil
General Manager

Attachments

CC: Gignac Architect, Mr. Raymond Gignac
D. Wilson Construction Co., Mr. Bill Wilson
Dos Logistics Inc., Mr. Jesus Jimenez, P.E.
Hinojosa Engineering, Mr. Albert Trevino
Prodigy CM's LLP, Mr. Jerry Garcia
Hidalgo Cnty Pct. 1, Mr. P.R. Avila

**CONCRETE COMPRESSION
TEST REPORT**

Project Description: Sheriff's Office Sub-Station Contract No. C-11-032C-10-11
Client: Hidalgo County Sheriff's Office
Architect: Gignac Architect
Contractor: D. Wilson Construction Co.

L&G Project Number: L2111201
L&G Report Number: R146-28
Sample Date: 07/16/2012
Date Reported: 08/13/2012


Client PO: 666659

Page 1 of 2

Placement Location: Circle Base for Post Lights
Mix ID: 3000 cg Supplier: Central Ready Mix
Specified Strength: 3,000 P.S.I. @ 28 days
Specified Slump: N/A Slump: 3.0"
Specified Air Content: N/A Air Content: 1.7%
Weather Conditions: Cloudy Air Temp.: 77°f
Time Batched: 8:30 am Time Sampled: 8:50 am Concrete Temp.: 73°f
Plant Ticket No: 398580 Truck No: 320 CY: 10
Water: 0 gal.

Compressive Strength Data

Set No.	Identification	Test Date	Age (days)	Maximum Load (pounds)	Break Type	Comp. Strength (psi)	Average Strength (psi)	% of Design
22	A	07/23/2012	7	71,770	Type 4	2,540		84.67%
	B	07/23/2012	7	72,615	Type 4	2,570	2,550	85.67%
	C	08/13/2012	28	126,825	Type 3	4,490		149.67%
	D	08/13/2012	28	119,815	Type 3	4,240	4,360	141.33%



Remarks/Comments:
6 x 12 in. Cylinders

Respectfully Submitted,
L&G Engineering Laboratory

Ricardo A. Gil, Lab Manager



L&G Engineering Laboratory

Construction Material Testing
Geotechnical Engineering

2100 W. Expressway 83 Mercedes, TX 78570 (956) 565-0760
900 S. Stewart Rd. Ste. 6 Mission, TX 78572 (956) 583-7117

CONCRETE COMPRESSION TEST REPORT

Project Description: Sheriff's Office Sub-Station Contract No. C-11-032C-10-11

Client: Hidalgo County Sheriff's Office

Architect: Gignac Architect

Contractor: D. Wilson Construction Co.

L&G Project Number: L2111201

L&G Report Number: R146-28

Sample Date: 07/16/2012

Date Reported: 08/13/2012

Client PO: 666659

Page 2 of 2

Orig: Hidalgo County Sheriff's Office

(Edinburg, TX) Attn: Mr. Juan Tapia

(1-cc copy)

1-cc Gignac Architect Attn: Raymond Gignac

1-cc Dos Logistics Inc. Attn: Jesus Jimenez P.E.

1-cc Hinojosa Engineering Attn: Albert Trevino

1-cc D. Wilson Construction Co. Attn: Bill Wilson

1-cc Hidalgo County Pct. #1 (R&B) (Hidalgo County Pct. #1)

Attn: Mr. P.R. Avila

1-cc Prodigy CM's LLP Attn: Jerry Garcia

1-cc Laboratory

Respectfully Submitted,

L&G Engineering Laboratory

Ricardo A. Gil, Lab Manager