

Southwest Auto Center  
P.O. Box 14261  
Lexington, KY 40512-4261  
800-236-0398 x 2303661



003424  
COUNTY OF HIDALGO  
PO Box 1356  
Attn Safety Dept  
EDINBURG, TX 78540

**Attention: This remittance incorporates  
1 claim payments**

Special Handling ID: RM 00

**Explanation of Benefits**

Page 1 of 1

| Invoice Number  | Claim Number/<br>Date of Loss | Insured Name/<br>Claimant Name       | Amount Paid   |
|---|-------------------------------|--------------------------------------|---------------|
|   | Y07AP 55903<br>04-10-13       | DOROTHY DILLARD<br>COUNTY OF HIDALGO | \$507.82      |
| Nature of Payment: PROPERTY DAMAGE SETTLEMENT   |                               |                                      | Service Dates |
| Additional Comments:  |                               |                                      |               |
| Paid on behalf of: Southern County Mutual<br>Claim Handler: Shawna Kelly<br>Claim Center: Southwest Auto Center<br>P.O. Box 14261<br>Lexington, KY 40512-4261 |                               |                                      |               |
| Please contact the claim handler listed above if you have any questions on this particular claim.   |                               |                                      |               |
| Issue Date  | 05-06-13                      | Check Number                         | 107545041 1   |
| Total Amount of Check   |                               |                                      | \$507.82      |

Please keep the above information for your records.

102045846

FOLD AT DOTTED LINE AND DETACH



SOUTHERN COUNTY MUTUAL INSURANCE COMPANY  
BY HARTFORD FIRE GENERAL AGENCY, INC.

56-1544  
441

Check Number: 107545041 1

Issue Date: 05-06-13

\$\*\*\*\*\*507.82

JPMorgan Chase Bank, N.A.  
Columbus, OH 43085

Pay

FIVE HUNDRED SEVEN DOLLARS AND 82/100

TO THE COUNTY OF HIDALGO  
ORDER PO Box 1356Attn Safety Dept  
OF EDINBURG, TX 78540

*Robert W. Paris*  
Authorized Signature

⑈ 107545041 ⑈ ⑆ 044 1 5443 ⑆

649035458⑈

102045846

03567

1000012 1075450411



HAR-100-2

**BOGGUS FORD-MC ALLEN**

1400 E US HIGHWAY 83, MC ALLEN, TX 78501

Phone: (956) 686-0911

FAX: (956) 686-0974

Workfile ID: 3e09f249  
Federal ID: 275381820**Preliminary Estimate****Customer: HIDALGO COUNTY PUT #2****Job Number:**

Written By: RICK MENDOZA

Insured: HIDALGO COUNTY PUT  
#2

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact: 06 Rear

**Owner:**HIDALGO COUNTY PUT #2  
301E STATE ST  
PHARR, TX 78577  
(956) 787-1891 Business  
(111) 111-1111 x1 Cell**Inspection Location:**BOGGUS FORD-MC ALLEN  
1400 E US HIGHWAY 83  
MC ALLEN, TX 78501  
Repair Facility  
(956) 686-0911 Day**Insurance Company:****VEHICLE**Year: 2004  
Make: FORD  
Model: F250 4X2 SUPERCAB  
Color: Int:Body Style: 4D SHORT  
Engine: 8-6.0L-TD  
Production Date:  
Condition:VIN: 1FTNX20P54EC24514  
License:  
State:  
Job #:Mileage In:  
Mileage Out:  
Vehicle Out:**TRANSMISSION**6 Speed Transmission  
Overdrive**POWER**Power Steering  
Power Brakes**DECOR**

Dual Mirrors

**CONVENIENCE**

Intermittent Wipers

**RADIO**AM Radio  
FM Radio  
Stereo**SAFETY**Anti-Lock Brakes (4)  
Driver Air Bag  
Passenger Air Bag  
4 Wheel Disc Brakes**WHEELS**

Styled Steel Wheels

**PAINT**

Clear Coat Paint

**TRUCK**

Rear Step Bumper

**Preliminary Estimate**

**Customer: HIDALGO COUNTY PUT #2**

**Job Number:**

Vehicle: 2004 FORD F250 4X2 SUPERCAB 4D SHORT 8-6.0L-TD

| Line             | Oper | Description          | Part Number   | Qty | Extended Price \$ | Labor      | Paint      |
|------------------|------|----------------------|---------------|-----|-------------------|------------|------------|
| 1                |      | <b>REAR BUMPER</b>   |               |     |                   |            |            |
| 2                |      | O/H rear bumper      |               |     |                   | 1.5        |            |
| 3                | R&I  | R&I bumper assy      |               |     |                   | Incl.      |            |
| 4                | *    | Rpr Bumper painted   |               |     |                   | 2.0        | 1.3        |
| 5                |      | Add for Clear Coat   |               |     |                   |            | 0.5        |
| 6                | Repl | RT Step pad upper    | F81Z17B807AB  | 1   | 30.25             | Incl.      |            |
| 7                | Repl | LT Step pad upper    | F81Z17B807AA  | 1   | 30.25             | Incl.      |            |
| 8                | Repl | Step pad lower       | XL3Z17B807AAA | 1   | 24.50             | Incl.      |            |
| 9                | #    | Repl ELECTRICAL PLUG |               | 1   | 100.00            | 1.0        |            |
| <b>SUBTOTALS</b> |      |                      |               |     | <b>185.00</b>     | <b>4.5</b> | <b>1.8</b> |

**ESTIMATE TOTALS**

| Category             | Basis       | Rate         | Cost \$       |
|----------------------|-------------|--------------|---------------|
| Parts                |             |              | 185.00        |
| Body Labor           | 4.5 hrs @   | \$ 40.00 /hr | 180.00        |
| Paint Labor          | 1.8 hrs @   | \$ 40.00 /hr | 72.00         |
| Paint Supplies       | 1.8 hrs @   | \$ 28.00 /hr | 50.40         |
| <b>Subtotal</b>      |             |              | <b>487.40</b> |
| Sales Tax            | \$ 235.40 @ | 8.2500 %     | 19.42         |
| <b>Grand Total</b>   |             |              | <b>506.82</b> |
| Deductible           |             |              | 0.00          |
| <b>CUSTOMER PAY</b>  |             |              | <b>0.00</b>   |
| <b>INSURANCE PAY</b> |             |              | <b>506.82</b> |