

PAYMENT NO 1 25 732705 J
PAYMENT AMOUNT \$454.00
ISSUE DATE 05-13-2013
AUTHORIZED BY SMITH, SIOBHAN
PHONE (888) 257-6077

CLAIM NO 53-261W-827
LOSS DATE 03-01-2013
POLICY NO 1563-582-53A
INSURED GARZA, MARIA

HIDALGO COUNTY
PO BOX 1356
EDINBURG TX 78540-1356

REMARKS Payment for your vehicle damages

COVERAGE DESCRIPTION	ON BEHALF OF	AMOUNT
PROPERTY DAMAGE LIABILITY	HIDALGO COUNTY	454.00

RETAIN STUB FOR RECORDS



STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY

TEXAS

CUSTOMER SERVICE P08PCL322

JPMORGAN CHASE BANK, NA 56-1544/441
2ND FLOOR
TAMPA, FL 33610-0000

1 25 732705 J

CLAIM NO 53-261W-827
LOSS DATE 03-01-2013

INSURED GARZA, MARIA

DATE 05-13-2013
MM DD YYYY

*****EXACTLY FOUR HUNDRED FIFTY-FOUR AND 00/100 DOLLARS

\$*****454.00

Pay to the
Order of: HIDALGO COUNTY

Edward B. Hunt Jr.
AUTHORIZED SIGNATURE
P. J. Smith
AUTHORIZED SIGNATURE

SECURED DOCUMENT WATERMARK APPEARS ON BACK, HOLD AT 45° ANGLE FOR VIEWING

⑈ 25 1 7 7 3 2 7 0 5 ⑈ ⑆ 0 4 4 1 1 5 4 4 3 ⑆

6 2 7 1 1 9 2 0 9 ⑈

GREEN DROPOUT APPEARS ON FACE OF DOCUMENT

VOID IF GREEN COLORED BACKGROUND IS MISSING



HIDALGO COUNTY
 DRM SAFETY DIVISION
 2013 MAY 8 AM 10 04

Date: 4/18/2013 12:44
 Estimate ID: 96
 Estimate Version: 0
 Preliminary
 Profile ID: * Mitchell

Mark of Xcellence Collision Services

612 W. Ferguson, Pharr, TX 78577
 (956) 460-2739
 Email: markofxcellnce.cruz@gmail.com

Damage Assessed By: MITCHELL MITCHELL

Deductible: UNKNOWN

Owner: ARMANDO CAMPOS

Telephone:

Cell Phone: (956) 784-3510

Mitchell Service: 910158

Description: 2005 Ford Pickup F150 XLT
 Body Style: 4D Pkpw 6' Bed 139" WB
 VIN: 1FTPW12505KC32198
 OEM/ALT: O
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
 MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS.
 CHROME WHEELS, FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM
 AUTOMATIC HEADLIGHTS, AM/FM STEREO CD, FRONT SPLIT BENCH SEAT
 KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER FOLDING EXTERIOR MIRRORS
 STEERING WHEEL MOUNTED CONTROLS

Drive Train: 5.4L Inj 8 Cyl 2WD
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	002550	REF	REFINISH	Frt Upr Bumper Cover			C 2.2
2	002555	BDY	REMOVE/INSTALL	Frt Upr Bumper Cover			1.4 #
3	002561	REF	REFINISH	R Fender Outside			C 2.2
4	007782	BDY	REMOVE/INSTALL	R Antenna Base			1.0 #
5	AUTO	REF	ADD'L OPR	Clear Coat			1.3
6	933018	REF	ADD'L OPR	Mask For Overspray			0.4*
7	AUTO		ADD'L COST	Paint/Materials		91.20 *	
8	AUTO		ADD'L COST	Hazardous Waste Disposal		22.80 *	

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc



Date: 4/18/2013 12:4
 Estimate ID: 96
 Estimate Version: 0
 Preliminary
 Profile ID: * Mitchell



Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount	
Body	2.4	40.00	0.00	0.00	96.00 T			
Refinish	6.1	40.00	0.00	0.00	244.00 T	Total Replacement Parts Amount	0.00	
	Taxable Labor				340.00			
Labor Summary	8.5				340.00			
III. Additional Costs					<u>Amount</u>	IV. Adjustments		<u>Amount</u>
					114.00	Customer Responsibility	0.00	
					114.00			
Paint Material Method: Percent Multiplier Percent Multiply = 40.00								
						I. Total Labor:	340.00	
						II. Total Replacement Parts:	0.00	
						III. Total Additional Costs:	114.00	
						Gross Total:	454.00	
						IV. Total Adjustments:	0.00	
						Net Total:	454.00	

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.