

MAIL DIRECT

03292.ZJC4.JSS650624038.01.01.997
COUNTY OF HIDALGO TEXAS
PO BOX 1356
ATTN SERGIO REYES
EDINBURG, TX 78540

USAA General Indemnity Company
PO Box 33490
San Antonio, TX 78265

INVOICE #: USAA-78990276216078446720
USAA #: 027629978
LOSS RPT #: 1
LOSS DATE: 05/22/2013
POLICYHOLDER:
JAMES B ARENDS

LOB: AUT
CLAIMS REP: 07456-76
CHECK #: 0005551077
CHECK DATE: 06/19/2013

EXPLANATION OF PAYMENT	TOTAL PAYMENT AMOUNT
Payment under Property Damage Liability Coverage COUNTY OF HIDALGO SAFETY DIVISION, 1998 GMC TRUCK 1500	***469.10

18433-0709

93868-1209

FACE OF DOCUMENT HAS A MULTI-COLORED BACKGROUND. THE BACK CONTAINS AN ARTIFICIAL WATERMARK. HOLD AT ANGLE TO VIEW.



USAA General Indemnity Company
PO Box 33490
San Antonio, TX 78265

0005551077

DATE
06/19/2013

CHECK AMOUNT
***469.10

PAY **Four Hundred Sixty-Nine and 10/100 s**

TO COUNTY OF HIDALGO TEXAS
THE
ORDER
OF:

USAA #: 027629978 / LR #: 1

NATURE OF PAYMENT:

Payment under Property Damage Liability Coverage COUNTY OF HIDALGO
SAFETY DIVISION, 1998 GMC TRUCK 1500
BANK OF AMERICA - HARTFORD, CT

VOID 180 DAYS FROM ISSUE DATE

Jose Robles Jr
AUTHORIZED SIGNATURE

0005551077 1011900445 2240015665

PAYNE COLLISION CENTER
727 E. BUSINESS 83
WESLACO, TX 78596
PHONE - 956-973-0782
FAX - 956-973-2513

*** PRELIMINARY ESTIMATE ***

06/10/2013 01:05 PM

Owner

Owner: HIDALGO COUNTY PCT 1

Inspection

Inspection Date: 06/10/2013 01:05 PM

Inspection Type:

Appraiser Name: ROBERTO FIGUEROA
Email: ROBERTF@PAYNEGROUP.COM

Appraiser License # :

Repairer

Repairer: PAYNE COLLISION CENTER,
INC.

Address: 727 E. BUSINESS 83

City State Zip: Weslaco, TX 78596

Contact:

Work/Day: (956)973-0753

Work/Day: (956)973-0782

FAX: (956)973-2513

Vehicle

1998 GMC C1500 SL 2 DR Ext Cab Long Bed
8cy. Gasoline 5.0
4 Speed Automatic

Lic Expire:

Veh Insp# :

Condition:

Ext. Color: WHITE

Ext. Refinish: Two-Stage

VIN: 1GTEC19M2WE520656

Mileage Type: Actual

Code: U8023C

Int. Color:

Int. Refinish: Two-Stage

Options

AM/FM Stereo
Intermittent Wipers
Power Steering
Tinted Glass

Anti-Lock Brakes
Lighted Entry System
Rear Step Bumper
Vinyl Seats

Dual Airbags
Power Brakes
Tachometer

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Rear Bumper										
1	PC	388		Bumper,Rear Step	Replace PXN Reconditioned	\$249.00			1.7	SM
2	L	388	13	Bumper,Rear Step	Refinish				1.8	RF

1.0 Surface
 0.6 Two-stage setup
 0.2 Two-stage

Manual Entries

3 SB HAZ MAT Sublet Repair \$5.00* SM*
 3 Items

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts \$249.00
 Paint Materials \$50.40
Parts & Material Total \$299.40
 Tax on Parts & Material @ 8.250% \$24.70

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$40.00	1.7		1.7	\$68.00
Mech/Elec (ME)	\$75.00				
Frame (FR)	\$45.00				
Refinish (RF)	\$40.00	1.8		1.8	\$72.00
Paint Materials	\$28.00				
Labor Total				3.5 Hours	\$140.00
Sublet Repairs					\$5.00
Gross Total					\$469.10
Net Total					\$469.10

Alternate Parts Y/01/01/00/00/00 CUM 01/01/00/00/00 Zip Code: 78596 Default
 Recycled Parts NOT REQUESTED

Audatex Estimating 7.0.019 ES 06/10/2013 01:06 PM REL 7.0.019 DT 05/01/2013
 Copyright (C) 2013 Audatex North America, Inc.

0.8 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Rebit	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check