

Type of Report: Safety Inspection

Report Number: 13-07-02-1000 Date: 7-2-2013 Page 1 of 2

Location:

Name of Office/Department: Hidalgo County Pct. 3 Motor-Pool  
Address: 8310 West Mile 7, Mission, Texas  
Phone: (956) 585-4509 ext: 3005 Precinct Area: 3 District: 2

Employee/Official Contact Data:

Name: Domingo Villarreal emp# 019135 Title: Administrative Ass.  
Name: Marcelo Garza emp# 103349 Title: Ass. Field of Operation  
Name: Roberto Salazar emp# 160814 Title: Ass Field of Operation

Inspection Standard: (circle appropriate description or list)

General Industry Construction Parks/Refuse Other: \_\_\_\_\_

Inspection Site: (circle appropriate description or list)

Personnel Building Warehouse Office Setting Work site Equipment Other: \_\_\_\_\_

Reason for Inspection:

Safety Inspection Complaint Assignment Work Place Accident Other: \_\_\_\_\_

**Inspection Type:** (circle appropriate description or list)

Record Keeping      Walking-Working Surfaces      Exit Routes      Emergency Action Plans  
 Power Platforms/ Lifts      Hazardous Material      P.P.E.      Welding, Cutting/Brazing  
 General Environmental Controls      Compressed Gas/Air Equipment      Material Handling/Storage  
 Machinery/Machine Guarding      Confined Space      Other: Building

**Concerns or Hazards:**

Standard/Rule/Code: \_\_\_\_\_

Description of Concern or Hazard: Loose sheet metal, holes in roof  
The building is unsound and may collapse

Disposition: Spoke with Domingo Villarreal about  
demolishing the building

(Note: if additional comment or information is required, place on second page in narrative format )

Photos Taken: Yes  No  If yes, submit with report.

Reporting S.O.: [Signature]

Employee No.: 129356

Approved By: [Signature]

Employee No.: 013281

Inspection: Pct. 3 Motor pool storage shed located at 8310 West Mile 7 Mission TX. Pct. 3 is in the process of demolishing the building. The building is unsafe. The roof has holes where the sheet- metal has blown off and some areas the sheet metal is loose. The building is unsound and may collapse in severe weather.



Inspection: Pct. 3 Motor pool storage shed located at 8310 West Mile 7 Mission TX. Pct. 3 is in the process of demolishing the building. The building is unsafe. The roof has holes where the sheet-metal has blown off and some areas the sheet metal is loose. The building is unsound and may collapse in severe weather.



Inspection: Pct. 3 Motor pool storage shed located at 8310 West Mile 7 Mission TX. Pct. 3 is in the process of demolishing the building. The building is unsafe. The roof has holes where the sheet- metal has blown off and some areas the sheet metal is loose. The building is unsound and may collapse in severe weather.

