



Chevrolet-Buick-GMC Trucks  
2401 E. Expressway 83 (Exit 1015)  
Weslaco, Texas 78596  
Bus. (956) 969-2525



35-1054  
1130

CHECK# 207428

207428

PAY \*\*SIX HUNDRED SEVEN DOLLARS AND 17/100\*\*

TO THE COUNTY OF HIDALGO TX  
ORDER  
OF

DATE  
10/22/13

AMOUNT  
\$607.17

SECURITY  
FEATURES INCLUDED  
DETAILS ON BACK

COMPASS BANK  
500 S. MISSOURI WESLACO, TX 78596-6020

VOID AFTER 90 DAYS

⑈ 207428 ⑈ ⑆ 113010547⑆ 0000126179 ⑈

PAYNE COLLISION CENTER  
 727 E. BUSINESS 83  
 WESLACO, TX 78596  
 PHONE - 956-973-0782  
 FAX - 956-973-2513

\*\*\* PRELIMINARY ESTIMATE \*\*\*

10/07/2013 03:32 PM

Owner

Owner: HIDALGO PCT. 1

Inspection

Inspection Date: 10/07/2013 03:33 PM

Inspection Type:

Appraiser Name: ROBERTO FIGUEROA  
 Email: ROBERTF@PAYNEGROUP.COM

Appraiser License #:

Repairer

Repairer: PAYNE COLLISION CENTER  
 Address: 727 E. BUSINESS 83

Contact:

Work/Day: (956)973-0753

Work/Day: (956)973-0782

FAX: (956)973-2513

City State Zip: Weslaco, TX 78596

Vehicle

2002 Ford Ranger XL 2 DR Standard Cab Short Bed  
 6cyl Gasoline 3.0  
 5 Speed Automatic

Lic Expire:

Veh Insp#:

Condition:

Ext. Color: WHITE

Ext. Refinish: Two-Stage

VIN: 1FTYR10UX2PB08329

Mileage Type: Actual

Code: P8332A

Int. Color:

Int. Refinish: Two-Stage

Options

AM/FM Stereo	Anti-Lock Brakes	Camper/Towing Package
Center Console	Dual Airbags	Intermittent Wipers
Lighted Entry System	Power Brakes	Power Steering
Rear Step Bumper	Split Front Bench Seat	Styled Steel Wheels
Tachometer	Tinted Glass	Vinyl Seats

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
<b>Rear Bumper</b>									
1	PC	563		Bumper,Rear Step	Replace PXN Reconditioned	\$192.00		1.6	SM
2	L	563	13	Bumper,Rear Step	Refinish			2.3	RF

				1.4 Surface				
				0.6 Two-stage setup				
				0.3 Two-stage				
3	E	573	Supt,RR Bumper Inner LT	F37Z17788A	\$22.55		INC	SM
4	E	574	Supt,RR Bumper Inner RT	F37Z17787A	\$22.55		INC	SM
5	E	570	01 Pad,Rear Bumper Step	4L5Z17B807BAC	\$110.67		INC	SM

**Manual Entries**

6	SB		HAZ MAT	Sublet Repair	\$5.00*			SM*
6			Items					

**MC Message**

01	CALL DEALER FOR EXACT PART # / PRICE
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

**Estimate Total & Entries**

Gross Parts		\$155.77	
Other Parts		\$192.00	
Paint Materials		\$64.40	
Parts & Material Total			\$412.17
Tax on Parts & Material	@ 8.250%		\$34.00

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$40.00	1.6		1.6	\$64.00
Mech/Elec (ME)	\$85.00				
Frame (FR)	\$45.00				
Refinish (RF)	\$40.00	2.3		2.3	\$92.00
Paint Materials	\$28.00				

Labor Total		3.9 Hours		\$156.00
Sublet Repairs			\$5.00	
Gross Total				<b>\$607.17</b>
Net Total				<b>\$607.17</b>

Alternate Parts Y/01/01/00/00/00 CUM 01/01/00/00/00 Zip Code: 78596 Default  
 Recycled Parts NOT REQUESTED

Audatex Estimating 7.0.019 ES 10/07/2013 03:34 PM REL 7.0.019 DT 09/01/2013  
 Copyright (C) 2013 Audatex North America, Inc.

0.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

**Op Codes**

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled