

REFERENCE NO.	DESCRIPTION	INVOICE DATE	INVOICE AMOUNT	DISCOUNT TAKEN	AMOUNT PAID
	MODEL FORD F-150 VIN#1FTMS1EE2AKA47739 LP#AT91835				387.22
					0.00
CHECK DATE	CHECK NO.	PAYEE		DISCOUNTS TAKEN	CHECK AMOUNT
10/23/13	F 031240	HIDALGO CO. HIDTA TASK FORCE			\$387.22

THE FACE OF THIS DOCUMENT HAS A COLORED BACKGROUND ON WHITE PAPER

SOUTH TEXAS COMMUNICATIONS, INC.
P.O. BOX 3712
McALLEN, TEXAS 78502
PHONE (956) 687-8591

FROST NATIONAL BANK
McALLEN, TEXAS
30-9/1140
80

F 031240

Memo:

F 031240
CHECK NO.

Oct 23, 2013
DATE

387.22
AMOUNT

Three Hundred Eighty-Seven and 22/100 Dollars

PAY TO THE ORDER OF: HIDALGO CO. HIDTA TASK FORCE



B. J. Ewing
AUTHORIZED SIGNATURE MP

SECURITY FEATURES INCLUDED. DETAILS ON BACK.

⑈031240⑈ ⑆114000093⑆ 80 0507091⑈

**COLLISION CENTER AUTO BODY &
GLASS**

Workfile ID: 29e54a61
Federal ID: 742570397

1610 N. MCCOLL, MCALLEN, TX 78501
Phone: (956) 686-4054

Preliminary Estimate

Customer: HIDALGO COUNTY DISTRICT ATTORNEY

Job Number:

Written By: JUAN MIRELES

Insured: HIDALGO COUNTY DISTRICT ATTORNEY Policy #: Claim #:
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact:

Owner: HIDALGO COUNTY DISTRICT ATTORNEY (956) 687-8591 Business
Inspection Location: COLLISION CENTER AUTO BODY & GLASS
1610 N. MCCOLL
MCALLEN, TX 78501
Repair Facility
(956) 686-4054 Day
Insurance Company:

VEHICLE

Year: 2010 Body Style: 2D SHORT VIN: Mileage In:
Make: FORD Engine: 8-4.6L-FI License: Mileage Out:
Model: F150 4X2 STX Production Date: State: Vehicle Out:
Color: Int: Condition: Job #:

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes

DECOR

Dual Mirrors
Privacy Glass
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags

SEATS

Cloth Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper

Preliminary Estimate

Customer: HIDALGO COUNTY DISTRICT ATTORNEY

Job Number:

Vehicle: 2010 FORD F150 4X2 STX 2D SHORT 8-4.6L-FI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	CAB						
2	*	Rpr Roof panel				2.5	2.8
3	*	Add for Clear Coat					1.2
4	REAR LAMPS						
5	R&I	High mount lamp w/o hill descent				0.3	
6	#	CORROSION PROTECTION		1	10.00		
7	#	CAR COVER		1	5.00		
SUBTOTALS					15.00	2.8	4.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			15.00
Body Labor	2.8 hrs @	\$ 38.00 /hr	106.40
Paint Labor	4.0 hrs @	\$ 38.00 /hr	152.00
Paint Supplies	4.0 hrs @	\$ 26.00 /hr	104.00
Subtotal			377.40
Sales Tax	\$ 119.00 @	8.2500 %	9.82
Grand Total			387.22
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			387.22

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ANY ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. OCCASIONALLY WORN OR DAMAGED PARTS ARE DISCOVERED WHICH MAY NOT BE EVIDENT ON THE FIRST INSPECTION. NATURALLY, THIS ESTIMATE CAN NOT COVER SUCH CONTIGENCIES. IT IS THE POLICY OF COLLISION CENTER & GLASS THAT WORKMANSHIP IS GUARANTEED.

SHOP IS NOT RESPONSIBLE FOR ITEMS LEFT IN VEHICLES. RUST REPAIRS ARE NOT GUARANTEED. THIS ESTIMATE HAS BEEN REVIEWED WITH VEHICLE OWNER. FULL AMOUNT IS DUE AT DELIVERY UNLESS WE HAVE INSURANCE AUTORIZATION OF PAYMENT. IF THERE IS A DEDUCTABLE, I UNDERSTAND THAT I AM RESPONSIBLE FOR PAYMENT AT TIME OF DELIVERY. 100% SATISFACTION IS OUR GOAL. YOUR COMMENTS ARE VALUED AND APPRECIATED.

SIGNATURE _____ DATE _____