

REFERENCE NO.	DESCRIPTION	INVOICE DATE	INVOICE AMOUNT	DISCOUNT TAKEN	AMOUNT PAID
	MODEL#M30TSS9PW1AN UC# <i>CLN3026</i> ID #IC8RR17TXDS663963 <i>Dodge Ram - White</i>				426.90
					0.00
CHECK DATE	CHECK NO.	PAYEE		DISCOUNTS TAKEN	CHECK AMOUNT
10/23/13	F 031238	HIDALGO COUNTY			\$426.90

THE FACE OF THIS DOCUMENT HAS A COLORED BACKGROUND ON WHITE PAPER

SOUTH TEXAS COMMUNICATIONS, INC.
P.O. BOX 3712
McALLEN, TEXAS 78502
PHONE (956) 687-8591

FROST NATIONAL BANK
McALLEN, TEXAS
30-9/1140
80

F 031238

Memo: **F 031238** **Oct 23, 2013** **426.90**
CHECK NO. DATE AMOUNT

Four Hundred Twenty-Six and 90/100 Dollars

PAY TO THE ORDER OF: **HIDALGO COUNTY**



AUTHORIZED SIGNATURE

SECURITY FEATURES INCLUDED. DETAILS ON BACK.

⑈031238⑈ ⑆114000093⑆ 80 0507091⑈

**COLLISION CENTER AUTO BODY &
GLASS**

Workfile ID: 436c5185
Federal ID: 742570397

1610 N. MCCOLL, MCALLEN, TX 78501
Phone: (956) 686-4054
FAX: (956) 686-2511

Preliminary Estimate

Customer: HIDALGO COUNTY CONSTABLE PCT #4

Job Number:

Written By: JUAN MIRELES

Insured: HIDALGO COUNTY
CONSTABLE PCT #4

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

Owner:

HIDALGO COUNTY CONSTABLE PCT #4

Inspection Location:

COLLISION CENTER AUTO BODY & GLASS
1610 N. MCCOLL
MCALLEN, TX 78501
Repair Facility
(956) 686-4054 Day

Insurance Company:

VEHICLE

Year: 2013

Body Style: 4D P/U

VIN: 1C6RR7KTXDS663963

Mileage In:

Make: DODG

Engine: 8-5.7L-FI

License: CNL3026

Mileage Out:

Model: RAM 1500 4X4 CREW
EXPRESS

Production Date:

State: TX

Vehicle Out:

Color: Int:

Condition:

Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

DECOR

Dual Mirrors

Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Keyless Entry

Message Center

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

SEATS

Cloth Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

TRUCK

Power Rear Window

Trailer Hitch

Trailer Package

Preliminary Estimate

Customer: HIDALGO COUNTY CONSTABLE PCT #4

Job Number:

Vehicle: 2013 DODG RAM 1500 4X4 CREW EXPRESS 4D P/U 8-5.7L-FI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	CAB						
2	*	Rpr Roof panel w/o sunroof (STL)				2.5	3.0
3	*	Add for Clear Coat					1.6
4	REAR LAMPS						
5		R&I High mount lamp				0.3	
6	#	CORROSION PROTECTION		1	10.00		
7	#	CAR COVER		1	5.00		
SUBTOTALS					15.00	2.8	4.6

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			15.00
Body Labor	2.8 hrs @	\$ 38.00 /hr	106.40
Paint Labor	4.6 hrs @	\$ 38.00 /hr	174.80
Paint Supplies	4.6 hrs @	\$ 26.00 /hr	119.60
Subtotal			415.80
Sales Tax	\$ 134.60 @	8.2500 %	11.10
Grand Total			426.90
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			426.90

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ANY ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. OCCASIONALLY WORN OR DAMAGED PARTS ARE DISCOVERED WHICH MAY NOT BE EVIDENT ON THE FIRST INSPECTION. NATURALLY, THIS ESTIMATE CAN NOT COVER SUCH CONTINGENCIES. IT IS THE POLICY OF COLLISION CENTER & GLASS THAT WORKMANSHIP IS GUARANTEED.

SHOP IS NOT RESPONSIBLE FOR ITEMS LEFT IN VEHICLES. RUST REPAIRS ARE NOT GUARANTEED. THIS ESTIMATE HAS BEEN REVIEWED WITH VEHICLE OWNER. FULL AMOUNT IS DUE AT DELIVERY UNLESS WE HAVE INSURANCE AUTORIZATION OF PAYMENT. IF THERE IS A DEDUCTABLE , I UNDERSTAND THAT I AM RESPONSIBLE FOR PAYMENT AT TIME OF DELIVERY. 100% SATISFACTION IS OUR GOAL. YOUR COMMENTS ARE VALUED AND APPRECIATED.

SIGNATURE _____ DATE _____