

Detailed Payment Summary

GEICO ADVANTAGE INSURANCE CO

Field Claim Center: 09 Dallas

NO. N 166228453

Date: 01/14/2014

4201 SPRING VALLEY RD
DALLAS TX 75244-3631

Claim #: 0381516780101022

Date of Loss: 12/01/2013

Claimant Name: County Hidalgo Attn Safety

Insured Name: Al Robert Chapa

Tax ID / SS# /

Atty ADJ Code:

Adjuster Code: F307

Pay To:

County Hidalgo Attn Safety Dept

County Hidalgo Attn Safety Dept
PO Box 1356
Edinburg TX 78540-1356



Total Amount:

\$****1,199.92

Payment Type:

LOSS

IP AND FEATURE AND AMOUNT

03 APD \$***1199.92

In Payment Of

Property Damage Coverage

Visit geico.com

Now, parties involved in a GEICO claim can track the progress of the claim, view damage photos and more at geico.com! *GEICO policyholders can make a payment, change drivers or vehicles and request additional coverages.* Not insured with GEICO? 15 minutes could save you 15% or more on car insurance. Of course, we're also available for policy or claim service 24/7 at 1-800-841-3000.

* These online services are unavailable to Assigned Risk policyholders.

clmschck

PLEASE DETACH AND KEEP FOR YOUR RECORDS

GEICO ADVANTAGE INSURANCE CO
4201 SPRING VALLEY RD
DALLAS TX 75244-3631

Bank of America
Hartford, CT 06120

51-44
119 CT

NO. N 166228453

VOID AFTER 180 DAYS

Date: 01/14/2014

Claimant:

County Hidalgo Attn Safety

Claim Number: 0381516780101022

Insured Name:

Al Robert Chapa

Feature Symbol & Amount

APD \$***1199.92

Amount:

\$****1,199.92

ONE-THOUSAND-ONE-HUNDRED-NINETY-NINE*AND*92/100*DOLLARS

Pay to the Order of:

County Hidalgo Attn Safety Dept

In Payment of:

Property Damage Coverage

Mail To:

County Hidalgo Attn Safety Dept
PO Box 1356
Edinburg TX 78540-1356

CG Schan

000021381516780101022C05261

10000001E 000014 000001 /000001 000001 /000001

Quote for Rear Repair Only

Rear Damage of County vehicle

MAACO COLLISION REPAIR
1500 W. POLK
PHARR, TEXAS 78577
OFFICE: 956-664-0405 FAX: 956-664-0506
TEXAS TAX ID # 1-74-2354530-4

*** PRELIMINARY ESTIMATE ***

01/06/2014 02:11 PM

Owner

Owner: HIDALGO COUNTY PROBATION
Contact: SERGIO REYES
Address: **Work/Day:** (956)533-0574

Inspection

Inspection Date: 01/06/2014 02:13 PM
Primary Impact: Right Rear Corner
Inspection Type:
Secondary Impact:
Appraiser Name: TIM HONEYCUTT
Address: 1500 W. POLK
City State Zip: Pharr, TX 78577
Email: MAACO1582@AOL.COM
Appraiser License # :
Work/Day: (956)664-0405
FAX:

Repairer

Repairer: MAACO COLLISION REPAIR
Address: 1500 W. POLK
City State Zip: PHARR, TX 78577
Email: thoney1006@aol.com
Contact: TIM HONEYCUTT
Work/Day: (956)664-0405
FAX: (956)664-0506

Vehicle

2012 Ford Escape XLT 4 DR Wagon
6cyl Gasoline 3.0 Flex
6-Speed Automatic
Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage
VIN: 1FMCU0DG6CKC47844
Mileage Type: Actual
Code: P7123C
Int. Refinish: Two-Stage

Options

- | | | |
|--------------------------|-------------------------|--------------------------|
| 2nd Row Head Airbags | AM/FM CD Player | Air Conditioning |
| Aluminum/Alloy Wheels | Anti-Lock Brakes | Auto Headlamp Control |
| Automatic Dimming Mirror | Bucket Seats | Center Console |
| Chrome Grille | Cruise Control | Dual Airbags |
| Flip-Up Liftgate Window | Floor Mats | Fog Lights |
| Halogen Headlights | Head Airbags | Illuminated Visor Mirror |
| Intermittent Wipers | Keyless Entry Keypad | Keyless Entry System |
| Leather Steering Wheel | Lighted Entry System | MP3 Player |
| Overhead Console | Power Brakes | Power Door Locks |
| Power Drivers Seat | Power Mirrors | Power Steering |
| Power Windows | Rear Step Bumper | Rear Window Defroster |
| Rear Window Wiper/Washer | Roof/Luggage Rack | Side Airbags |
| Sirius Satellite Radio | Split Folding Rear Seat | Stability Cntrl Suspensn |

Strg Wheel Radio Control
 Tinted Glass
 Trip Computer

Tachometer
 Tire Pressure Monitor
 Velour/Cloth Seats

Tilt Steering Wheel
 Traction Control System

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R	
Rear Bumper											
1	EC	566		Cover,Rear Bumper	Replace Economy	\$189.00*			0.5	SM	
2	L	566	13	Cover,Rear Bumper	Refinish				3.4	RF	
					2.3 Surface						
					0.6 Two-stage setup						
					0.5 Two-stage						
3	E	55		Reinf,Rear Bumper	9L8Z17D942A	\$117.25			1.3	SM	
4	EC	567		Absorber,Rear Bumper	Replace Economy	\$76.00*			INC	SM	
Rear Body Lamps And Floor Pan											
5	E	581		Muffler Assembly	9L8Z5A212C	\$256.54			0.4	ME	
6	I	486		Pnl,Rear Body Outer	Repair				2.0*	SM	
7	L	486		Pnl,Rear Body Outer	Refinish				1.2	RF	
					1.0 Surface						
					0.2 Two-stage						
Manual Entries											
8	SB			waste removal	Sublet Repair	\$5.00*				SM*	
		8	Items								
			MC	Message							
			13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE							

Estimate Total & Entries

Gross Parts						\$373.79				
Other Parts						\$265.00				
Paint Materials						\$128.80				
Parts & Material Total									\$767.59	
Tax on Parts & Material					@ 8.250%				\$63.33	
Labor				Rate	Replace Hrs	Repair Hrs	Total Hrs			
Sheet Metal (SM)				\$40.00	1.8	2.0	3.8	\$152.00		
Mech/Elec (ME)				\$70.00	0.4		0.4	\$28.00		
Frame (FR)				\$50.00						
Refinish (RF)				\$40.00	4.6		4.6	\$184.00		
Paint Materials				\$28.00						
Labor Total							8.8 Hours		\$364.00	
Sublet Repairs								\$5.00		
Gross Total									\$1,199.92	
Net Total									\$1,199.92	

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 78577 Audatex Host