



**CONSENT AGENDA
DRAINAGE DISTRICT
BOARD OF DIRECTORS
September 30, 2014
9:00 A.M.**

NOTICE is hereby given in accordance with Chapter 551, Texas Government Code, that a REGULAR MEETING of the Drainage District #1 Board of Directors will be held at the Edinburg Council Chambers 415 W. University Drive, Edinburg, Hidalgo County, Texas. Discussion and possible action relating to the following business will be transacted:

**NOTICE TO THE PUBLIC
CONSENT AGENDA**

The following items are of a routine or administrative nature. The Drainage District #1 Board has been furnished with background and support on each item, and/or it has been discussed at a previous meeting. All items will be acted upon by one vote without being discussed separately unless requested by a Board Member, in which event the item or items will immediately be withdrawn for individual consideration in its normal sequence after the items not requiring separate discussion have been acted upon. The remaining items will be adopted by one vote.

1. Approval of check register and payment of claims and bills - County Treasurer

2. AI-46747 2013 Bonds:

Request Approval to issue payment after review and audit procedures have been completed on the following items:

Invoice no. 0059958 in the amount of \$19,996.97 and Inv. no. 0060528 in the amount of \$8,151.58 from Melden & Hunt, Inc. related to Work Authorization no. 1-Rado Drain Project. PO#622613.

AI-46747

2.

DRAINAGE - CONSENT

Meeting Date: 09/30/2014

Submitted By: Claudette Guerrero, DRAINAGE
DISTRICT

Department: DRAINAGE DISTRICT

Information

CAPTION

2013 Bonds:

Request Approval to issue payment after review and audit procedures have been completed on the following items:

Invoice no. 0059958 in the amount of \$19,996.97 and Inv. no. 0060528 in the amount of \$8,151.58 from Melden & Hunt, Inc. related to Work Authorization no. 1-Rado Drain Project. PO#622613.

BACKGROUND


Attachments

Melden Inv#0059958

Melden Inv#0060528

Form Review

Inbox	Reviewed By	Date
Budget & Management	Debbie Tamez	09/26/2014 05:07 PM
Final Approval	Monica Badillo	09/26/2014 05:16 PM
Form Started By: Claudette Guerrero		Started On: 09/26/2014 04:40 PM
	Final Approval Date: 09/26/2014	



MELDEN & HUNT INC.

CONSULTANTS ENGINEERS SURVEYORS

TBPE FIRM# F-1435

115 West McIntyre
Edinburg, TX 78541
(956) 381-0981
(956) 381-1839 fax
www.meldenandhunt.com

227 N. FM 3167
Rio Grande City, TX 78582
(956) 487-8256
(956) 488-8591 fax

Date: September 18, 2014

Transmittal

To:	Hidalgo County Drainage District
Attention:	Mr. Godfrey Garza
From:	Laura C. Garcia
Job Title:	RADO Drain Project
Job No.:	07129.01/02/16

The following is being transmitted:

- Plans
 Construction Drawings
 Documents
 CD/Diskette
 Legal Descriptions
 Letter
 Original Plat
 Copies
 Fee
 Other:

Transmitted as Follows:

- For your use
 As Requested
 Review/Comment
 Approval
 Signature
 FYI

No. of Copies	Description
1	August Invoice and Inspection Reports; August Engineering Report
1	May Invoice and Inspection Reports; May Engineering Report (second submission)

Remarks: Please review for processing.

RECEIVED
HIDALGO COUNTY
DRAINAGE DISTRICT #1

SEP 18 2014

3:09 AM/PM

BY: Rosa Arce

Transmitted By: Laura C. Garcia, Accounting Dept.

Received By: _____

Date: _____ Time: _____


HIDALGO COUNTY DRAINAGE DISTRICT NUMBER ONE

902 NORTH DOOLITTLE

EDINBURG, TEXAS 78542

(956) 292-7080

FAX (956) 292-7089



GODFREY GARZA, JR.
MANAGER

INVOICE PROCESSING CHECKLIST

Date Received: 9-18-14

Engineer/Firm Name: MELDEN & HUNT

Project Name/Number: RADO DRAIN PCT 2

Invoice No: #0059958

Logged in and Scanned: 318 9/18 By: Rosa Arce Forwarded to: Joey Garza

Engineer	Name	Date	Comment
Scope of work reviewed			

Accounting	Name	Date	Comment
Encumbrance			
Purchase Order Attached			
Audit			
Final Approval for Agenda			

	Name	Date	Comment
Placed on Agenda			

Additional Comments: _____

7129.02		May		2014	
Invoice 59958					
Billing Phase	Fee	Prior Fee	Percent Complete	Current Fee	Earned
Eval of Alt/Prel. Eng Report	30,118.90	30,118.90	100.00		30,118.90
Design Engineering	180,713.38	180,713.38	100.00		180,713.38
Bidding/Recommendations	15,059.45	15,059.45	100.00		15,059.45
Const. Eng. Derv/Proj.Perfor	75,297.24	18,824.31	75.00	18,824.31	56,472.93
Reimbursables	0.00		0.00		0.00
Totals	301,188.97	263,540.35		18,824.31	282,364.66
7129.01					
Billing Phase	Fee	Prior Fee	Percent Complete	Current Fee	Earned
Geotech	25,000.00	25,000.00	100.00	0.00	25,000.00
Surveying Services (.09)	16,732.72	16,732.72	100.00	0.00	16,732.72
Res. Project Inspection	85,867.33	0.00	0.00	0.00	0.00
Const. Material Testing	25,000.00	1,750.00	7.00		1,750.00
Reimbursables	0.00	0.00	0.00		0.00
	152,600.05	43,482.72		0.00	43,482.72
7129.16					
(Billed Hourly as per Contract)			Current Hours	Total Amount	
			16.50	1,172.66	
Total This Invoice				19,996.97	

RECEIVED
HIDALGO COUNTY
DRAINAGE DISTRICT #1

SEP 18 2014

3:09 AM/PM

BY: Rosa Arce

SEP 18 2014

3:09 AM (PM)

BY: Rosa Arce

Invoice

MELDEN & HUNT, INC.
Consulting Engineers
115 West McIntyre
Edinburg, Texas 78541

May 31, 2014
Project No: 07129.02
Invoice No: 0059958

Hidalgo County Drainage District #1
Attention: Godfrey Garza
902 N. Doolittle
Edinburg, TX 78541

Project 07129.02 HCDD#1-RADO Drain Pct 2- Basic Services
Rado Drain Pct 2 - Basic Services. P.O. #622613.

Professional Services from May 01, 2014 to May 31, 2014
Fee

Billing Phase	Fee	Percent Complete	Earned
Eval. of Alt/ Prel. Eng. Report	30,118.90	100.00	30,118.90
Design Engineering	180,713.38	100.00	180,713.38
Bidding/ Recommendations	15,059.45	100.00	15,059.45
Const. Eng. Serv/Proj. Performance	75,297.24	75.00	56,472.93
Reimbursables	0.00	0.00	0.00
Total Fee	301,188.97		282,364.66
	Previous Fee Billing		263,540.35
	Current Fee Billing		18,824.31
	Total Fee		18,824.31
		Total this Project	\$18,824.31

Billings to date

Fee	Current	Prior	Total
Expense	18,824.31	263,540.35	282,364.66
Total	18,824.31	263,557.35	282,381.66

Project 07129.01 HCDD#1 -RADO Drain Pct. 2 - Special Serv
Rado Drain Pct. 2 - Special Services. P.O. #622596.
Fee

Billing Phase	Fee	Percent Complete	Earned
Geotech	25,000.00	100.00	25,000.00
Surveying Services (.09)	16,732.72	100.00	16,732.72
Resident Proj. Inspection (.16)	85,867.33	0.00	0.00
Const. Material Testing	25,000.00	7.00	1,750.00
Reimbursables	0.00	0.00	0.00
Total Fee	152,600.05		43,482.72
	Previous Fee Billing		43,482.72
	Current Fee Billing		0.00
	Total Fee		0.00
		Total this Project	0.00

Billings to date

Project	07129.02	HCDD#1-RADO Drain Pct 2- Basic Services		Invoice	0059958
Fee		Current	Prior	Total	
		0.00	43,482.72	43,482.72	
Total		0.00	43,482.72	43,482.72	

 Project 07129.16 HCDD#1-twin 115-in CMP, RADO Drain
 Rado Drain Pct 2 - Inspections Services as per contract rates.
 Professional Personnel

Totals	Hours	Amount	
Total Labor	16.50	1,172.66	
			1,172.66
			Total this Project \$1,172.66

Billings to date

Labor	Current	Prior	Total	
	1,172.66	4,974.90	6,147.56	
Total	1,172.66	4,974.90	6,147.56	
				Total this Invoice \$19,996.97

Outstanding Invoices

Number	Date	Balance
0058805	12/31/2013	21,836.20
0059070	1/31/2014	10,093.27
0059244	2/28/2014	9,630.05
0059433	3/31/2014	8,737.91
0059772	4/30/2014	12,147.43
Total		62,444.86

Total Now Due \$82,441.83

Labor Detail

MELDEN & HUNT, INC.

Thursday, June 12, 2014
4:18:03 PM

For the period 5/1/2014 - 5/31/2014

	Date	Regular Hours	Total Ovt Hrs	Total Hours	Regular Billing	Tot. Ovt Billing	Total Billing
00236	5/1/2014	1.00		1.00	71.07		71.07
00236	5/2/2014	.50		.50	35.54		35.54
00236	5/5/2014	1.00		1.00	71.07		71.07
00236	5/6/2014	1.00		1.00	71.07		71.07
00236	5/8/2014	1.00		1.00	71.07		71.07
00236	5/9/2014	1.00		1.00	71.07		71.07
00236	5/12/2014	1.00		1.00	71.07		71.07
00236	5/13/2014	1.00		1.00	71.07		71.07
00236	5/14/2014	1.00		1.00	71.07		71.07
00236	5/15/2014	1.00		1.00	71.07		71.07
00236	5/16/2014	1.00		1.00	71.07		71.07
00236	5/19/2014	1.00		1.00	71.07		71.07
00236	5/21/2014	1.00		1.00	71.07		71.07
00236	5/23/2014	1.00		1.00	71.07		71.07
00236	5/27/2014	1.00		1.00	71.07		71.07
00236	5/29/2014	1.00		1.00	71.07		71.07
00236	5/30/2014	1.00		1.00	71.07		71.07
Total for 126		16.50		16.50	1,172.66		1,172.66
Total for 06		16.50		16.50	1,172.66		1,172.66
Total for 07129.16		16.50		16.50	1,172.66		1,172.66

Project Number: 07129.16 HCDD#1-twin 115-in CMP, RADO Drain

Labor Code Level 1: 06 Construction Administration

Labor Code Level 2: 126 Inspection / Reports



TBPE Firm # F-1435
TBPLS # 10096900

MELDEN & HUNT INC.


CONSULTANTS • ENGINEERS • SURVEYORS
FRED L. KURTH • ALLAN F. BOOE • KELLEY A. HELLER-VELA • ROBERT TAMEZ

RADO Drain Project Engineering Report

May 2014

- 1) IPR completed repair of west pipe from station 29+00 to station 36+26.
- 2) IPR started cleaning the first 300 feet of the east pipe starting at the south end.

Site visit with Godfrey May 8th 5:00

 5-31-14
Fred L. Kurth, P.E. #54151



FIELD PROJECT REPORT

REPORT: 72 MON TUE WED TH FRI DATE: 05-01-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED N CONTRACT

OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
---------------	-----------------------------------------	---------------------------

CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
--------------------	-----------------------------------------------	--

WEATHER	TEMPERATURES: 79	CONDITION
<input type="checkbox"/> CLEAR <input checked="" type="checkbox"/> CLOUDY <input type="checkbox"/> RAIN <input type="checkbox"/> WINDY <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9		TOTAL HOUR'S: 8	

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is placing injection ports for grouting application in the next few days.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 73 MON TUE WED TH FRI DATE: 05-02-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER: *Hidalgo County Drainage District* **MHI JOB #** 07129.16

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER	TEMPERATURES: 82	CONDITION
<input type="checkbox"/> CLEAR <input checked="" type="checkbox"/> CLOUDY <input checked="" type="checkbox"/> RAIN <input type="checkbox"/> WINDY <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 **TOTAL HOUR'S:** 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is running pumps to lower water levels.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 74 MON TUE WED TH FRI DATE: 05-05-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
---------------	-----------------------------------------	---------------------------

CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
--------------------	-----------------------------------------------	--

WEATHER	TEMPERATURES: 87	CONDITION
<input checked="" type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> RAIN <input type="checkbox"/> WINDY <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8
----------------------------	------------------------

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR has started grout injection of bottom of pipe working from station 36+00 south.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 75 MON TUE WED TH FRI DATE: 05-06-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # 07129.16

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER: CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST
TEMPERATURES: 91 CONDITION: _____

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is continuing with controlling water levels on last section and grouting bottom of pipe.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 76 MON TUE WED TH FRI DATE: 05-08-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED N CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	

WEATHER **TEMPERATURES: 88** **CONDITION**
 CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTION
PERSONNEL ON JOB: 9		TOTAL HOUR'S: 8	

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is attempting first material application on top half of pipe working south from station 36+00.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 77 MON TUE WED TH FRI DATE: 05-09-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	

WEATHER	TEMPERATURES: 94	CONDITION
<input type="checkbox"/> CLEAR <input checked="" type="checkbox"/> CLOUDY <input checked="" type="checkbox"/> RAIN <input type="checkbox"/> WINDY <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTION
PERSONNEL ON JOB: 0		TOTAL HOUR'S: 0	

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
No Activity (Rain)

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 78 MON TUE WED TH FRI DATE: 05-12-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER: *Hidalgo County Drainage District* **MHI JOB # 07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER	TEMPERATURES: 93	CONDITION
<input type="checkbox"/> CLEAR <input checked="" type="checkbox"/> CLOUDY <input checked="" type="checkbox"/> RAIN <input type="checkbox"/> WINDY <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 0 TOTAL HOUR'S: 0

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
No Activity (Rain)

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 79 MON TUE WED TH FRI DATE: 05-13-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED N CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 80	CONDITION
<input type="checkbox"/> CLEAR <input checked="" type="checkbox"/> CLOUDY <input checked="" type="checkbox"/> RAIN <input type="checkbox"/> WINDY	<input type="checkbox"/> DRY <input type="checkbox"/> DAMP	<input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTION
PERSONNEL ON JOB: 0	TOTAL HOUR'S: 0		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
No Activity (Rain)

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 80 MON TUE WED TH FRI DATE: 05-14-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # *07129.16*

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 63 CONDITION
 CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR continues with grout injection on bottom at station 32+00.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 81 MON TUE WED TH FRI DATE: 05-15-15

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 86	CONDITION
<input checked="" type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> RAIN <input type="checkbox"/> WINDY <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR continues with grout injection on bottom at station 33+00.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 82 MON TUE WED TH FRI DATE: 05-16-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # 07129.16

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 88 CONDITION
 CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR nearing completion of sealing bottom of last section of west pipe.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 83 MON TUE WED TH FRI DATE: 05-19-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
---------------	-----------------------------------------	---------------------------

CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
--------------------	-----------------------------------------------	--

WEATHER	TEMPERATURES: 92	CONDITION
<input checked="" type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> RAIN <input type="checkbox"/> WINDY <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8
----------------------------	------------------------

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR has started working on east pipe at the south end by cleaning and power washing first 300 feet.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 84 MON TUE WED TH FRI DATE: 05-21-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # 07129.16

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 100 CONDITION
 CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on bottom half material application from station 36+00 south to station 29+00.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 85 MON TUE WED TH FRI DATE: 05-23-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # *07129.16*

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 101 CONDITION
 CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on final material application from station 36+00 south to station 29+00.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 87 MON TUE WED TH FRI DATE: 05-29-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # 07129.16

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER: _____ TEMPERATURES: 102 CONDITION: _____
 CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is cleaning west pipe and sealing minor weeping points along the length of pipe.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 88 MON TUE WED TH FRI DATE: 05-30-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	

WEATHER TEMPERATURES: 102 CONDITION

CLEAR CLOUDY RAIN WINDY DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is continuing the cleaning of west pipe and sealing minor weeping points along the length of pipe.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela



TBPE Firm # F-1435
TBPLS # 10096900

MELDEN & HUNT INC.

CONSULTANTS • ENGINEERS • SURVEYORS
FRED L. KURTH • ALLAN F. BOOE • KELLEY A. HELLER-VELA • ROBERT TAMEZ

RECEIVED
HIDALGO COUNTY
DRAINAGE DISTRICT #1

SEP 18 2014


3:09 AM PM

BY: Rosa Arce

RADO Drain Project Engineering Report

August 2014

- 1) IPR has completed repair of east pipe.
- 2) They have also grouted head walls.
- 3) IPR subcontractor will begin work on removal of dam and placement of manhole covers.


Fred L. Kurth, P.E. #54151 9-18-14



FIELD PROJECT REPORT

REPORT: 106 MON TUE WED TH FRI DATE: 08-01-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
---------------	-----------------------------------------	---------------------------

CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
--------------------	-----------------------------------------------	--

WEATHER	TEMPERATURES: 103	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY <input type="checkbox"/> RAIN <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input checked="" type="checkbox"/> OVERCAST		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8
---------------------	-----------------

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is continuing with placement of injection ports at station 35+00.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 107 MON TUE WED TH FRI DATE: 08-05-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 102	CONDITION
<input type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input checked="" type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

IPR is working on sealing the top half of remaining pipe buttering in the cracks with grout.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 108 MON TUE WED TH FRI DATE: 08-07-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # **07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 104 CONDITION

<input checked="" type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY	<input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN	<input type="checkbox"/> DRY	<input type="checkbox"/> DAMP	<input type="checkbox"/> MUDDY	<input type="checkbox"/> OVERCAST
-------------------------------------------	---------------------------------	----------------------------------------	-------------------------------	------------------------------	-------------------------------	--------------------------------	-----------------------------------

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on placing final injection ports around final 100 ft of pipe around joints.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 109 MON TUE WED TH FRI DATE: 08-11-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 100	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input checked="" type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is preparing to run sled for initial pass.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 110 MON TUE WED TH FRI DATE: 08-13-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # 07129.16

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 100 CONDITION

CLEAR CLOUDY PARTLY CLOUDY RAIN DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is continuing with running sled for final sealing of last section.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 111 MON TUE WED TH FRI DATE: 08-15-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 100	CONDITION
<input type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input checked="" type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9		TOTAL HOUR'S: 8	

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

IPR has completed sealing of east pipe and will grout head walls.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 112 MON TUE WED TH FRI DATE: 08-18-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 100	CONDITION
<input checked="" type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on grouting of head walls and equipment break down.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 113 MON TUE WED TH FRI DATE: 08-20-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 100	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input checked="" type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

IPR is breaking down equipment.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 114 MON TUE WED TH FRI DATE: 08-25-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 102	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input checked="" type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on clean up within the east pipe.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 115 MON TUE WED TH FRI DATE: 08-27-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 102	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input checked="" type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY <input type="checkbox"/> DAMP	<input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

Had a walkthrough of the east and west pipes. Everything looks good. REIM will be in next week to remove dam and place manhole rims and covers.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 116 MON TUE WED TH FRI DATE: 08-29-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 102	CONDITION
<input type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> DRY <input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST
<input checked="" type="checkbox"/> RAIN		

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 0	TOTAL HOUR'S: 0		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input type="checkbox"/> PUMPS	<input type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None


DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
No Activity

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela



MELDEN & HUNT INC.

CONSULTANTS ENGINEERS SURVEYORS

TBPE FIRM# F-1435

115 West McIntyre
Edinburg, TX 78541
(956) 381-0981
(956) 381-1839 fax
www.meldenandhunt.com

227 N. FM 3167
Rio Grande City, TX 78582
(956) 487-8256
(956) 488-8591 fax

Date: September 18, 2014

Transmittal

To:	Hidalgo County Drainage District
Attention:	Mr. Godfrey Garza
From:	Laura C. Garcia
Job Title:	RADO Drain Project
Job No.:	07129.01/.02/.16

The following is being transmitted:

- Plans
- Construction Drawings
- Documents
- CD/Diskette
- Legal Descriptions
- Letter
- Original Plat
- Copies
- Fee
- Other:

Transmitted as Follows:

- For your use
- As Requested
- Review/Comment
- Approval
- Signature
- FYI

No. of Copies	Description
1	August Invoice and Inspection Reports; August Engineering Report
1	May Invoice and Inspection Reports; May Engineering Report (second submission)

Remarks: Please review for processing.

RECEIVED
HIDALGO COUNTY
DRAINAGE DISTRICT #1

Transmitted By: Laura C. Garcia, Accounting Dept.

SEP 18 2014

3:09 AM/PM

Received By: _____

Date: _____ Time: _____

BY: Pasa Arce

HIDALGO COUNTY DRAINAGE DISTRICT NUMBER ONE

902 NORTH DOOLITTLE

EDINBURG, TEXAS 78542

(956) 292-7080

FAX (956) 292-7089



GODFREY GARZA, JR.
MANAGER

INVOICE PROCESSING CHECKLIST

Date Received: Sep. 18 - 2014

Engineer/Firm Name: Melden & Hunt

Project Name/Number: RADO Drain Pet 2

Invoice No: #0060528

Logged in and Scanned: 314 9/18 By: Rosa Orce Forwarded to: Joey Garza

Engineer	Name	Date	Comment
Scope of work reviewed			

Accounting	Name	Date	Comment
Encumbrance			
Purchase Order Attached			
Audit			
Final Approval for Agenda			

	Name	Date	Comment
Placed on Agenda			

Additional Comments: _____

7129.02				August	2014	
				Invoice	60528	
Billing Phase	Fee	Prior Fee	Percent Complete	Current Fee	Earned	
Eval of Alt/Prel. Eng Report	30,118.90	30,118.90	100.00		30,118.90	
Design Engineering	180,713.38	180,713.38	100.00		180,713.38	
Bidding/Recommendations	15,059.45	15,059.45	100.00		15,059.45	
Const. Eng. Derv/Proj.Perfor	75,297.24	67,767.52	100.00	7,529.72	75,297.24	
Reimbursables	0.00		0.00		0.00	
Totals	301,188.97	293,659.25		7,529.72	301,188.97	
7129.01						
Billing Phase	Fee	Prior Fee	Percent Complete	Current Fee	Earned	
Geotech	25,000.00	25,000.00	100.00	0.00	25,000.00	
Surveying Services (.09)	16,732.72	16,732.72	100.00	0.00	16,732.72	
Res. Project Inspection	85,867.33	0.00	0.00	0.00	0.00	
Const. Material Testing	25,000.00	1,750.00	7.00		1,750.00	
Reimbursables	0.00	0.00	0.00		0.00	
	152,600.05	43,482.72		0.00	43,482.72	
7129.16						
(Billed Hourly as per Contract)			Current Hours	Total Amount		
			8.75	621.86		
				Total This Invoice	8,151.58	

RECEIVED
HIDALGO COUNTY
DRAINAGE DISTRICT #1

SEP 18 2014

3:09 AM/PM

BY: Rosa Arce

SEP 18 2014

3:09 AM (PM)

BY: Rosa Arce

Invoice

MELDEN & HUNT, INC.
Consulting Engineers
115 West McIntyre
Edinburg, Texas 78541

August 31, 2014
Project No: 07129.02
Invoice No: 0060528

Hidalgo County Drainage District #1
Attention: Godfrey Garza
902 N. Doolittle
Edinburg, TX 78541

Project 07129.02 HCDD#1-RADO Drain Pct 2- Basic Services
Rado Drain Pct 2 - Basic Services. P.O. #622613.

Professional Services from August 01, 2014 to August 31, 2014

Fee

Billing Phase	Fee	Percent Complete	Earned
Eval. of Alt/ Prel. Eng. Report	30,118.90	100.00	30,118.90
Design Engineering	180,713.38	100.00	180,713.38
Bidding/ Recommendations	15,059.45	100.00	15,059.45
Const. Eng. Serv/Proj. Performance	75,297.24	100.00	75,297.24
Reimbursables	0.00	0.00	0.00
Total Fee	301,188.97		301,188.97
	Previous Fee Billing		293,659.25
	Current Fee Billing		7,529.72
	Total Fee		7,529.72
		Total this Project	\$7,529.72

Billings to date

	Current	Prior	Total
Fee	7,529.72	293,659.25	301,188.97
Expense	0.00	17.00	17.00
Total	7,529.72	293,676.25	301,205.97

Project 07129.01 HCDD#1 -RADO Drain Pct. 2 - Special Serv
Rado Drain Pct. 2 - Special Services. P.O. #622596.

Fee

Billing Phase	Fee	Percent Complete	Earned
Geotech	25,000.00	100.00	25,000.00
Surveying Services (.09)	16,732.72	100.00	16,732.72
Resident Proj. Inspection (.16)	85,867.33	0.00	0.00
Const. Material Testing	25,000.00	7.00	1,750.00
Reimbursables	0.00	0.00	0.00
Total Fee	152,600.05		43,482.72
	Previous Fee Billing		43,482.72
	Current Fee Billing		0.00
	Total Fee		0.00
		Total this Project	0.00

Billings to date

	Current	Prior	Total
Fee	0.00	43,482.72	43,482.72
Total	0.00	43,482.72	43,482.72

Project 07129.16 HCDD#1-twin 115-in CMP, RADO Drain
 Rado Drain Pct 2 - Inspections Services as per contract rates.

Professional Personnel

	Hours	Amount	
Totals	8.75	621.86	
Total Labor			621.86
			Total this Project \$621.86

Billings to date

	Current	Prior	Total	
Labor	621.86	7,391.29	8,013.15	
Total	621.86	7,391.29	8,013.15	
				Total this Invoice \$8,151.58

Outstanding Invoices

Number	Date	Balance	
0059958	5/31/2014	19,996.97	
0060151	6/30/2014	10,428.27	
0060330	7/31/2014	2,110.05	
Total		32,535.29	
			Total Now Due \$40,686.87

Labor Detail

Thursday, September 18, 2014
9:00:33 AM

MELDEN & HUNT, INC.

Transactions for 8/2014 through 8/2014

		Date	Regular Hours	Total Ovt Hrs	Total Hours	Regular Billing	Tot. Ovt Billing	Total Billing
Project Number: 07129.16 HCDD#1-twin 115-in CMP, RADO Drain								
Labor Code Level 1: 06 Construction Administration								
Labor Code Level 2: 126 Inspection / Reports								
00236	VELA, JUAN	8/1/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/5/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/7/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/11/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/13/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/15/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/18/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/20/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/25/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/27/2014	.75		.75	53.30		53.30
00236	VELA, JUAN	8/29/2014	.75		.75	53.30		53.30
Total for 126			8.25		8.25	586.30		586.30
Labor Code Level 2: 128 Pay Estimate Certification								
00236	VELA, JUAN	8/18/2014	.50		.50	35.54		35.54
Total for 06			8.75		8.75	621.84		621.84
Total for 07129.16			8.75		8.75	621.84		621.84

FIELD PROJECT REPORT

REPORT: 106

 MON TUE WED TH FRI

DATE: 08-01-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT
OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
WEATHER	TEMPERATURES: 103	CONDITION
<input type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY	<input type="checkbox"/> PARTLY CLOUDY
<input type="checkbox"/> RAIN	<input type="checkbox"/> DRY	<input type="checkbox"/> DAMP
		<input type="checkbox"/> MUDDY
		<input checked="" type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8		

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

IPR is continuing with placement of injection ports at station 35+00.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
 RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 107 MON TUE WED TH FRI DATE: 08-05-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER: *Hidalgo County Drainage District* **MHI JOB # 07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER	TEMPERATURES: 102	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input checked="" type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on sealing the top half of remaining pipe buttering in the cracks with grout.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 108 MON TUE WED TH FRI DATE: 08-07-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER: *Hidalgo County Drainage District* **MHI JOB # 07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER	TEMPERATURES: 104	CONDITION
<input checked="" type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

IPR is working on placing final injection ports around final 100 ft of pipe around joints.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 109 MON TUE WED TH FRI DATE: 08-11-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
---------------	-----------------------------------------	---------------------------

CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
--------------------	-----------------------------------------------	--

WEATHER	TEMPERATURES: 100	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input type="checkbox"/> PARTLY CLOUDY	<input checked="" type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8
----------------------------	------------------------

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

IPR is preparing to run sled for initial pass.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 110 MON TUE WED TH FRI DATE: 08-13-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # **07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 100 CONDITION

CLEAR CLOUDY PARTLY CLOUDY RAIN DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is continuing with running sled for final sealing of last section.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 111	<input type="checkbox"/> MON	<input type="checkbox"/> TUE	<input type="checkbox"/> WED	<input type="checkbox"/> TH	<input checked="" type="checkbox"/> FRI	DATE: 08-15-14
-------------	------------------------------	------------------------------	------------------------------	-----------------------------	-----------------------------------------	----------------

Project Information

PROJECT	RADO Storm Sewer Rehab	DAYS USED IN CONTRACT
OWNER:	Hidalgo County Drainage District	MHI JOB # 07129.16
CONTRACTOR:	Inland Pipe Rehab South Central / REIM	
WEATHER	TEMPERATURES: 100	CONDITION
<input type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY	<input type="checkbox"/> RAIN
	<input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> DRY
		<input type="checkbox"/> DAMP
		<input type="checkbox"/> MUDDY
		<input checked="" type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION
PERSONNEL ON JOB: 9		TOTAL HOUR'S: 8	

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:

IPR has completed sealing of east pipe and will grout head walls.

CONTRACTOR COMMENTS: None

VISITORS:

PROJECT SUPERINTENDENT: Chuck Slack
 RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 112 MON TUE WED TH FRI DATE: 08-18-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # **07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 100 CONDITION

<input checked="" type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY	<input type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN	<input type="checkbox"/> DRY	<input type="checkbox"/> DAMP	<input type="checkbox"/> MUDDY	<input type="checkbox"/> OVERCAST
-------------------------------------------	---------------------------------	----------------------------------------	-------------------------------	------------------------------	-------------------------------	--------------------------------	-----------------------------------

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on grouting of head walls and equipment break down.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 113 MON TUE WED TH FRI DATE: 08-20-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # **07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 100 CONDITION

CLEAR CLOUDY PARTLY CLOUDY RAIN DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 TOTAL HOUR'S: 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is breaking down equipment.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 114 MON TUE WED TH FRI DATE: 08-25-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* **DAYS USED IN CONTRACT:** _____

OWNER: *Hidalgo County Drainage District* **MHI JOB # 07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER: **TEMPERATURES:** 102 **CONDITION:**

<input type="checkbox"/> CLEAR	<input type="checkbox"/> CLOUDY	<input checked="" type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN	<input type="checkbox"/> DRY	<input type="checkbox"/> DAMP	<input type="checkbox"/> MUDDY	<input type="checkbox"/> OVERCAST
--------------------------------	---------------------------------	---------------------------------------------------	-------------------------------	------------------------------	-------------------------------	--------------------------------	-----------------------------------

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9 **TOTAL HOUR'S:** 8

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
IPR is working on clean up within the east pipe.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 115 MON TUE WED TH FRI DATE: 08-27-14

Project Information

PROJECT	<i>RADO Storm Sewer Rehab</i>	DAYS USED IN CONTRACT

OWNER:	<i>Hidalgo County Drainage District</i>	MHI JOB # 07129.16
---------------	-----------------------------------------	---------------------------

CONTRACTOR:	<i>Inland Pipe Rehab South Central / REIM</i>	
--------------------	-----------------------------------------------	--

WEATHER	TEMPERATURES: 102	CONDITION
<input type="checkbox"/> CLEAR <input type="checkbox"/> CLOUDY <input checked="" type="checkbox"/> PARTLY CLOUDY	<input type="checkbox"/> RAIN <input type="checkbox"/> DRY	<input type="checkbox"/> DAMP <input type="checkbox"/> MUDDY <input type="checkbox"/> OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 9	TOTAL HOUR'S: 8
----------------------------	------------------------

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input checked="" type="checkbox"/> PUMPS	<input checked="" type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input checked="" type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
Had a walkthrough of the east and west pipes. Everything looks good. REIM will be in next week to remove dam and place manhole rims and covers.

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela

FIELD PROJECT REPORT

REPORT: 116 MON TUE WED TH FRI DATE: 08-29-14

Project Information

PROJECT: *RADO Storm Sewer Rehab* DAYS USED IN CONTRACT: _____

OWNER: *Hidalgo County Drainage District* MHI JOB # **07129.16**

CONTRACTOR: *Inland Pipe Rehab South Central / REIM*

WEATHER TEMPERATURES: 102 CONDITION

CLEAR CLOUDY PARTLY CLOUDY RAIN DRY DAMP MUDDY OVERCAST

CLASSIFICATION OF WORKMEN ON THE PROJECT

<input checked="" type="checkbox"/> SITEWORK	<input type="checkbox"/> CONCRETE	<input type="checkbox"/> MASONRY	<input type="checkbox"/> REBAR
<input type="checkbox"/> WOOD AND PLASTICS	<input type="checkbox"/> THERMAL MOISTURE PRO	<input type="checkbox"/> DOORS AND WINDOWS	<input type="checkbox"/> FINISHES
<input type="checkbox"/> SPECIALTIES	<input checked="" type="checkbox"/> EQUIPMENT	<input type="checkbox"/> FURNISHINGS	<input type="checkbox"/> SPECIAL CONSTRUCTION
<input type="checkbox"/> CONVEYING SYSTEMS	<input checked="" type="checkbox"/> MECHANICAL	<input type="checkbox"/> ELECTRICAL	<input type="checkbox"/> INSTRUMENTATION

PERSONNEL ON JOB: 0 TOTAL HOUR'S: 0

MAJOR EQUIPMENT ON PROJECT

<input type="checkbox"/> CRANES	<input type="checkbox"/> LOADERS	<input type="checkbox"/> BACKHOES (TRK)	<input type="checkbox"/> BACKHOES (TIRE)	<input type="checkbox"/> DOZERS
<input type="checkbox"/> WELDERS	<input type="checkbox"/> PUMPS	<input type="checkbox"/> COMPRESSORS	<input checked="" type="checkbox"/> TRUCK	<input type="checkbox"/> LIFTS

TESTING DONE TODAY: None

MATERIALS RECEIVED TODAY: None

DIFFICULTIES ON JOB: None

DIFFICIENCIES: None

DISPUTES: None

DESCRIPTION OF WORK ACCOMPLISHED:
No Activity

CONTRACTOR COMMENTS: None

VISITORS: _____

PROJECT SUPERINTENDENT: Chuck Slack
RESIDENT PROJECT REPRESENTATIVE: Juan Vela