

FRED LOYA INSURANCE AGENCY
FOR LOYA INSURANCE COMPANY

Frost Bank 30-971140
Fort Worth, TX

10150193

CLAIMS ACCOUNT
1800 LEE TREVINO
EL PASO, TEXAS 79938

VOID IF NOT PRESENTED FOR PAYMENT WITHIN 6 MONTHS FROM DATE OF ISSUE.

PAY * FOUR THOUSAND NINE HUNDRED FORTY EIGHT DOLLARS & 09 CENTS

TO THE ORDER OF THE COUNTY OF HIDALGO TEXAS
9805 NORTH 10TH STREET
MCALLEN, TX 78504

4,948.09
CHECK AMOUNT

5/27/15

COMMENTS: REF INCIDENT DATE: DECEMBER 10, 2014
FULL & FINAL PAYMENT FOR DAMAGES
BDM



AUTHORIZED SIGNATURE

THIS CHECK CONTAINS MULTIPLE SECURITY FEATURES - SEE BACK FOR DETAILS

⑈0010150193⑈ ⑆114000093⑆ 650016756⑈

FRED LOYA INSURANCE AGENCY
FOR LOYA INSURANCE COMPANY
CLAIMS ACCOUNT

DETACH AND RETAIN THIS STATEMENT
THE ATTACHED CHECK IS IN PAYMENT OF THE ITEMS DESCRIBED BELOW.
IF NOT CORRECT PLEASE NOTIFY US PROMPTLY. NO RECEIPT DESIRED.

10150193

DATE	DRAFT#	CLAIM#	POLICY#	AMOUNT
5/27/15	10150193	556 29961	66 689620133	4,948.09

INSURED: MELINDA CASILLAS

THE COUNTY OF HIDALGO TEXAS
ATTN: SAFETY DIVISION
9805 NORTH 10TH STREET
MCALLEN, TX 78504

UNIVERSAL CLAIMS SERVICES, INC.
P.O. BOX 5609
MCALLEN, TX 78502-5609
PHONE: (956) 994-1277 FAX: 994-9958

*** ESTIMATE ***

12/19/2014 12:40 PM

Owner

Owner: Hidalgo County

Control Information

Loss Date/Time: 12/10/2014
File #: 01-43859CG

Loss Type: Other
Accounting #:

Ins. Company: Universal Claims Services
Company Contact: Motalvo Ins.
Address: P. O. Box 5609
City State Zip: McAllen, TX 78502-5609
Email: UniCImSrv@aol.com

Work/Day: (956)994-1277
FAX: (956)994-9958

Insured: Hidalgo County

Claim Rep: Sylvia Anciso
Contact: Unkn

Inspection

Inspection Date: 12/18/2014
Inspection Location: Work
City State Zip: Edinburg, TX 78539
Primary Impact: Rear

Inspection Type: Independent Field
Contact:
FAX:
Secondary Impact:

Appraiser Name: Charlie Guerra
Address:
City State Zip:
Email: uniclmsrv@aol.com

Appraiser License #:
Work/Day: (956)994-1277
FAX: (956)994-9958

Vehicle

2008 Ford F-150 XL 4 DR Ext Cab Short Bed
8cyl Gasoline 4.6
4 Speed Automatic

Lic.Plate: 106-2203
Lic Expire:
Prod Date:
Veh Insp#:
Condition: Fair
Ext. Color: Gold
Ext. Refinish: Two-Stage

Lic State: TX
VIN: 1FTRX12W28FB16688
Mileage: 107,417
Mileage Type: Actual
Code: P8014C
Int. Color:
Int. Refinish:

Options

AM/FM Stereo
Dual Airbags

Air Conditioning
Halogen Headlights

Anti-Lock Brakes
Hinged Fourth Door

Intermittent Wipers	Power Brakes	Power Steering
Privacy Glass	Rear Bench Seat	Rear Step Bumper
Split Front Bench Seat	Styled Steel Wheels	Theft Deterrent System
Tilt Steering Wheel	Tinted Glass	Tire Pressure Monitor

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Body Interior Sheetmetal										
1	I	281		Pillar,Door Frame Rear RT	Repair				1.5*	SM
Cab And Components										
2	L	281		Pillar,Door Frame Rear RT	Refinish				1.7	RF
3	I	47		Panel,Cab Rear	Repair				2.0*	SM
4	L	47	13	Panel,Cab Rear	Refinish				3.5	RF
Bed										
5	E	428		Panel,Bedside RT	8L3Z9927840A	\$612.07			13.5	SM
6	L	428		Panel,Bedside RT	Refinish				3.5	RF
7	I	514		Pnl,Rear Sill Lower	Repair				4.0*	SM
8	L	514		Pnl,Rear Sill Lower	Refinish				0.6	RF
9	I	94		Floor,Rear Bed	Repair				3.0*	SM
10	L	94		Floor,Rear Bed	Refinish				4.1	RF
Tailgate										
11	EU	479		Tailgate Assembly	LIKE KIND & QUAL.PRT	\$450.00*	+25.00		0.9	SM
12	L	479		Shell,Tailgate	Refinish				3.3	RF
13	RI	186		Emblem,Tailgate	R & I Assembly				0.2	SM
14	RI	531		Handle,Tailgate Outer	R & I Assembly				INC	SM
Rear Bumper										
15	EU	565		Bumper Assy,Rear Step	LIKE KIND & QUAL.PRT	\$650.00*	+25.00		INC	SM
				>> Rey's Auto Salv. With Hitch asm						
16	L	565		Bumper,Rear Step	Refinish				1.6	RF
Rear Body, Lamps And Floor Pan										
17	EC	521		Muffler Assembly	Replace Economy	\$145.00*	+25.00		1.0	ME
				>> Jesse's Star Muffler						
18	E	534		Taillamp Assembly RT	6L3Z13404BA	\$43.04			INC	SM
Manual Entries										
19	I	M18		Set-Up And Measure	Repair				3.0*	FR
				>> Incl.Set up						
20	SB	M60		Hazardous Waste Removal	Sublet Repair	\$5.00*				SM
				20 Items						

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts	\$655.11	
Other Parts	\$1,245.00	
Paint Materials	\$549.00	
Line Item Markup	\$311.25	
Parts & Material Total		\$2,760.36
Tax on Parts & Material	@ 8.250%	\$227.73

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$40.00	14.6	10.5	25.1	\$1,004.00
Mech/Elec (ME)	\$75.00	1.0		1.0	\$75.00
Frame (FR)	\$48.00		3.0	3.0	\$144.00
Refinish (RF)	\$40.00	18.3		18.3	\$732.00
Paint Materials	\$30.00				
Labor Total				47.4 Hours	\$1,955.00
Sublet Repairs					\$5.00
Gross Total					\$4,948.09
Net Total					\$4,948.09 TOTAL LOSS

Alternate Parts No


Audatex Estimating 7.0.334 ES 12/19/2014 01:58 PM REL 7.0.334 DT 11/01/2014 DB 12/15/2014
 Copyright (C) 2013 Audatex North America, Inc.

2.5 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.
 ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.

THIS IS NOT A REPAIR AUTHORIZATION. NO SUPPLEMENT WITHOUT PRIOR APPROVAL.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = LIKE KIND & QUAL.PRT
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2013 Audatex North America, Inc.
 Audatex Estimating is a trademark of Audatex North America, Inc.