



Nationwide Insurance  
 Allied Insurance  
 Nationwide Agribusiness  
 Titan Insurance  
 Victoria Insurance

On Your Side™

Nationwide Insurance  
 PO BOX 182166  
 COLUMBUS OH 43218-2166  
 1-800-421-3535

Policy Holder: RUBEN RAMIREZ  
 Policy Number: 7238076  
 Contract Number:

Claim Key: 581169-GB  
 Check Number: 4926579  
 Check Issued: 05-01-2015 duchena

**Below Check Covers Items Indicated**

Company: TITAN INSURANCE SERVICES, INC.

Payment of \$4919.92 for Commerical Auto is being paid under the Liability coverage.

Memo: Claim 581169-GB

If you have questions about this check please contact AJ DuChene 515-508-4031

00729003429013

**Detach Stub Before Cashing And Keep For Your Record**

G-2002-2D (8/2014)

**THIS IS NATIONWIDE WATERMARKED PAPER - HOLD TO LIGHT TO VERIFY NATIONWIDE WATERMARK**

Nationwide Insurance  
 PO BOX 182166  
 COLUMBUS OH 43218-2166  
 1-800-421-3535



On Your Side™

Nationwide Insurance  
 Allied Insurance  
 Nationwide Agribusiness  
 Titan Insurance  
 Victoria Insurance

Check No: 4926579

56-1544

Date: 05-01-2015

441

Void If Not Cashed Within 180 Days

Ref: 581169-GB

4926579

PAY EXACTLY

**\*\*FOUR THOUSAND NINE HUNDRED NINETEEN AND 92/100 DOLLARS\*\***

Pay To The Order Of

Hidalgo County  
 9805 N 10th St  
 Mcallen TX 78504

\$\*4,919.92\*

JPMorgan Chase Bank, N.A.  
 Columbus, OH

Authorized Signature

⑈04926579⑈ ⑆044115443⑆ 976485235⑈

Security Features included ED Details on back

**Nationwide Enterprise**  
**5525 Parkcenter Circle**  
**ADJ CONTACT INFO ON LAST PAGE OF ESTIMATE**  
**Dublin, OH 43017**

Phone: (888)703-0770 Fax: ()-

**Carrier: Titan Insurance**

Date: 5/1/2015	File Number: 581169-GB
Claim Number: 581169-GB	Year: 2005
Policy Number: 7238076	Make: Peterbilt
Loss Date:	Model: 335 & 340
Assigned Date:	Style: Conventional
Inspected Date:	VIN: 2NPLLZ9X35M871258
Insured: RUBEN RAMIREZ - Hidalgo County	Plate/State:
Claimant: Hidalgo County	Unit #:
Address: 9805 N 10th St,	Odometer:
McAllen, TX 78504-9529	Engine:
Phone:	Transmission:
Alt Phone:	Color:
Fax:	Condition: Unknown
Claim Contact:	Inspected At:
Contact Title:	Contact Email:
Contact Phone:	Reference #: 8970021239

Operation	Description	Part #	Labor	Paint	-----Parts-----	Sublet
	----- Grille (One Piece) -----					
Replace	Grille Assembly (AM - Cost:\$378.57/Markup:25%)		Incl			\$0.00 \$473.21
	----- Hood (1 Piece) -----					
	Paint Overhaul Hood (1 Piece)		Ovhl	6.00		\$0.00
	Labor Overhaul Hood (1 Piece)		Ovhl	6.50		\$0.00
Replace	Hood (AM - Cost:\$1895.00/Markup:25% )		Ovhl			\$0.00\$2,368.75
	Add for Underside - Hood		AddPnt	2.50		\$0.00
	Aim Head Lamps		AddLbr	0.50		\$0.00
	----- Calculated Values -----					
	Shop Supplies					\$22.50
	Hazardous Waste					\$3.00
	Truck Cover		0.50		\$15.00	\$0.00
	Paint Materials					\$382.50

**Estimate Notes:**

Hood pricing provided by [http://www.32chrome.com/index.php?l=product\\_detail&p=385](http://www.32chrome.com/index.php?l=product_detail&p=385)

Grille pricing provided by <http://www.raneystruckparts.com/peterbilt-330-stainless-steel-grill-replacement/>

**Nationwide Enterprise**  
**5525 Parkcenter Circle**  
**ADJ CONTACT INFO ON LAST PAGE OF ESTIMATE**  
**Dublin, OH 43017**  
Phone: (888)703-0770

Date:	5/1/2015	File Number:	581169-GB
Claim Number:	581169-GB	Year:	2005
Adjuster:		Make:	Peterbilt
Loss Date:		Model:	335 & 340
Insured:	RUBEN RAMIREZ - Hidalgo County	Style:	Conventional
Claimant:	Hidalgo County	VIN:	2NPLLZ9X35M871258
Reference #:	8970021239	Plate/State:	

Repair Facility:  
Address:  
Phone:  
Fax:  
Agreed With:  
License 1:  
License 2:  
Fed Tax ID:

Summary	Hours	Disc	Rate	Total
Body Labor	7.50		\$80.00	\$600.00
Paint Labor	8.50		\$80.00	\$680.00
Mechanical			\$80.00	\$0.00
Frame			\$80.00	\$0.00
Miscellaneous			\$80.00	\$0.00
Parts	\$15.00			\$15.00
Sublet				\$3,249.96
<b>Tax Detail:</b>			Sub-total	\$4,544.96
City (Parts, Materials)			Sales Tax	\$374.96
County (Parts, Materials)			Total	\$4,919.92
State (Labor, Parts, Materials)			Betterment	\$0.00
\$4,544.96 @ 8.250%: \$374.96			Deductible	\$0.00
			Grand Total	\$4,919.92

Appraised By: AJ DuChene  
License #1:  
License #2:  
Phone: 515-508-2694  
Email: duchena@nationwide.com

An '\*' indicates user change of database part and '^' indicates manually entered or custom database rows.

**TERMS & CONDITIONS**

This is not an authorization to repair. This is an appraisal of damages only. Repair authorizations and guarantee of payment can only be given by owner of vehicle.

\*\*\*\*\*  
\*\*\*\*\* All shipping invoices need sent to 877-580-4127. They are payable only after upon receipt and after review.

\*\*\*\*\*  
\*\*\*\*\* Estimate prepared by: AJ DuChene Special Claim Rep. I Phone: 515-508-4031 Fax: 877-580-4127 Email: duchena@nationwide.com

\*\*\*\*\* All supplements need prior approval by adjuster and/or insurance company. There is no consideration for part prices above factory list.

\*\*\*\*\* Any person who knowingly and with intent to defraud any insurance company or other person files an application for insurance or statement of claim containing any materially false information or conceals for the purpose of misleading, information concerning any fact material thereto commits a fraudulent insurance act, which is a crime and subjects such a person to criminal and civil penalties.

\*\*\*\*\* The above is an estimate based on our inspection and does not cover any additional parts or labor which may be required after the work has started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change. \*\*\*\*\*NO SUPPLEMENT WITHOUT PRIOR

APPROVAL \*\*\*\*\* SUPPLEMENT WILL REQUIRE COPY OF ALL PARTS AND SUBLET INVOICES \*\*\*\*\* THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST