



Texas Municipal League
 Intergovernmental Risk Pool
 Joint Self Insurance Fund
 1821 Rutherford Lane
 Austin, TX 78754 (512) 491-2300

FROST BANK
 Parkdale

30-91/1140 59

Date	Number
09/11/15	5316532
LB0000000018881	
Amount	

Pay *Eight Thousand Five Hundred And Forty Four And 90/100 US
 Dollars * * * * * \$8,544.90*

To Hidalgo County Precient 1
 1902 Joe Stephens
 Weslaco, TX 78596

Carol A. Doyle
Ann S. Almonaco
 Void After 90 Days

SIGNATURE HAS A COLORED BACKGROUND • BORDER CONTAINS MICROPRINTING

⑈05316532⑈ ⑆114923222⑆ 29 9990348⑈

CLAIM NUMBER	PAYMENT FOR	FOR THE PERIOD	AMOUNT	ADJUSTER LINE CATEGORY
LB0000000018881	Hidalgo County Precient 1		\$8,544.90	SCurby Vehicle

**INSURANCE CLAIM AND APPRAISAL
SERVICE**

Workfile ID:

4df4df83

26669 IH 10 WEST #4
BOERNE, TX 78006
Phone: (210) 698-8708, FAX:(210) 698-8719

**TML INTERGOVERNMENTAL RISK
POOL**

TMLIRP
Phone: (512) 491-2436, FAX:(512) 491-2366

Preliminary Estimate

Customer: Precient #1, Hidalgo County

Job Number:

Insured: Precient #1, Hidalgo County Policy #: LB18881 Claim #: LB18881
Type of Loss: Collision Date of Loss: 6/15/2015 12:00 AM Days to Repair: 4
Point of Impact: 14 Unknown

Owner:

Precient #1, Hidalgo County
1902 Joe Stephens
Weslaco, TX 78596
(956) 292-7030 Day

Inspection Location:

Precient #1, Hidalgo County
1902 Joe Stephens
Weslaco, TX 78596
Work
(956) 292-7030 Day

Repair Facility:

OWNERS CHOICE

VEHICLE

Year: 2014 Color: White Int: Gray License: 1166280 Production Date: 12/2013
Make: OTHE Body Style: 2D State: TX Odometer:
Model: Cati Dump Truck Engine: VIN: 3HTJGTKR5EN034126 Condition: Good

TRANSMISSION

Automatic Transmission

DECOR

Dual Mirrors
Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

SEATS

Bucket Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

Preliminary Estimate

Customer: Precient #1, Hidalgo County

Job Number:

Vehicle: 2014 OTHE Cati Dump Truck 2D White

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	Rpr Roof Note: ROOF IS CREASED ABOUT 3/4 OF THE ROOF.				14.0	1.8
2	*	Add for Clear Coat					0.4
3	#	Repl Headliner Note: INCLUDES R&I SUNVISORS AND UPPER STORAGE.		1	337.12	4.0	
4	#	Repl Tailpipe extension		1	270.18	1.0	
5	#	Material for dump bed		1	650.00		
6	#	Subl Labor to cut out and install the front bed end		1	4,700.00 X		
7	#	Paint bed Note: FRONT CAP OF BED, FRONT BED PANEL AND SIDES WHERE WELDING IS AT.		1	1,600.00		
8	#	Shop supplies		1	35.00		
9	#	**** ADD ONS ****		1			
10	#	Subl Hazardous Material		1	3.00 X		
11	#	Repl Cover Car		1	8.00 X	0.3	
12	#	Repl Corrosion Protection		1	8.00 T	0.3	
SUBTOTALS					7,611.30	19.6	2.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,892.30
Body Labor	19.6 hrs @	\$ 40.00 /hr	784.00
Paint Labor	2.2 hrs @	\$ 40.00 /hr	88.00
Paint Supplies	2.2 hrs @	\$ 28.00 /hr	61.60
Miscellaneous			4,719.00
Subtotal			8,544.90
Total Cost of Repairs			8,544.90
Deductible			0.00
Total Adjustments			0.00
Net Cost of Repairs			8,544.90