



AMERICAN ACCESS CASUALTY COMPANY
2211 Butterfield Road, Suite 200
Downers Grove, IL 60515
Claims Account

The Private Bank
Chicago, IL 60602
2-648/710

CHECK NUMBER
0000465643

12/08/16

VOID AFTER 180 DAYS

PAY THREE THOUSAND TWO HUNDRED FIFTY TWO DOLLARS & 99/100

\$3,252.99

To The Order Of COUNTY OF HIDALGO
9805 North 10th St
McAllen, TX 78504

Memo CLM 1611050990 DL 11/03/2016 pg

AUTHORIZED SIGNATURE

SECURE FEATURES INCLUDE INVISIBLE FIBERS • MICROPRINTING • VOID PANTOGRAPH • ENDORSEMENT BACKER • CHEMICAL REACTANT

⑈0000465643⑈ ⑆071006486⑆ 2185034⑈

AMERICAN ACCESS CASUALTY COMPANY

COUNTY OF HIDALGO
9805 North 10th St
McAllen, TX 78504

CHECK NUMBER 0000465643
CHECK DATE 12/08/16

Invoice Date	Invoice No.	Description	Invoice Amt.
12/08/16	683310	CLM 1611050990 DL 11/03/2016 pg attn: Lauro Torres pd pmt 2012 chevy express	3,252.99

AMERICAN ACCESS CASUALTY COMPANY

COUNTY OF HIDALGO
9805 North 10th St
McAllen, TX 78504

CHECK NUMBER 0000465643
CHECK DATE 12/08/16

Invoice Date	Invoice No.	Description	Invoice Amt.
12/08/16	683310	CLM 1611050990 DL 11/03/2016 pg attn: Lauro Torres pd pmt 2012 chevy express	3,252.99

Nationwide Appraisals, LLC
2521 Technology Drive, Ste. 213 Elgin, IL 60124
PHONE: (888) 863-0001 FAX: (847) 594-0244

***ALL SUPPLEMENTS MUST BE FAXED TO (847) 594-0244 OR EMAILED TO Claims@NationwideAppraisals.net ***
ALL APPRAISALS ARE SUBJECT TO THE REVIEW AND THE APPROVAL OF THE ASSIGNING INSURANCE COMPANY

*** ESTIMATE ***

12/05/2016 08:04 PM

Owner

Owner: Rodolfo Garcia

Control Information

Claim #: 1611050990-01
Loss Date/Time: 11/03/2016
Deductible: \$500.00
Company Contact: American Access Casualty Co.

Insured Policy # :
Loss Type: Other

Insured: Rodolfo Garcia
Address: 1901 W State Hwy.107

Work/Day: (956)383-0706
Home/Evening: (956)581-1980
FAX:

City State Zip: McAllen, TX 78504

Claim Rep: Vista Claims
Contact: Unkn

Inspection

Inspection Date: 12/05/2016
Inspection Location: Work
City State Zip: Palmview, TX 78572
Primary Impact: Right Side

Inspection Type: Independent Field
Contact:
FAX:
Secondary Impact:

Company: Guerra's Appraisal Service
Contact: Charlie Guerra
Address: 303 W Los Ebanos St
City State Zip: San Juan, TX 78589
Email: crmmguerra@yahoo.com

Appraiser License # :
Work/Day: (956)588-6255
FAX:

Repairer

Target Complete Date/Time:

Days To Repair: 12

Vehicle

OEM Part Price Quote ID: 14288850

2012 Chevrolet G25 Express STD 2 DR Cargo Van Extended
8cyl Gas 4.8 Liter Flex
6-Speed Automatic

Lic.Plates: 113-2161
Lic Expire:
Prod Date:
Veh Insp# :
Condition: Fair

Lic State: TX
VIN: 1GCEGGCA9C1149427
Mileage: 61,482
Mileage Type: Actual
Code: U6175A

Ext. Color: White
 Ext. Refinish: Two-Stage

Int. Color:
 Int. Refinish:

Options

Air Conditioning	Anti-Lock Brakes	Auto Headlamp Control
Bucket Seats	Daytime Running Lights	Dual Airbags
Engine Cover Console	Full Size Spare Tire	Halogen Headlights
Intermittent Wipers	Power Brakes	Power Steering
Rear Step Bumper	Stability Cntrl Suspensn	Steel Wheels
Tachometer	Theft Deterrent System	Tinted Glass
Tire Pressure Monitor	Traction Control System	Trip Computer
Vinyl Seats		

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Doors										
1	I	210		Pnl,Front Door Outer RT >> Buff	Repair				0.3*	SM
Side Doors										
2	EP	449		Door Shell,Rear RT	Replace PXN	\$414.96			2.4	SM
3	L	449		Door Shell,Rear RT	Refinish				3.0	RF
4	BR	360	13	Pnl,Rear Door Outer RT	Blend Refinish				1.8	RF
5	E	230		Hinge,Body Side Lower RT	15993424 GM Part	\$21.75			0.2	SM
6	L	230		Hinge,Body Side Lower RT	Refinish				0.2	RF
Body Side Assembly										
7	EU	294		Frame,Door Opening RT >> Rey's Auto Salv.	Replace Recycled	\$650.00*	+25.00		0.0*	SM
8	ET	628		Panel,Rocker RT	Partial Replace Labor				10.2	SM
9	L	628		Panel,Rocker RT	Refinish				1.6	RF
10	I	390		Panel,Bodyside Outer RT	Repair				12.5*	SM
11	L	390		Panel,Bodyside Outer RT	Refinish				5.4	RF
Manual Entries										
12	SB	M60		Hazardous Waste Removal	Sublet Repair	\$3.00*			0.0*	SM
13	SB			Seam Sealer	Sublet Repair	\$10.00*			0.3*	SM*
14	SB			Corrosion Protection	Sublet Repair	\$8.00*			0.0*	SM*
14	Items									

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts	\$21.75
Other Parts	\$1,064.96
Paint & Materials	12.0 Hours @ \$28.00
Line Item Markup	\$336.00
Parts & Material Total	\$162.50
Tax on Parts & Material	\$1,585.21
	@ 8.250%
	\$130.78

Labor	Rate	Replace	Repair Hrs	Total Hrs
			Hrs	

Sheet Metal (SM)	\$40.00	12.8	13.1	25.9	\$1,036.00
Mech/Elec (ME)	\$65.00				
Frame (FR)	\$50.00				
Refinish (RF)	\$40.00	12.0		12.0	\$480.00

Labor Total				37.9 Hours	\$1,516.00
Sublet Repairs					\$21.00
Gross Total					\$3,252.99
Less: Deductible					\$500.00-
Net Total					\$2,752.99

Alternate Parts Y/01/01/00/00/00 CUM 01/01/00/00/00 Zip Code: 78589 Geo 78589
 OEM Part Prices DT 12/05/2016 08:05 PM EstimateID 235221224370741248 QuotID 14288850
 SPPL Yes Zip Code: 78501 Default
 Rate Name Default

Audatex Estimating 8.0.035 ES 12/05/2016 08:20 PM REL 8.0.035 DT 11/01/2016 DB 12/01/2016
 © 2016 Audatex North America, Inc.

2.4 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

*** THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL REPAIR COSTS ARE THE RESPONSIBILITY OF THE VEHICLE OWNER, WHO ULTIMATELY MUST AUTHORIZE ALL REPAIRS. NO ESTIMATES OR SUPPLEMENTS WILL BE HONORED WITHOUT PRIOR INSPECTION AND AUTHORIZATION.***

*** COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS NOT AN ACCEPTANCE OF COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE DETERMINED BY THE INSURANCE COMPANY. ***

Op Codes

- | | | |
|----------------------------|---|--------------------------------|
| * = User-Entered Value | ^ = Labor Matches System Assigned Rates | E = Replace OEM |
| NG = Replace NAGS | EC = Replace Economy | OE = Replace PXN OE Srpls |
| UE = Replace OE Surplus | ET = Partial Replace Labor | EP = Replace PXN |
| EU = Replace Recycled | TE = Partial Replace Price | PM = Replace PXN Reman/Reblt |
| UM = Replace Reman/Rebuilt | L = Refinish | PC = Replace PXN Reconditioned |
| UC = Replace Reconditioned | TT = Two-Tone | SB = Sublet Repair |
| N = Additional Labor | BR = Blend Refinish | I = Repair |
| IT = Partial Repair | CG = Chipguard | RI = R & I Assembly |
| P = Check | AA = Appearance Allowance | RP = Related Prior Damage |