



HILGADO COUNTY
300 W HALL ACRES RD
PHARR TX 78577-5485

01/18/2017

HILGADO COUNTY,

ENCLOSED PLEASE FIND PAYMENT IN THE AMOUNT OF \$1,929.98 FOR YOUR LOSS ON 10/5/2016.

PLEASE REFERENCE CLAIM DETAILS BELOW.

CLAIM NUMBER: 0431435353

DATE OF LOSS: 10/05/2016

INSURED: MARIA PENA

In payment for COMB SINGLE LMYS PD for Date of Loss 10/5/2016.

ALLSTATE COUNTY MUTUAL INSURANCE COMPANY
1-800-255-7828

000020170118000123ZCT03001001000130



INSURED: MARIA PENA
CLAIMANT: HILGADO COUNTY
IN PAYMENT OF: LOSS ON: 10/5/2016

POLICY NUMBER		CLAIM NUMBER	
648587234		0431435353	
TAX ID	DESK LOC	EMPLOYEE ID	
	ARL	N5HS	
Bank of America NA Atlanta, Dekalb Cty, Georgia		Bank of America Customer Connection	

64-1278
611

PAY: ONE THOUSAND NINE HUNDRED TWENTY-NINE DOLLARS AND NINETY-EIGHT CENTS

1,929.98

INVOICE NUMBER	MCO	DATE ISSUED
	5830	01/18/2017

151658724




TO THE ORDER OF HILGADO COUNTY
300 W HALL ACRES RD
PHARR TX 78577-5485

COMPANY: ALLSTATE COUNTY MUTUAL INSURANCE COMPANY

Amren K. Gupta
Samuel D. Rich

AUTHORIZED SIGNATURES



VOID IF NOT PRESENTED WITHIN THREE HUNDRED, SIXTY-FIVE DAYS OF DATE OF ISSUE

⑈ 15 16 58 7 24 ⑈ ⑆ 06 1 1 1 2 7 8 8 ⑆ 3 2 9 9 1 1 9 5 6 2 ⑈

VIC'S AUTO REBUILDERS
610 EAST EXP. 83
PHARR, TEXAS 78577
956-787-5084 FAX: 956-787-5331

Unit 229

*** PRELIMINARY ESTIMATE ***

10/06/2016 10:21 AM

Owner

Owner: HCCO pct 2
Address: 300 W HALL ACRES RD STE E
City State Zip: PHARR, TX

Work/Day: (956)784-3510
FAX:

Inspection

Inspection Date: 10/06/2016 10:21 AM
Primary Impact: Right Rear Side

Inspection Type:
Secondary Impact:

Appraiser Name: FREDDY SUSTAITA
Address: 610 E EXP 83
City State Zip: Pharr, TX 78577
Email: freddy@vicsautorebuilders.com

Appraiser License # :
Work/Day: (956)787-5084
FAX: (956)787-5331

Repairer

Repairer: VIC'S AUTO REBUILDERS
Address: 610 E EXPRESSWAY 83

City State Zip: PHARR, TX 78577

Contact: VICTOR CARRILLO
Work/Day: (956)787-5084
Home/Evening: (956)787-6239
FAX: (956)787-5331

Target Complete Date/Time:

Days To Repair: 8

Vehicle

OEM Part Price Quote ID: ****

2016 Chevrolet Tahoe Police 4 DR Wagon
8cyl Gasoline 5.3 FLEX
6-Speed Automatic

Lic.Plate: 1190298
Lic Expire:
Veh Insp# :
Condition:
Ext. Color: BLACK
Ext. Refinish: Two-Stage

Lic State: TX
VIN: 1GNLCDEC9GR141712
Mileage Type: Actual
Code: U7434D
Int. Color:
Int. Refinish: Two-Stage

Options

2nd Row Head Airbags
Alarm System
Auxiliary Audio Input
Cargo Organizer
Daytime Running Lights
Dual Zone Auto A/C
Halogen Headlights
Heavy Duty Battery
In-Vehicle WiFi

AM/FM CD Player
Anti-Lock Brakes
Camper/Towing Package
Cargo/Trunk Net
Driver Information Sys
Extra HD Alternator
Head Airbags
Heavy Duty Cooling
Intermittent Wipers

Air Conditioning
Auto Headlamp Control
Cargo Lamp
Cruise Control
Dual Airbags
Full Size Spare Tire
Heated Power Mirrors
Hi-Flow Air Cleaner
Keyless Entry System

Lighted Entry System	Locking Differential	MP3 Decoder
OnStar System	Power Brakes	Power Door Locks
Power Drivers Seat	Power Steering	Power Windows
Privacy Glass	Pwr Accessory Outlet(s)	Rain-Sensing W/S Wipers
Rear View Camera	Rear Window Defroster	Rear Window Wiper/Washer
Reverse Sensing System	Side Airbags	Skid Plates
Split Folding Rear Seat	Split Front Bench Seat	Stability Cntrl Suspensn
Steel Wheels	Strg Wheel Radio Control	Theft Deterrent System
Tilt Steering Wheel	Tinted Glass	Tire Pressure Monitor
Traction Control System	Trailer Hitch	USB Audio Input(s)
Velour/Cloth Seats	Wireless Audio Streaming	Wireless Phone Connect

Damages

Line Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Wheels								
1	E	956	Wheel,Rear RT	20942021 GM Part	\$245.00		0.3	SM
Quarter And Rocker Panel								
2	I	390	Panel,Quarter RT	Repair			8.0*	SM
3	L	390	13 Panel,Quarter RT	Refinish			4.0	RF
				2.8 Surface				
				0.6 Two-stage setup				
				0.6 Two-stage				
Rear Bumper								
4	N	584	Rear Bumper Cover R&I	Additional Labor			INC	SM
5	I	584	Cover,Rear Bumper	Repair			4.0*	SM
6	L	584	Cover,Rear Bumper	Refinish			3.1	RF
				2.6 Surface				
				0.5 Two-stage				
7	E	573	Brkt,Rear Bumper Mtg RT	22806426 GM Part	\$15.78		1.6	SM
Manual Entries								
8	EC		COVER CAR INTERIOR	Replace Economy	\$5.00*			RF
9	L		HAZARD. WSTE. REM.	Refinish	\$5.00*			SM
10	I		SET-UP FOR REALIGN.	Repair			1.5*	FR
11	I		CORROSION PROTECTION	Sublet Repair	\$16.00*			RF
12	SB		WHEEL BALANCE	Sublet Repair	\$10.00*			SM
13	L		FLEX ADDITIVE	Refinish	\$5.00*			RF
14	I		BODY PULLS	Repair			2.0*	SM*
15	EC		Eagle RS-A RR	Replace Economy	\$246.20			SM
			>> GOODYEAR 265/60R17 732301500 VSB 260 11 108V					
			>> Tire Rack					
			>> South Bend IN (800) 445-0179					
16	I		CK REAR SUSP FOR DAMAGE	Repair			1.0*	ME*
16 Items								

MC	Message
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts	\$260.78
Other Parts	\$261.20
Paint & Materials	7.1 Hours @ \$30.00
Parts & Material Total	\$213.00
	\$734.98

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$44.00	1.9	14.0	15.9	\$699.60
Mech/Elec (ME)	\$85.00		1.0	1.0	\$85.00
Frame (FR)	\$48.00		1.5	1.5	\$72.00
Refinish (RF)	\$44.00	7.1		7.1	\$312.40
Labor Total				25.5 Hours	\$1,169.00
Sublet Repairs					\$26.00
Gross Total					\$1,929.98
Net Total					\$1,929.98


Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 78577 Default
 OEM Part Prices DT 10/06/2016 10:21 AM EstimateID 213315499327504384 QuoteID ****
 Recycled Parts No
 Rate Name Default

Audatex Estimating 8.0.035 ES 10/06/2016 10:29 AM REL 8.0.035 DT 09/01/2016 DB 10/01/2016,
 © 2016 Audatex North America, Inc.

1.7 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2016 Audatex North America, Inc.
 AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

