

HIDALGO COUNTY FIRE MARSHAL'S OFFICE
FIRE INSPECTION REPORT

8476
Receipt No.

(956) 318-2656 1124 North "M" Road, Edinburg, Texas 78542

DATE: 7/23/15 ADDRESS: 21611 Hwy 186 Edinburg, TX

OCCUPANT: Linn FD / Icon Construction TYPE OF OCCUPANCY: Fire Dept

TYPE OF INSPECTION: ANNUAL OCCUPANCY INSP. RE-INSPECTION

THE FOLLOWING HAZARDS WERE FOUND:

- 1. Accumulation of empty boxes, trash, rubbish paper, etc. IN OUT side of building.
- 2. No approved trash cans.
- 3. Absolutely no combustible storage under wooden stairs.
- 4. Merchandise crowded: obstructing aisles.
- 5. Maintain egress to exits.
- 6. Exit doors locked.
- 7. Exits shall be unlocked during business hours.
- 8. Vents unsafely arranged on water heater and/or dryers.
- 9. Accumulation of lint behind dryers.
- 10. Dust covered motors.
- 11. Chemically treated dust mops/oily rags shall be stored in metal containers with a lid.
- 12. Do not use gasoline as a cleaning agent.
- 13. Address not posted.
- 14. Defective wiring.
- 15. Lighting devices improperly installed.
- 16. Lighting devices too close to stock.
- 17. Junction boxes, light switches, and electrical outlets shall have safety covers.
- 18. Fuses bridged.
- 19. Repair exit and/or emergency lights.
- 20. Install exit and/or emergency lights.
- 21. All permanent wiring and equipment shall be wired to conduit.
- 22. All wiring shall be done by a licensed electrician.
- 23. Clean out accumulation of grease on cooking stove, filter, ducts, and hood.
- 24. Hood over stove and deep fat fryers must meet N.F.P.A. Number 96.
- 25. Install automatic fire extinguishing system in accordance with N.F.P.A. Number 96.
- 26. Have fire extinguishers recharged.
- 27. Have fire extinguishers checked by a licensed inspector on an annual basis.
- 28. Fire extinguisher blocked.
- 29. No fire extinguisher in building. Require some be installed.
- 30. Anchor pressurized cylinders.
- 31. Have sprinkler system checked by a licensed inspector on an annual basis.
- 32. Sprinkler riser area shall be kept clean at all times.
- 33. Maintain 18" clearance from sprinkler heads.
- 34. Do not block Fire Department connections.
- 35. Caps missing from Fire Department connections.
- 36. Water gong not working; needs to be repaired.
- 37. Repair or replace hose and/or nozzle at dispensing pumps.
- 38. Remove latching devices on dispensing nozzles at self-service retail stations.
- 39. The use of L.P.G. is not permissible, when natural gas is available.
- 40. Maintain good housekeeping throughout the building.
- 41. Smoke alarms are required in any overnight accommodation H.B. 2046.
- 42. Smoke detectors not working.
- 43. Re-inspection date, _____

REMARKS: Everything in order at time of inspection

Such conditions are violations of either County and/or State Fire Prevention regulation. Please correct hazard and help prevent fires. **PROTECT LIFE AND PROPERTY.**
(If not corrected within 10 days, Legal Action will be taken.)

Copy delivered to Dominico Desissa
Print
[Signature]
Signature

[Signature]
Fire Marshal