

PROGRESSIVE  
PO BOX 512926  
LOS ANGELES, CA 90051

**PROGRESSIVE®**

Pct. 1

HILDALGO COUNTY  
1902 JOE STEPHENS AVE STE 101  
WESLACO, TX 78599-3704

HILDALGO COUNTY PCT 1  
MAR 19 '18 PM 2:51

*q.c.*

DRAFT NUMBER: 2020334426

AMOUNT:

\$\*\*\*\*\*686.59

ISSUE DATE: March 13, 2018

Form 7721 (06/15)

KEEP THIS TOP PORTION FOR YOUR RECORDS

**PROGRESSIVE®**

PAYABLE THROUGH  
PNC BANK, N.A. 070  
ASHLAND, OH  
1-877-448-9544

VOID IF NOT PRESENTED WITHIN 90 DAYS

CLAIM NUMBER: 18-4105902  
NAME: HILDALGO COUNTY

DRAFT NUMBER: 56-389  
2020334426  
March 13, 2018  
412

PAY EXACTLY \$\*\*\*\*\*686.59

SIX HUNDRED EIGHTY-SIX AND 59/100 \*\*\*\*\*

PAY TO THE ORDER OF: HILDALGO COUNTY

Progressive County Mutual Insurance Company

BY:   
AUTHORIZED SIGNATURE

⑈ 20 20334426⑈ ⑆04⑆ 203895⑆ 4239694516⑈

Date: 3/ 8/2018 11:54 AM  
 Estimate ID: 18-4105902-02  
 Estimate Version: 0  
 Committed  
 Profile ID: \* Texas - PCA

## Progressive County Mutual Ins Co

Damage Assessed By: Quintin Wadley

Claim Rep: Grecla Perez  
 (908) 941-3828

Classification:

Product Type: Tractor  
 Date of Loss: 1/31/2018  
 Contact Date: 3/ 8/2018  
 Deductible: NONE  
 Claim Number: 18-4105902-02

Claimant: HILDALGO COUNTY  
 Address: 1902 JOE STEPHENS AVE STE 101, WESLACO, TX 78596  
 Telephone: Work Phone: (956) 292-7000 ext. 5464  
 Owner: HILDALGO COUNTY  
 Address: 1902 JOE STEPHENS AVE STE 101, WESLACO, TX 78596  
 Telephone: Work Phone: (956) 292-7000 ext. 5464

Contact Phone: (956) 292-7000

Mitchell Service: 910003

Description: 17 Cat CT 660  
 VIN: 3HTJGTKT1HN466664  
 Mileage: 37,552  
 OEM/ALT: A

License: 1331009 TX

Search Code: PCATX

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	REMOVE/REPLACE	C -Channel 4x1.72 x 12 feet	** Non-OEM	114.72	* INC*
2				Steel Chanel Priced Online at WWW.Metals Depot.com			
3				Line Markup %25.00		28.68	
4	900500	BDY *	REPAIR	Cut out damaged vertical supports and weld in new material Aprox 48 Total Inches	Existing		2.0*
5							
6	900500	REF *	REFINISH/REPAIR	Refinihs Aprox 9 Feet Of Channel or Tubbing	Existing		3.6*
7	936004		ADD'L COST	Shipping		31.64	*
8	900500	BDY *	REMOVE/REPLACE	Dot Tape 3@2.00	** Non-OEM	6.00	* 0.2*
9				Line Markup %25.00		1.50	
10	936007		ADD'L COST	Shop Materials		7.65	*
11	936012		ADD'L COST	Hazardous Waste Disposal		10.00	*
12	AUTO		ADD'L COST	Paint/Materials		36.00	*

\* - Judgment Item

"All manufacturers requirements regarding seat belt and supplemental restraint system replacement must be adhered to. If additional parts or operations are necessary to properly accomplish this, please contact the estimating claims rep"

ESTIMATE RECALL NUMBER: 03/08/2018 11:54:20 18-4105902-02

Mitchell Data Version: OEM: JAN\_18\_V

MAPP:JAN\_18\_V

Copyright (C) 1994 - 2018 Mitchell International

Page 1 of 4

Software Version: 7.1.226

All Rights Reserved

Date: 3/ 8/2018 11:54 AM  
 Estimate ID: 18-4105902-02  
 Estimate Version: 0  
 Committed  
 Profile ID: \* Texas - PCA

## Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	2.2	75.00	0.00	0.00	165.00	Taxable Parts	120.72
Refinish	3.6	75.00	0.00	0.00	270.00	Parts Adjustments	30.18
						Sales Tax @ 8.240%	12.43
					435.00	Total Replacement Parts Amount	163.33
Labor Summary	5.8				435.00		
						IV. Adjustments	Amount
III. Additional Costs					Amount	Insurance Deductible	0.00
Taxable Costs					36.00	Customer Responsibility	0.00
Sales Tax @ 8.240%					2.97		
Non-Taxable Costs					49.29		
Total Additional Costs					88.26		
Paint Material Method: Rates Init Rate = 10.00							
						I. Total Labor:	435.00
						II. Total Replacement Parts:	163.33
						III. Total Additional Costs:	88.26
						Gross Total:	686.59
						IV. Total Adjustments:	0.00
						Net Total:	686.59

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Alt. Location: PROGRESSIVE

Inspection Site: Not Available  
 Address: Mile 1 1/2 West  
 highway 11  
 Mercedes, TX 78570  
 (956) 292-7000 ext. 5464