

EMPOWER INSURANCE
OBO ALINSCO INSURANCE COMPANY

JP MORGAN CHASE BANK
FORT WORTH TX 76102

8105116

PO BOX 137089
FORT WORTH, TX 76136

DATE: 04/05/2018

PAY TO THE ORDER OF: **THE COUNTY OF HIDALGO**

PAY: **TWO THOUSAND ONE HUNDRED SEVENTY-SEVEN AND 82/100 DOLLARS**

\$2,177.82

MEMO: PD FULL & FINAL PAYMENT
FINAL CL:270557
3G1BF5SM3HS563304



⑈8105116⑈ ⑆111000614⑆ ⑈560887833⑈

EMPOWER INSURANCE
OBO ALINSCO INSURANCE COMPANY
PO BOX 137089
FORT WORTH, TX 76136

Claimant: Noe Aguilera
Pol: EAA1396618 Adj: D.Austin Req: daustin
Claim: 270557 Cov: PDM

THE COUNTY OF HIDALGO
9805 N 10TH ST.
MCALLEN , TX 78504

EMPOWER INSURANCE GROUP

Empower Insurance Group
All Supplements must be approved prior to repairs.

supplementhotline@empowerins.com

PO Box 137089

Fort Worth, TX 76136

Phone: (817) 586-8973

Fax: (817) 245-4185

Claim #:

270557-02

Workfile ID:

6cc2a7cc

Estimate of Record

Written By: RUBEN AGUINAGA, 4/2/2018 2:58:33 PM
Adjuster: AUSTIN, DOMINIQUE, (817) 306-2300 Business

Insured: Jesus Torres-Rosales Owner Policy #: Claim #: 270557-02
Type of Loss: Liability Date of Loss: 03/22/2018 10:15 AM Days to Repair: 0
Point of Impact: 06 Rear Deductible:

Owner (Claimant):	Inspection Location:	Appraiser Information:	Repair Facility:
Noe Aguilera 10606 N express way 281 Edinburg, TX 78542 (956) 414-0627 Cellular	unk unk 101 S 10th Ave Edinburg, TX 78539 Field (956) 318-2570 Day	(817) 586-8973	

VEHICLE

2017 CHEV Cruze Premier w/1SF Equip Pkg 4D SED 4-1.4L Turbocharged Gasoline Direct Injection White

VIN: 3G1BF5SM3HS563304	Production Date: 11/2016	Interior Color: gray
License: 127-4989	Odometer: 5038	Exterior Color: White
State: TX	Condition: Fair	

TRANSMISSION	Intermittent Wipers	Search/Seek	Reclining/Lounge Seats
Automatic Transmission	Tilt Wheel	Auxiliary Audio Connection	Leather Seats
POWER	Cruise Control	Satellite Radio	Heated Seats
Power Steering	Rear Defogger	SAFETY	WHEELS
Power Brakes	Keyless Entry	Drivers Side Air Bag	Aluminum/Alloy Wheels
Power Windows	Alarm	Passenger Air Bag	PAINT
Power Locks	Message Center	Anti-Lock Brakes (4)	Clear Coat Paint
Power Mirrors	Steering Wheel Touch Controls	4 Wheel Disc Brakes	OTHER
Heated Mirrors	Telescopic Wheel	Front Side Impact Air Bags	Traction Control
Power Driver Seat	Remote Starter	Head/Curtain Air Bags	Stability Control
DECOR	Backup Camera w/Parking Sensors	Communications System	Signal Integrated Mirrors
Dual Mirrors	RADIO	Hands Free Device	Xenon Headlamps
Console/Storage	AM Radio	Rear Side Impact Air Bags	Power Trunk/Gate Release
CONVENIENCE	FM Radio	SEATS	

Estimate of Record

2017 CHEV Cruze Premier w/1SF Equip Pkg 4D SED 4-1.4L Turbocharged Gasoline Direct Injection White

Air Conditioning

Stereo

Bucket Seats

Estimate of Record

2017 CHEV Cruze Premier w/1SF Equip Pkg 4D SED 4-1.4L Turbocharged Gasoline Direct Injection White

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		REAR BODY & FLOOR					
2	*	Rpr Rear body panel	84035767			4.0	1.3
		NOTE: Partial paint, full clear.					
3	*	Add for Clear Coat					0.6
4		R&I Rear sill plate	84243012			0.3	
5		R&I RT Trunk side trim black	84175596			0.3	
6		R&I LT Trunk side trim black	84175598			0.3	
7		TRUNK LID					
8	*	Rpr Trunk lid w/o spoiler	84080949			4.5	2.0
		NOTE: allow time to repair outer panel an shelf.					
9		Overlap Major Adj. Panel					-0.4
10	*	Add for Clear Coat					0.4
11	*	Add for Underside(Complete)					0.4
12		R&I Body w'strip	84151531			0.4	
13	*	Align Trunk lid w/o spoiler	84080949			0.5	
14	*	R&I Emblem	23401134			0.2	
15	**	Repl Alt OEM Nameplate "CRUZE" w/o code CG6	23368275	1	38.40	0.2	
16	*	R&I Nameplate "PREMIER"	23419657			0.2	
17		R&I Trunk lid trim	84114303			0.3	
18		REAR LAMPS					
19		R&I RT Tail lamp assy	84078119			0.3	
20		R&I LT Tail lamp assy	84078120			0.3	
21		R&I RT Backup lamp assy	84075815			0.2	
22		R&I LT Backup lamp assy	84075816			0.2	
23		REAR BUMPER					
24		O/H rear bumper				1.9	
25	** <>	Repl Alt OEM Bumper cover w/o obstacle detection	19354103	1	418.21	Incl.	3.0
26		Overlap Major Non-Adj. Panel					-0.2
27		Add for Clear Coat					0.6
28	**	Repl A/M Impact bar	GM1106707DSC	1	216.00	0.4	
29	**	Repl Alt OEM Center support	84077172	1	38.28	0.3	
30	**	Repl Alt OEM Absorber	23354374	1	148.40	Incl.	
31	#	Rpr tie down an rough pull				2.0	
32	#	Subl Hazardous Waste		1	3.00 X		
33	#	Repl Flex Additive		1	7.00 T		
34	#	Subl Cover Car		1	7.00 X		
SUBTOTALS					876.29	16.8	7.7

NOTES

Estimate of Record

2017 CHEV Cruze Premier w/1SF Equip Pkg 4D SED 4-1.4L Turbocharged Gasoline Direct Injection White

Prior Damage Notes:
unk

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			859.29
Body Labor	16.8 hrs @	\$ 40.00 /hr	672.00
Paint Labor	7.7 hrs @	\$ 40.00 /hr	308.00
Paint Supplies	7.7 hrs @	\$ 30.00 /hr	231.00
Miscellaneous			17.00
Subtotal			2,087.29
Sales Tax	\$ 1,097.29 @	8.2500 %	90.53
Total Cost of Repairs			2,177.82
Total Adjustments			0.00
Net Cost of Repairs			2,177.82

MyPriceLink Estimate ID: 410160171659042816

DISCLAIMER: In accordance with Sec. 1952.301-304 of the Texas Insurance Code, please be advised that an insurer may not, directly or indirectly specify the brand, age, vendor, supplier or condition of parts or products that may be used to repair the vehicle. The insurer may not limit the policy beneficiary or third party claimant from selecting a repair person or facility to repair damages to the motor vehicle. This does not make the insurance company responsible for the extra cost should you choose a different repair method or shop that charges in excess of the going market rate for repairs.

The fact that this estimate has been prepared does not, in anyway, expressly or implied confirm the existence of any insurance coverage or acceptance of any claim for which this estimate has been prepared. If repairs are completed in accordance with this estimate, the repairer must adhere to all manufacturer specifications for completing repairs.

If additional damages related to this accident are found, please call the adjuster or appraiser at the number listed at the top of this estimate. Please be aware that we will not pay for any additional damage that we have not inspected and/or approved prior to repair.

"THIS IS NOT AN AUTHORIZATION FOR REPAIR." - The appraiser or adjuster does not have the authority to authorize repairs. Authorization to repair can only be made by the owner of the vehicle."

This estimate has been prepared based on the use of replacement parts supplied by a source other than the manufacturer of your motor vehicle. Warranties applicable to these replacement parts are provided by the manufacturer or distributor of these parts rather than the manufacturer of your vehicle. These warranties generally meet or exceed those provided by your vehicle manufacturer.