

Detailed Payment Summary

NO. N621604473

GEICO COUNTY MUTUAL INSURANCE COMPANY
PO BOX 509105
SAN DIEGO CA, 92150

Claim #
0627562900101017-02

Date of Loss
11/2/2018

Date
1/2/2019

Field Claim Center
REGION V DALLAS

Adjuster Code
CCFE

Payment Type
LOSS

Tax ID/SS//Atty ADJ Code

Claimant Name
HIDALGO COUNTY ANIMAL CONTROL

Total Amount
\$2,899.09

Insured Name
LARRY MICHAEL GRAY

Pay To
HIDALGO COUNTY

Feature and Amount
APD \$2,899.09

In Payment Of
PROPERTY DAMAGE COVERAGE

Visit geico.com

Now, parties involved in a GEICO claim can track the progress of the claim, view damage photos and more at geico.com! *GEICO policyholders can make a payment, change drivers or vehicles and request additional coverages. *Not insured with GEICO? 15 minutes could save you 15% or more on car insurance. Of course, we're also available for policy or claim service 24/7 at 1-800-841-3000.

* These online services are unavailable to Assigned Risk Policyholders.

C-624-BK

PLEASE DETACH AND KEEP FOR YOUR RECORDS

GEICO COUNTY MUTUAL INSURANCE COMPANY
PO BOX 509105
SAN DIEGO CA, 92150

Bank of America
HARTFORD, CT 06210

51-44
119 CT

NO. N621604473

Claimant Name:
HIDALGO COUNTY ANIMAL CONTROL

Claim Number: 0627562900101017-02

VOID AFTER 180 DAYS

Insured Name:
LARRY MICHAEL GRAY

Date: 1/2/2019

Feature Symbol and Amount:
APD \$2,899.09


Amount:
\$2,899.09

TWO THOUSAND EIGHT HUNDRED NINETY NINE AND 09/100 DOLLARS***

Pay to
the
Order
Of:
HIDALGO COUNTY

In
Payment
Of:
PROPERTY DAMAGE COVERAGE

Mail To: HIDALGO COUNTY ANIMAL CONTROL
1304 S 25TH AVE
EDINBURG TX, 78542-7205
US



GEICO

05

Request a supplement at partners.geico.com
partners.geico.com/gvbps/Logon.aspx
DALLAS, TX 75244

Phone: (956) 271-3865
Fax: (866) 959-1069

Claim #: 0627562900101017-02
Workfile ID: d22bebf1

Estimate of Record

Written By: SAUL BENAVIDES, License Number: 2086284, 12/12/2018 11:18:25 AM
Adjuster: H732

Insured: Larry Gray Owner Policy #: Claim #: 0627562900101017-02
Type of Loss: Liability Date of Loss: 11/02/2018 12:46 PM Days to Repair: 6
Point of Impact: 06 Rear Deductible:

Owner (Claimant): Hidalgo County Animal Control 1304 S 25th Ave Edinburg, TX 78542 (956) 383-0111 Business	Inspection Location: Hacienda Collision Ctr-XD Hacienda Collision Ctr-XD 1325 E PECAN BLVD MCALLEN, TX 78501 Drive-in (956) 213-1000 Day	Appraiser Information: sbenavides@geico.com (956) 271-3865	Repair Facility: UNKNOWN AT THIS TIME
---	---	---	---

VEHICLE

2011 FORD F-150 XL Regular Cab 126" WB 2D P/U 6-3.7L Flex Fuel Electronic Fuel Injection WHITE

VIN: 1FTMF1CMXBKD38579 Production Date: Interior Color:
License: 1118637 Odometer: 169937 Exterior Color: WHITE
State: TX Condition:

TRANSMISSION AUTOMATIC TRANSMISSION OVERDRIVE	TRACTION CONTROL STABILITY CONTROL AIR CONDITIONING	DRIVERS SIDE AIR BAG PASSENGER AIR BAG FRONT SIDE IMPACT AIR BAGS HEAD/CURTAIN AIR BAGS	ANTI-LOCK BRAKES (4)
DRIVER CONVENIENCE MESSAGE CENTER INTERMITTENT WIPERS TILT WHEEL CONSOLE/STORAGE	RADIO AM RADIO FM RADIO STEREO SEARCH/SEEK	PAINT CLEARCOAT PAINT	GLASS & MIRRORS DUAL MIRRORS TINTED GLASS
INSTRUMENT PANEL	SAFETY	FRONT END POWER STEERING POWER BRAKES	WHEELS 4-WHEEL DISC BRAKES STYLED STEEL WHEELS TRUCK & TOWING REAR STEP BUMPER

Estimate of Record

2011 FORD F-150 XL Regular Cab 126" WB 2D P/U 6-3.7L Flex Fuel Electronic Fuel Injection WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		PICK UP BOX					
2	**	Repl A/M CAPA Tail gate w/o flex step	FO1900124PP	1	598.00	1.7	3.0
3		R&I RT Upper molding carbon black	9L3Z99291A40AA			0.3	
4		R&I LT Upper molding carbon black	9L3Z99291A41BA			0.3	
5		R&I RT Lower deflector black textured	5L3Z99292A22AAA			0.2	
6		R&I LT Lower deflector black textured	5L3Z99292A23AAA			0.2	
7	*	Rpr RT Side panel	9L3Z9927840A			<u>3.0</u>	<u>2.2</u>
		NOTE: Partial Paint / Full Clear Coat					
8		Overlap Major Non-Adj. Panel					-0.2
9	*	Rpr LT Side panel	9L3Z9927841A			<u>5.0</u>	<u>2.7</u>
10		Overlap Major Non-Adj. Panel					-0.2
11		REAR LAMPS					
12		R&I RT Tail lamp assy w/bright trim	BL3Z13404B			0.3	
13		R&I LT Tail lamp assy w/bright trim	BL3Z13405B			0.3	
14	#	Set Up & Measure		1		1.5 F	
15		REAR BUMPER					
16		O/H rear bumper				1.8	
17	*	Repl LKQ Step pad w/o trailer tow	9L3Z17B807A	1	<u>Incl.</u>	<u>Incl.</u>	
18	* <>	Repl LKQ Bumper painted w/o reverse sensor +25%	9L3Z17906CPTM	1	<u>562.50</u>	<u>Incl.</u>	<u>1.8</u>
		NOTE: INCLUDES BRACKETS, STEP PAD					
		available at r&r auto parts 956-461-6733 450 PLUS MARK UP					
		not available at reys auto parts, 956-787-8300					
		not available at discount auto parts, 956-464-7171					
19		Overlap Major Non-Adj. Panel					-0.2
20	*	Repl LKQ Reinforcement w/o hitch	9L3Z17D826A	1	<u>Incl.</u>	<u>Incl.</u>	
21	*	Repl LKQ RT Bumper bracket	9L3Z17788B	1	<u>Incl. s</u>	<u>1.5</u>	<u>0.4</u>
22	*	Repl LKQ LT Bumper bracket	9L3Z17788A	1	<u>Incl. s</u>	<u>1.5</u>	<u>0.4</u>
23		Clear Coat					2.5
24		OTHER CHARGES					
25	#	E.P.C.		1	2.50		
SUBTOTALS					1,163.00	17.6	12.4

NOTES

Prior Damage Notes:

Estimate of Record

2011 FORD F-150 XL Regular Cab 126" WB 2D P/U 6-3.7L Flex Fuel Electronic Fuel Injection WHITE

DAMAGE NEAR CAB, LOWER AREA BUCKLE
 SCRATCHES ON TAIL LAMPS
 DENTS RT SIDE BED PANEL
 RUST ON FRONT BOX PANEL
 BOX RT & LT SIDE UPPER MOLDINGS DAMAGED
 CHIPS ON WINDSHIELD
 MISSING F150 EMBLEMS ON FENDERS

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,160.50
Body Labor	16.1 hrs @	\$ 42.00 /hr	676.20
Paint Labor	12.4 hrs @	\$ 42.00 /hr	520.80
Frame Labor	1.5 hrs @	\$ 45.00 /hr	67.50
Paint Supplies	12.4 hrs @	\$ 28.00 /hr	347.20
Other Charges			2.50
Subtotal			2,774.70
Sales Tax	\$ 1,507.70 @	8.2500 %	124.39
Total Cost of Repairs			2,899.09
Total Adjustments			0.00
Net Cost of Repairs			2,899.09

This is not an authorization to repair.

All GEICO customers have the right to have their vehicle repaired in the shop of their choice.

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

***IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:

****OWNER LIMITED GUARANTEE**** WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR