

## Magline MDS-16-92-36-6F-AS-12C Mobile Container Loading Ramp

ITEM# **1865781**  
LOCATION **Fayetteville, North Carolina, United States, 28306**



(15 - photos)

[Print](#) [Email](#) [Shar](#) [Shar](#) [Shar](#)

SOLD ON **1/9/19**

WINNING BID **US \$7,785**

# OF BIDS **199** [View Bid History](#)

# SOLD!

## ITEM DETAILS

METER READING

Not Available

SERIAL #

385X

Capacity: 16,000 lbs



Inspected by IronPlanet.

Your purchase is protected by our IronClad Assurance.



Get **PurchaseFlex™ Financing**: Up to 100% financing with \$0 down

Calculate monthly payment 

## Recommendations For You [Search all](#)



**Automatic Car Wash**

Texas (288 mi away)

**US \$64,000**



**Lot of (8) 55 Gallon Drums (Empty)**

Texas (306 mi away)

**Coming Soon**



**Lot of (2) Small Arms Storage Racks**

Alabama (687 mi away)

**US \$5.00**



**Ground Fueling Ad**

Georgia (928 mi away)

**US \$5.00**

## Previously Viewed



**1991 AM General M998 HMMWV 4 Door Hard Top**

California (1,259 mi away)

**US \$12,575**

## INSPECTION REPORT

Please note that as the buyer, you are responsible for reviewing the entire inspection report when evaluating an item.

 Protected by IronClad Assurance®

## GENERAL APPEARANCE

DESCRIPTION	RATING	DETAILS
-------------	--------	---------

 (11)		
--	--	--

## LOGISTICS

DESCRIPTION	RATING	DETAILS
-------------	--------	---------

Shipping Dimensions - DLA		Length: 36'; Width: 8'; Height: 5'
---------------------------	--	------------------------------------

Machine Weight - DLA		Machine weight: 5,000 lbs
----------------------	--	---------------------------

Modifications - DLA		Please provide any comments on potential shipping issues and note any modifications; Flatbed transport only
---------------------	--	---

## Disputes:

This item is offered with **IronClad Assurance®** protection. With IronClad Assurance®, if a buyer discovers that the item is not substantially in the condition as represented in this inspection report, the buyer may submit a written dispute claim to IronPlanet. Following submission of a written dispute claim, IronPlanet will investigate the claim, re-inspecting the equipment item as necessary, and determine a fair and mutually beneficial resolution. Please note that IronPlanet inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

 [Need help? Contact Us](#)

 North America  English 

Company



---

**Support**



---

**Our family of sites**



---

**Popular categories**



---

**Stay connected**



**Download Our Mobile App**



**App Store**

**Google play**

---

Copyright © 1999-2019 IronPlanet, Inc. All Rights Reserved. IronPlanet®, Asset Appraisal Services<sup>SM</sup>, TruckPlanet®, GovPlanet®, Kruse Energy<sup>SM</sup>, IronClad Assurance® and Auctions you can trust® are service marks of IronPlanet, Inc. All other marks and brands are the property of their respective owners.