

HIDALGO COUNTY MUTUAL SAFETY DIVISION  
 2818 S EXP 281 HWY  
 EDINBURGH TX 78539

AUTO CLUB COUNTY MUTUAL INSURANCE COMPANY					Check No: 0005419996
					Issued Date: 08/14/2019
Claim Number 013853552	Date of Occurrence 07/03/19	COV Type PD	COV Type	Type of Payment CLAIM	Payment/Withholding Information
Named Insured (Last, First, Middle) MARILOU PANCHO					Total Payment Amount: \$1,253.83
Name of Claimant AARON GARZA					Federal Withholding: \$0.00
Payment Memo Vehicle Repairs					State Withholding: \$0.00
					Total Check Amount: \$1,253.83
Handling Adjuster Colby Bailey			Adjuster Number 672652		District Office TX IRVING - ER7
Telephone 469-221-2385	Envelope Number 58263	Document	U.S. YES		Stop Code

HARLAND CLARKE 10421 REV 10/15 80178378

THE FACE OF THIS DOCUMENT HAS A COLORED BACKGROUND ON WHITE PAPER

AUTO CLUB COUNTY MUTUAL INSURANCE COMPANY  
 P.O. BOX 630588, IRVING, TX 75069-0588

Bank of America

70-2328  
 719 IL

08/14/2019

No. 0005419996

Pay One Thousand Two Hundred Fifty-Three Dollars And Eighty-Three Cents\*\*\*\*\*

\$ \*\*\*\*\*1,253.83

TO THE ORDER OF HIDALGO COUNTY MUTUAL SAFETY DIVISION  
 2818 S EXP 281 HWY  
 EDINBURGH TX 78539

Memo

Type: CLAIM CHECK Office: TX IRVING - ER7  
 Insured: MARILOU PANCHO  
 Claimant: AARON GARZA  
 Claim Number: 013853552 Date of Occurrence: 07/03/19 Coverage Type: PD

*Rajiv Vaema*

AUTHORIZED SIGNATURE

CASH CHECK PROMPTLY VOID AFTER 6 MONTHS

⑈0005419996⑈ ⑆071923284⑆ 8765118152⑈

Details on Back. Security Features Included.

Date: 8/13/2019 11:46 AM  
 Estimate ID: 3349080053  
 Estimate Version: 0  
 Committed  
 Profile ID: \* PDA TX

# Property Damage Appraisers (PDA Harlingen)

Harlingen/Brownsville/McAllen P.O. BOX 531911, HARLINGEN, TX 78553  
 (956) 425-1912  
 Fax: (956) 425-2335  
 Email: PDAHARLINGEN@PDAORG.NET

\*Not An Authorization For repair\*  
 Read disclaimers following appraisal calculations.

Damage Assessed By: Joel Martinez  
 Classification:

Appraised For: Anthony Torres-Amaya

Condition Code: Good  
 Date of Loss: 7/ 3/2019  
 Contact Date: 8/13/2019  
 Deductible: 0.00  
 File Number: 3349080053  
 Policy No: TPA061384172

Type of Loss: Collision  
 Arrival Date: 8/13/2019  
 Accident Date: 7/ 3/2019

Claim Number: 013853552-C-3098

Insured: MARILOU PANCHO  
 Claimant: Hidalgo County Mutual Safety Divisi  
 Owner: Hidalgo County Mutual Safety Divisi

Mitchell Service: 911730

Description: 2015 Ford F-150 XL  
 Body Style: 4D PkUpXCb 7' Bed 145" WB  
 VIN: 1FTEX1C82FKD98964  
 Mileage: 49,721  
 OEM/ALT: A  
 Parts Profile: Harlingen  
 Color: Red

Vehicle Production Date: 6/15  
 Drive Train: 3.5L Inj 6 Cyl 2WD  
 License: 125 6022 TX

Parts Profile Version: 2

Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, AIR CONDITION  
 TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG  
 FRONT SIDE AIRBAG WITH HEAD PROTECTION, ANTI-LOCK BRAKE SYS., TRACTION CONTROL  
 TIRE INFLATION/PRESSURE MONITOR, FIRST ROW SPLIT BENCH SEAT, CLOTH SEAT  
 SIDE AIRBAGS, AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION  
 ELECTRONIC STABILITY CONTROL, REAR BENCH SEAT

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	104071	BDY	REMOVE/INSTALL	Frt Bumper Assy			1.0
2	100933	BDY	REMOVE/INSTALL	R Front Combination Lamp			0.7 #
3	101669	REF	BLEND	R Fender Outside			1.2*
4	101677	BDY	REPAIR	R Fender Panel	Existing		2.0**
5	102319	BDY	REMOVE/INSTALL	R Fender Splash Shield			0.1 #
6	102321	BDY	REMOVE/INSTALL	R Antenna Base			0.2 #
7	102270	BDY	REMOVE/INSTALL	R Cowl Top Grille			0.6 #
8	100081	REF	BLEND	R Frt Door Outside			1.2*
9	100619	BDY	REPAIR	R Frt Door Repair Panel	Existing		2.0**
10	100053	BDY	REMOVE/INSTALL	R Frt Rear View Mirror			0.3
11	100057	BDY	REMOVE/INSTALL	R Frt Door Rear Sash Moulding			0.2 #
12	100059	BDY	REMOVE/INSTALL	R Frt Otr Door Belt Moulding			0.2
13	100061	BDY	REMOVE/INSTALL	R Frt Door Trim Panel			INC
14	100095	BDY	REMOVE/INSTALL	R Frt Otr Door Handle			0.7 #
15	900500	BDY*	REMOVE/REPLACE	Decals	Sublet	120.00	* INC*
16	900500	BDY*	REMOVE/INSTALL	Brush Guard	Existing		1.5* r
17	900500	REF *	REFINISH/REPAIR	Brush Guard	Existing		1.0*
18	900500	BDY*	REPAIR	R Brush Guard Section	Existing		3.0*
19	936007		ADD'L COST	Shop Materials		25.00	*

Date: 8/13/2019 11:46 AM  
 Estimate ID: 3349080053  
 Estimate Version: 0  
 Committed  
 Profile ID: \* PDA TX

20	936012		ADD'L COST	Hazardous Waste Disposal		
21	933002	REF	ADD'L OPR	Clear Coat		3.00 *
22	933005	BDY	ADD'L OPR	Restore Corrosion Protection		10.00 * 0.2*
23	AUTO		ADD'L COST	Paint/Materials		211.20 *

\* - Judgment Item  
 # - Labor Note Applies  
 r - CEG R&R Time Used For This Labor Operation

### Estimate Totals

<table border="0" style="width: 100%;"> <tr> <td style="width: 10%;">I. Labor Subtotals</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;"><u>Units</u></td> <td style="width: 10%; text-align: center;"><u>Rate</u></td> <td style="width: 10%; text-align: center;"><u>Add'l Labor Amount</u></td> <td style="width: 10%; text-align: center;"><u>Sublet Amount</u></td> <td style="width: 10%; text-align: center;"><u>Totals</u></td> </tr> <tr> <td>Body</td> <td></td> <td style="text-align: center;">12.7</td> <td style="text-align: center;">50.00</td> <td style="text-align: center;">10.00</td> <td style="text-align: center;">0.00</td> <td style="text-align: center;">645.00</td> </tr> <tr> <td>Refinish</td> <td></td> <td style="text-align: center;">4.4</td> <td style="text-align: center;">50.00</td> <td style="text-align: center;">0.00</td> <td style="text-align: center;">0.00</td> <td style="text-align: center;">220.00</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td colspan="2" style="text-align: center;">Non-Taxable Labor</td> <td style="text-align: center;">865.00</td> </tr> <tr> <td>Labor Summary</td> <td></td> <td style="text-align: center;">17.1</td> <td></td> <td></td> <td></td> <td style="text-align: center;">865.00</td> </tr> </table>	I. Labor Subtotals		<u>Units</u>	<u>Rate</u>	<u>Add'l Labor Amount</u>	<u>Sublet Amount</u>	<u>Totals</u>	Body		12.7	50.00	10.00	0.00	645.00	Refinish		4.4	50.00	0.00	0.00	220.00					Non-Taxable Labor		865.00	Labor Summary		17.1				865.00	<table border="0" style="width: 100%;"> <tr> <td style="width: 10%;">II. Part Replacement Summary</td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;"><u>Amount</u></td> </tr> <tr> <td>Taxable Parts</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">120.00</td> </tr> <tr> <td>Sales Tax</td> <td style="text-align: center;">@</td> <td style="text-align: center;">8.250%</td> <td></td> <td></td> <td></td> <td style="text-align: center;">9.90</td> </tr> <tr> <td>Total Replacement Parts Amount</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">129.90</td> </tr> </table> <table border="0" style="width: 100%;"> <tr> <td style="width: 10%;">III. Additional Costs</td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;"><u>Amount</u></td> </tr> <tr> <td>Taxable Costs</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">239.20</td> </tr> <tr> <td>Sales Tax</td> <td style="text-align: center;">@</td> <td style="text-align: center;">8.250%</td> <td></td> <td></td> <td></td> <td style="text-align: center;">19.73</td> </tr> <tr> <td>Total Additional Costs</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">258.93</td> </tr> </table> <p>Paint Material Method: Rates      Init Rate = 48.00 , Init Max Hours = 99.9, Addl Rate = 0.00</p>	II. Part Replacement Summary						<u>Amount</u>	Taxable Parts						120.00	Sales Tax	@	8.250%				9.90	Total Replacement Parts Amount						129.90	III. Additional Costs						<u>Amount</u>	Taxable Costs						239.20	Sales Tax	@	8.250%				19.73	Total Additional Costs						258.93
I. Labor Subtotals		<u>Units</u>	<u>Rate</u>	<u>Add'l Labor Amount</u>	<u>Sublet Amount</u>	<u>Totals</u>																																																																																						
Body		12.7	50.00	10.00	0.00	645.00																																																																																						
Refinish		4.4	50.00	0.00	0.00	220.00																																																																																						
				Non-Taxable Labor		865.00																																																																																						
Labor Summary		17.1				865.00																																																																																						
II. Part Replacement Summary						<u>Amount</u>																																																																																						
Taxable Parts						120.00																																																																																						
Sales Tax	@	8.250%				9.90																																																																																						
Total Replacement Parts Amount						129.90																																																																																						
III. Additional Costs						<u>Amount</u>																																																																																						
Taxable Costs						239.20																																																																																						
Sales Tax	@	8.250%				19.73																																																																																						
Total Additional Costs						258.93																																																																																						

  

	I. Total Labor:		865.00
	II. Total Replacement Parts:		129.90
	III. Total Additional Costs:		258.93
	Gross Total:		1,253.83
	IV. Total Adjustments:		0.00
	Net Total:		1,253.83

Point(s) of Impact

2 Right Front Side (P)

Insurance Co: AAA AUTO OF TEXAS (CBILL)  
 TX

Inspection Site: Hidalgo County Mutual Safety Division  
 Address: 9805 N 10th St  
 McAllen, TX 78504  
 (956) 292-7030

Inspection Date: 8/13/2019

Body Shop: Hacienda Ford  
 Address: 3010 W. UNIVERSITY DR.  
 Edinburg, TX 78539  
 Telephone: (956) 383-1615  
 State Lic. No: 74-2606273