



AMERICAN ACCESS CASUALTY COMPANY
2211 Butterfield Road, Suite 200
Downers Grove, IL 60515

CIBC Bank
Chicago, IL 60603
2-648/710

CHECK NUMBER
0000867990

03/26/21

Claims Account

VOID AFTER 180 DAYS

PAY SEVEN HUNDRED FIFTY DOLLARS & 31/100

\$ 750.31

To The Order Of COUNTY OF HIDALGO
9805 N 10TH ST
MCALLEN, TX 78504

Memo CLM 2102264282 DL 12/08/2020 pg

AUTHORIZED SIGNATURE

SECURE FEATURES INCLUDE INVISIBLE FIBERS • MICROPRINTING • VOID PANTOGRAPH • ENDORSEMENT BACKER • CHEMICAL REACTANT

⑈0000867990⑈ ⑆071006486⑆ 2185034⑈

AMERICAN ACCESS CASUALTY COMPANY

COUNTY OF HIDALGO
9805 N 10TH ST
MCALLEN, TX 78504

CHECK NUMBER 0000867990
CHECK DATE 03/26/21

Invoice Date	Invoice No.	Description	Invoice Amt.
03/26/21	1225058	CLM 2102264282 DL 12/08/2020 pg PAYMENT FOR PROPERTY DAMAGES TO 2017 CHEV SILVERADO 1500 VIN: 3GCUKNECXHG245830	750.31

AMERICAN ACCESS CASUALTY COMPANY

COUNTY OF HIDALGO
9805 N 10TH ST
MCALLEN, TX 78504

CHECK NUMBER 0000867990
CHECK DATE 03/26/21

Invoice Date	Invoice No.	Description	Invoice Amt.
03/26/21	1225058	CLM 2102264282 DL 12/08/2020 pg PAYMENT FOR PROPERTY DAMAGES TO 2017 CHEV SILVERADO 1500 VIN: 3GCUKNECXHG245830	750.31

Hacienda Collision Center - Weslaco

1302 North Annie Drive, Weslaco, TX 78596

Phone: (956) 447-9777

FAX: (956) 447-1412

Workfile ID:

a388eec7

PartsShare:

64HXHR

Preliminary Estimate

Customer: County Sheriff, Hidalgo

Job Number:

Written By: Jaime Luna

Insured: County Sheriff, Hidalgo

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

Owner:

County Sheriff, Hidalgo

Inspection Location:

Hacienda Collision Center - Weslaco

1302 North Annie Drive

Weslaco, TX 78596

Repair Facility

(956) 447-9777 Business

Insurance Company:

VEHICLE

2017 CHEV Silverado 1500 Work Truck Crew Cab 143.5" WB 4WD 4D SHORT 8-5.3L Flex Fuel Direct Injection

VIN: 3GCUKNECXHG245830

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

Mileage Out:

State:

Production Date:

Condition:

Job #:

TRANSMISSION

Automatic Transmission

Overdrive

4 Wheel Drive

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

DECOR

Dual Mirrors

Tinted Glass

Console/Storage

CONVENIENCE

Air Conditioning

Tilt Wheel

Cruise Control

Message Center

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Xenon or L.E.D. Headlamps

SEATS

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper

Preliminary Estimate

Customer: County Sheriff, Hidalgo

Job Number:

2017 CHEV Silverado 1500 Work Truck Crew Cab 143.5" WB 4WD 4D SHORT 8-5.3L Flex Fuel Direct Injection

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2		O/H bumper assy				2.6	
3	* <>	Rpr Front bumper w/o park assist, w/o fog lamps paint to mtch				4.0	2.6
4		Add for Clear Coat					1.0
5	Repl	RT Support brace	22757268	1	40.92	0.1	
6	#	Subl Hazardous waste removal		1	5.00 T		
7	#	Subl Wheel alignment		1	69.99 T		
8	#	R&I Brush Guard				1.5	
SUBTOTALS					115.91	8.2	3.6

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			40.92
Body Labor	8.2 hrs @	\$ 44.00 /hr	360.80
Paint Labor	3.6 hrs @	\$ 44.00 /hr	158.40
Paint Supplies	3.6 hrs @	\$ 32.00 /hr	115.20
Miscellaneous			74.99
Subtotal			750.31
Grand Total			750.31
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			750.31

MyPriceLink Estimate ID / Quote ID:

765658126731976704 / 77863525