

**Hidalgo County -
New Courthouse Project**
Monthly Progress Report

**Executive
Report**

Construction
QAI/QC

Utilities

Coordination Efforts

Construction


Controls

Testing

Disclaimer

Jacobs

Executive Report




Jacobs

Morganti

HDR

Terracon



Jacobs Progress Update

- PM/CM
 - Deliberating Roof solutions
 - Coordination between construction and FF&E packages
- Commissioning
 - Start up of equipment is coming to completion
 - Domestic Water Skid Pump package completed
 - Development of functional performance test documents completed
- Activation and Move Management
 - Continued Key User Meetings for activation and move management
 - Coordination of FF&E deliveries for levels 1-4
 - Coordination with HDR and Key Users to identify and address work flow issues

MTI Progress Update

- Subcontractors continuous work
- Completion of East Curtain Wall
- Continued roof investigation

Future Key Activities

- Beginning of punch list for Levels 1-4
- On going commissioning and testing
- Continued site work and landscaping

Level 1

Level 2

Level 3

Level 4

Level 5

Level 6

Level 7

Roof

Site work

CUP



HDR Progress Update

- Phase 1
 - Mechanical Roof Screen Design
 - Pandemic Preparedness Rough Order of Magnitude (ROM's)
- Phase 2
 - Finalizing Demo and Site Design
- Review and approve MTT's Punch List

Future Key Activities



Terracon Progress Update

- Microbial Assessment Report submission

Future Key Activities

- 100 % Dry-in
- Roofing system testing
- Final curtain wall testing