



Certificate of Substantial Completion

PROJECT: AVILA HARWELL CAMPUSES SAFE WALK COMMUNITY PROJECT
PRECINCT NO. 4

PROJECT NUMBER: C-21-331-04-06

OWNER: HIDALGO COUNTY PRECINCT NO. 4

CONTRACTOR: TEXAS CORDIA CONSTRUCTION

The Work performed under this Contract has been reviewed and found, to the Engineer's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion is sufficiently complete in accordance with the Contract Documents so that the owner can occupy or utilize the Work for its intended use.

HCDD No. 1
Engineering Firm

[Handwritten signature]

By: Signature

Jorge A. Gonzalez, PE
By: Print Name

08-03-21
Date of Issuance

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

Cost estimate of Work that is incomplete or defective: \$ 2000.00

The Contractor will complete or correct the Work on the list of items attached hereto and complete the work by 8/17/21
Date

Texas Cordia Construction
Contractor

[Handwritten signature]

By: Signature

Yara M. Corbitt, PE, CEO
By: Print Name

08/18/2021
Date of Issuance

REVIEWED BY: HIDALGO COUNTY DRAINAGE DISTRICT NO. 1
By: Signature By: Print Name Date of Issuance

Certificate of Substantial Completion – Page 2

**PROJECT: AVILA HARWELL CAMPUSES SAFE WALK COMMUNITY PROJECT
PRECINCT NO. 4**

PROJECT NUMBER: C-21-331-04-06

OWNER: HIDALGO COUNTY PRECINCT NO. 4

CONTRACTOR: TEXAS CORDIA CONSTRUCTION

LIST OF ITEMS TO BE COMPLETED OR CORRECTED FOR THE ABOVE REFERENCED PROJECT.

1. STA 21*50 clean the brush debris
2. STA 11*50 please check the top elevation of the manhole it seems that's to low , and level out the natural ground
3. STA 10+90 please trim the tree branch for the school Crossing sign to be full visible
Also, same Station # the edge of the ADA Ramp has a bump that's Not flush and could
4. cause an accident
5. _____
6. _____
7. _____
8. _____
9. _____
10. _____

Prepared By:

HCDD No. 1
Engineering Firm

By: Signature

By: Print Name

Date of Issuance









