



P.O. Box 645
 Brenham, TX 77834-0645
 (979) 836-5224 (800) 392-2202



COUNTY OF HIDALGO
 9805 N 10TH ST
 MCALLEN TX 78504-9529

INVOICE NUMBER	POLICY NUMBER	CLAIM NUMBER	LOSS DATE	PAYMENT
	4-304-3230182	103-63-994	01/19/2022	\$887.37

NOTE:

CLAIMANT: County of Hidalgo
ADJUSTER: Sandy Sanchez

INSURED: JUAN LOPEZ

GFM NoAdd-103-63-994-001-157824493-0001

THE ORIGINAL DOCUMENT HAS A WHITE REFLECTIVE WATERMARK ON THE BACK. HOLD AT AN ANGLE TO VIEW. DO NOT CASH IF NOT PRESENT.

BATCH 1061232 88-88 11/18/2022 103-63-994

GERMANIA INSURANCE COMPANY
 P.O. Box 645
 Brenham, TX 77834-0645
 (979) 836-5224 (800) 392-2202

JP. Morgan Chase Bank, N.A.
 Dallas, TX
 800-457-7191

CHECK NO.: 1061232
DATE ISSUED: 11/18/2022

POLICY NUMBER: 4-304-3230182
CLAIM NUMBER: 103-63-994
LOSS DATE: 01/19/2022

Rear-end collision

**ALL PAYEES MUST ENDORSE
 VOID AFTER 365 DAYS**

\$887.37

EIGHT HUNDRED EIGHTY SEVEN DOLLARS AND 37 CENTS

PAY TO THE ORDER OF:
 COUNTY OF HIDALGO

Authorized Signature

⑈0001061232⑈ ⑆111300880⑆ 6300004432⑈

FORM NO. 2860-S COPY/ISSUE DATE 11/15/2018

Security Features Included



Hacienda Ford Collision Center

" A BLUE OVAL CERTIFIED DEALER "
 3010 West University Drive, Edinburg, TX 78539
 Phone: (956) 219-2117
 FAX: (956) 386-0217

Workfile ID: 446bc537
 PartsShare: 6Chc7G
 Federal ID: 742606273

Preliminary Estimate

Customer: Salazar, Robert

Job Number:

Written By: EVERARDO GOMEZ

Insured: Salazar, Robert
 Type of Loss:
 Point of Impact: 06 Rear

Policy #:
 Date of Loss:

Claim #:
 Days to Repair: 0

Owner:
 Salazar, Robert
 20805
 edinburg, TX 78542
 (956) 585-4509 Business

Inspection Location:
 Hacienda Ford Collision Center
 3010 West University Drive
 Edinburg, TX 78539
 Repair Facility
 (956) 219-2117 Day

Insurance Company:

VEHICLE

2017 FORD F-150 XLT SuperCrew 4WD w/5.5' Box 4D SHORT 8-5.0L Flex Fuel Sequential MPI white

VIN: 1FTEW1EF1HKC47910	Interior Color: GRAY	Mileage In:	Vehicle Out:
License: 1360695	Exterior Color: white	Mileage Out:	
State: TX	Production Date: 12/2016	Condition:	Job #:

TRANSMISSION

Automatic Transmission
 4 Wheel Drive

POWER

Power Steering
 Power Brakes
 Power Windows
 Power Locks
 Power Mirrors

DECOR

Dual Mirrors
 Privacy Glass

CONVENIENCE

Air Conditioning
 Intermittent Wipers
 Tilt Wheel
 Cruise Control
 Keyless Entry
 Alarm
 Steering Wheel Touch Controls
 Telescopic Wheel

RADIO

AM Radio
 FM Radio
 Stereo
 Search/Seek

CD Player
SAFETY
 Drivers Side Air Bag
 Passenger Air Bag
 Anti-Lock Brakes (4)
 4 Wheel Disc Brakes
 Traction Control
 Stability Control
 Front Side Impact Air Bags
 Head/Curtain Air Bags
 Hands Free Device

SEATS

Cloth Seats

Bucket Seats
 Reclining/Lounge Seats
WHEELS
 Aluminum/Alloy Wheels
PAINT
 Clear Coat Paint
OTHER
 Fog Lamps
TRUCK
 Rear Step Bumper

Get live updates at www.carwise.com/e/4b3jVC

Preliminary Estimate

Customer: Salazar, Robert

Job Number:

2017 FORD F-150 XLT SuperCrew 4WD w/5.5' Box 4D SHORT 8-5.0L Flex Fuel Sequential MPI white

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	Disconnect Battery		1		0.2	
2	REAR BUMPER						
3		O/H rear bumper				2.7	
4	Repl	Bumper chrome w/o park sensor	FL3Z17906A	1	518.37	Incl.	
5	VEHICLE DIAGNOSTICS						
6	Repl	Pre-repair scan		1		1.0 M	
7	Repl	Post-repair scan		1		1.0 M	
SUBTOTALS					518.37	4.9	0.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			518.37
Body Labor	2.9 hrs @	\$ 50.00 /hr	145.00
Mechanical Labor	2.0 hrs @	\$ 112.00 /hr	224.00
Subtotal			887.37
Grand Total			887.37
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			887.37

MyPriceLink Estimate ID / Quote ID:

915983662472765440 / 99834312