

# KEMPER

American Access Casualty Company  
2211 Butterfield Road, Suite 200  
Downers Grove, IL 60515

MB 01 000863 19334 H 5 B  
COUNTY OF HIDALGO  
9805 N. 10TH STREET  
MCALLEN, TX 78504

Named insured: CHRISTINE REYES  
Claimant: HIDALGO COUNTY SHERIFF'S  
DEPARTMENT  
Policy number: 42AU000948800  
Claim number: 2301040444  
Loss date: October 3, 2022

000863 1/1



## Your Automobile policy claim payment

We attached a check for payment of the above noted claim. For full explanation or if you have any questions, please contact me.

Thank you,

American Access Casualty Company

TRINA HARTFIELD  
Claims Department  
4693244527

PD SUBRO SETTLEMENT FOR 2017 CHEVY SILVERADO VIN 250924



SECURITY NOTE: The face of this check is printed on a blue background. See reverse for additional security features.

<b>American Access Casualty Company</b> 2211 Butterfield Road, Suite 200 Downers Grove, IL 60515	Claim number: 2301040444	Issue Date: 3/9/2023 Loss Date: 10/3/2022	7000074549 70-1558 719
PAY TO THE ORDER OF COUNTY OF HIDALGO			
Six Thousand Sixteen and 63/100 BMO Harris Central N.A.			Dollars \$6,016.63 Void after 180 days from date issued <i>Michael W. Simon</i>
Memo:			

Security Features Included Details on back

⑈ 7000074549⑈ ⑆ 071915580⑆ 04⑈ 164⑈ 963⑈ 1⑈



**PAINTS, DENTS & MORE / PDM**  
**Collision Repair Center**

Workfile ID: 67c2a7a0  
 PartsShare: 6ZYHpD  
 Federal ID: 45-4423007

Your Accident Repair Center  
 5320 N. Birch St., Pharr, TX 78577  
 Phone: (956) 787-3368  
 FAX: (956) 502-5613

**Final Bill**

**RO Number: 33101**

Customer: Hidalgo County Sheriff Insurance: FLEET Adjuster: Keren Gonzalez  
 Phone: Create Date: 10/18/2022  
 Claim:  
 Loss Date:  
 Deductible:

(956) 460-6416

Unit # 798

2017 CHEV Silverado 1500 LS Crew Cab 143.5" WB 4D SHORT 8-5.3L Flex Fuel Direct Injection

VIN: 3GPCNCE8HG250924 Interior Color: Mileage In: 95,862 Vehicle Out:  
 License: Exterior Color: Mileage Out:  
 State: Production Date: Condition: Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		<b>PICK UP BOX</b>						
2	E01	Repair	Tall gate w/o gate assist				6.0	Body	2.3
3	E01		Add for Clear Coat						0.9
4	E01	Remove/Install	Emblem "BOWTIE" gold insert				0.3	Body	
5	E01	Remove/Replace	LT Latch	1	85.52T	OEM	0.2	Body	
6	E01	Remove/Replace	LT Side panel Chevrolet	1	1,091.63T	OEM	9.5	Body	5.2
7	E01		Overlap Major Non-Adj. Panel						(0.2)
8	E01		Add for Clear Coat						1.0
9	E01		<b>REAR LAMPS</b>						
10	E01	Remove/Replace	LT Tall lamp assy w/LED	1	695.00T	A/M	0.0	Body	
11	E01		<b>REAR BUMPER</b>						
12	E01	Remove/Replace	O/H rear bumper				3.5	Body	
13	E01	Remove/Replace	Rear bumper primed w/o pk assist	1	953.75T	OEM	0.0	Body	2.0
14	E01		Add for Clear Coat						0.8
15	E01	Remove/Replace	LT Insert pad	1	46.07T	OEM			
16	E01	Remove/Replace	LT Insert	1	67.10T	OEM	0.0	Body	
17	E01	Remove/Replace	Step pad	1	272.95T	OEM	0.0	Body	

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					3,212.02
Labor, Body			50.00	19.5	975.00
Labor, Refinish			50.00	12.0	600.00
Material, Paint					456.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

**Final Bill**

**RO Number: 33101**

2017 CHEV Silverado 1500 LS Crew Cab 143.5" WB 4D SHORT 8-5.3L Flex Fuel Direct Injection

Material, Shop	30.00	15.7	471.00
<b>Subtotal</b>			<b>5,714.02</b>
Sales Tax			302.61
<b>Grand Total</b>			<b>6,016.63</b>
<b>Net Total</b>			<b>6,016.63</b>

Estimate Version	Total \$
Original	6,016.63

Insurance Total \$:	6,016.63
Received from Insurance \$:	0.00
Balance due from Insurance \$:	6,016.63
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural