



HIDALGO COUNTY COMMISSIONER'S COURT
9805 N 10TH ST
MCALLEN TX 78504-9529

03/24/2023

HIDALGO COUNTY COMMISSIONER'S COURT,
ENCLOSED PLEASE FIND PAYMENT IN THE AMOUNT OF \$1,672.33 FOR YOUR LOSS ON 9/16/2022.
PLEASE REFERENCE CLAIM DETAILS BELOW.

CLAIM NUMBER: 0696208214
DATE OF LOSS: 09/16/2022
INSURED: DOMINGO LOPEZ

In payment for Property Damage Liability for Date of Loss 9/16/2022.

ALLSTATE FIRE AND CASUALTY INSURANCE COMPANY
1-800-255-7828



-P0555W

0000020230324004388ZCT01001001004882

INSURED: DOMINGO LOPEZ
CLAIMANT: HIDALGO COUNTY COMMISSIONER'S COURT
IN PAYMENT OF: LOSS ON 9/16/2022.

CLAIM NUMBER		132404318
0696208214		
TAX ID	EMPLOYEE ID	
	GOWE	64-1278
Bank of America NA Atlanta, DeKalb, Cty, Georgia	Bank of America Customer Connection	611

PAY: ONE THOUSAND SIX HUNDRED SEVENTY-TWO DOLLARS AND THIRTY-THREE CENTS

\$ 1,672.33



TO THE ORDER OF HIDALGO COUNTY COMMISSIONER'S COURT
9805 N 10TH ST
MCALLEN TX 78504-9529


INVOICE NUMBER	MCO	DATE ISSUED
	4170	03/24/2023

COMPANY: ALLSTATE FIRE AND CASUALTY INSURANCE COMPANY

Julie Parsons

John C Pinterogi

AUTHORIZED SIGNATURES



VOID IF NOT PRESENTED WITHIN THREE HUNDRED, SIXTY-FIVE DAYS OF DATE OF ISSUE

132404318 061112788 329 911 95620

Allstate Fire and Casualty Insurance Company
8675 Freeport Parkway, E-1, Irving, TX 75063

Estimate ID
13128278
Original

Claim Number
000696208214-003

For Self Service Customer Inquiries www.allstate.com/claims/track-claim.aspx

Owner
Vehicle Owner
9805 N 10TH ST
MCALLEN, TX 78504
(956) 292-7030 (Home)

Claimant
Vehicle Owner

Appraiser
Digital Operating Center 115
(888) 706-3686 (Work)

TX License
1609717

Underwriter
Allstate Fire and Casualty Insurance
Company
8675 Freeport Parkway, E-1
Irving, TX 75063

Allstate Fire and Casualty Insurance Company

Loss Type	Claim Number	Deductible	Reported Date
Liability	000696208214-003	0.00 - Not Waived	12/19/2022

Loss Date
09/16/2022

2022 Ford F-150 XLT 4 Door Crew Cab 145" WB 6 Foot Bed 5.0L 8 Cyl Gas Injected 2WD

Exterior Color	License	VIN	Drivable
Black	TX-RWW 8711	1FTEW1C51NKD72122	Yes

Odometer	Mitchell Service Code
12095	912329

Options

Air Conditioning	Alum/Alloy Wheels	AM-FM Stereo	Anti-Lock Brake Sys. (ABS)	Automatic Headlights
Auxiliary Input	Bluetooth Wireless Connectivity	Cloth Seat	Cruise Control	Daytime Running Lights
Driver Seat With Power Lumbar Support	Driver-Front Air Bag	Electric Defogger	Electronic Parking Aid	Electronic Stability Control
First Row Split Bench Seat	Fog Lights	Front Seats With Power Lumbar Support	Heated Mirror	Keyless Entry System
Left-Curtain Air Bag	MP3 Player	Passenger-Front Air Bag	Power Door Locks	Power Remote Mirror
Power Steering	Power Windows	Privacy Glass	Rear Bench Seat	Rearview Camera
Remote Vehicle Starter System	Second Row Side Airbag With Head Protection	Side Airbags	Side Blind Zone Alert	Steering Wheel Mounted Audio Control
Telematic Systems	Theft Deterrent Sys.	Tilt Steering Wheel	Tire Pressure Monitoring System	Traction Control/Electronic
Trip Computer				

Vehicle Owner | 2022 Ford F-150 XLT

Parts Profile
-Texas IP

Parts Profile Version
19.0

Line #	Description	LABOR			PART				
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Cab									
1	201700 R Cab Door Opening Panel	Repair	Body	2.0*#	Existing				
2	AUTO R Cab Corner Panel	Refinish Only	Refinish	1.5* C	Existing				
3	900501 Modified Refinish With Full Clear Coat								
4	201306 R Roof Moulding	Remove / Install	Body	0.3#	Existing				
5	201309 R Lwr Corner Panel Mldg	Remove / Install	Body	0.2	Existing				
6	200190 R Running Board Assy	Remove / Install	Body	0.5	Existing				
Front Door									
7	200297 R Frt Door Repair Panel	Repair	Body	6.0*#	Existing				
8	AUTO R Frt Door Outside	Refinish Only	Refinish	1.9* C	Existing				
9	900501 Modified Refinish With Full Clear Coat								
10	200303 R Frt Rear View Mirror	Remove / Install	Body	0.3#	Existing				
11	200309 R Frt Otr Door Belt Moulding	Remove / Install	Body	0.2	Existing				
12	200416 R Frt Door Trim Panel	Remove / Install	Body	0.4	Existing				
13	202281 R Frt Otr Door Handle	Remove / Install	Body	0.3	Existing				
Rear Door									
14	201408 R Rear Door Repair Panel	Repair	Body	1.0*#	Existing				
15	AUTO R Rear Door Outside	Refinish Only	Refinish	1.8* C	Existing				
16	900501 Modified Refinish With Full Clear Coat								
17	201412 R Rear Otr Door Belt Moulding	Remove / Install	Body	0.2	Existing				
18	201422 R Rear Door Trim Panel	Remove / Install	Body	0.4	Existing				
19	202283 R Rear Otr Door Handle	Remove / Install	Body	0.3	Existing				
Pickup Bed									
20	200571 Bed Assembly	Remove / Install	Body	2.5#	Existing				
21	200750 R Pickup Bed Side Panel	Repair	Body	2.0*#	Existing				
22	AUTO R Bed Side Panel Outside	Refinish Only	Refinish	2.8 C	Existing				
23	900501 damage to front and rear of bed.								
24	200103 R Pickup Bed Moulding	Remove / Install	Body	0.4#	Existing				
25	200905 R Frt Pickup Bed Stone Deflector	Remove / Install	Body	0.2#	Existing				

Line #	Description	LABOR			PART				
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
26	200105 R Rear Pickup Bed Stone Deflector	Remove / Install	Body	0.2#	Existing				
27	200907 R Corner Panel Mldg	Remove / Install	Body	0.2#	Existing				
Rear Lamps									
28	201977 R Rear Combination Lamp	Remove / Install	Body	0.2	Existing				
Rear Bumper									
29	200981 Rear Bumper Assy	Remove / Install	Body	INC	Existing				
Additional Costs & Materials									
30	AUTO Paint/Materials	Additional Cost						\$343.40*	Yes
31	936012 Hazardous Waste Disposal	Additional Cost						\$3.00*	
Additional Operations									
32	AUTO Clear Coat	Additional Operation	Refinish	2.1				\$0.00	
33	933005 Restore Corrosion Protection	Additional Operation	Body	0.2*				\$0.00	
Special / Manual Entry									
34	900500 Car Cover	Remove / Replace	Body*	0.0*	Aftermarket New	1		\$5.00*	

* Judgment Item

T Included in Two Tone Calculation

Labor Note Applies

d Discontinued by Manufacturer

C Included in Clear Coat Calculation

A Included in Clear Coat and Two Tone Calculation

r CEG R&R Time Used for this Labor Operation

[] Verify the part number and price before ordering

Disclaimer: This estimate has been prepared based on the use of replacement parts supplied by a source other than the manufacturer of your motor vehicle. Warranties applicable to these replacement parts are provided by the manufacturer or distributor of these parts rather than the manufacturer of your vehicle.

Estimate Totals

Labor	Units	Rate	Sublet Add'l Amount	Totals
Body Labor	18.0	\$46.00		\$828.00
Refinish Labor	10.1	\$46.00		\$464.60
Total Labor	28.1			\$1,292.60
			Taxable	\$1,292.60
			Tax 0.0000%	\$0.00
			Non-Taxable	\$0.00
			Labor Total	\$1,292.60
Parts		Amount		
Taxable Parts		\$0.00		\$0.00
			Parts Adjustments	\$0.00
			Tax 8.2500%	\$0.00
			Non-Taxable	\$5.00
			Parts Total	\$5.00
Costs		Amount		
Other Additional Costs		\$3.00		\$3.00
Paint Materials		\$343.40		\$343.40

Estimate Totals

Paint Materials Rate: \$34.00
 Rate Max: 99.9 units
 Additional Rate: \$0.00

Gross Totals	Amount
Gross Total	\$1,672.33

Taxable	\$343.40
Tax 8.2500%	\$28.33
Non-Taxable	\$3.00
Costs Total	\$374.73

Taxable	\$1,636.00
Tax	\$28.33
Non-Taxable	\$8.00
Gross Total	\$1,672.33

Adjustments	Amount
Total Customer Responsibility	\$0.00

Net Estimate Total \$1,672.33

SUPPLEMENT PROCESS INSTRUCTIONS:

Please be aware that any additional damage must be inspected by an Allstate technician while the vehicle is at the shop and torn down (when reasonably appropriate), prior to the repairs being completed. If Allstate is not informed of supplemental damage, it may not be covered under the claim. In addition, all invoices will be requested and reviewed.

Please follow the Virtual Assist App process for all future supplement requests.

The Virtual Assist App can be downloaded at no charge by visiting the Apple App store or the Google Play store. Search, download and install: Virtual Assist Arity

Updated 5/31/22 JB

IMPORTANT INFORMATION ABOUT THE NAMED INSURANCE COMPANY'S PARTS POLICY.

THIS ESTIMATE MAY LIST PARTS FOR USE IN THE REPAIR OF YOUR VEHICLE THAT ARE MANUFACTURED BY A COMPANY OTHER THAN THE ORIGINAL MANUFACTURER OF YOUR VEHICLE. THESE PARTS ARE COMMONLY REFERRED TO AS AFTERMARKET PARTS OR COMPETITIVE PARTS, AND MAY INCLUDE COSMETIC OUTER BODY CRASH PARTS SUCH AS HOODS, FENDERS, BUMPER COVERS, ETC. THE INSURANCE COMPANY GUARANTEES THE FIT AND CORROSION RESISTANCE OF ANY AFTERMARKET/COMPETITIVE OUTER BODY CRASH PARTS THAT ARE LISTED ON THIS ESTIMATE AND ACTUALLY USED IN THE REPAIR OF YOUR VEHICLE FOR AS LONG AS YOU OWN IT. IF A PROBLEM DEVELOPS WITH THE FIT OR CORROSION RESISTANCE OF THESE PARTS, THEY WILL BE REPAIRED OR REPLACED AT THE INSURANCE COMPANY'S EXPENSE. THIS GUARANTEE IS LIMITED TO THE REPAIR OR REPLACEMENT OF THE PART. THE INSURANCE COMPANY DOES NOT SEPARATELY GUARANTEE THE PERFORMANCE OF ORIGINAL EQUIPMENT MANUFACTURER PARTS AND MAKES NO REPRESENTATION ABOUT THE AVAILABILITY OF ANY MANUFACTURER'S GUARANTEE.

Disclaimer: Any person who knowingly presents a false or fraudulent claim for payment of a loss or benefit or knowingly