
Continental Plumbing Services, LLC

109 Red Ant Dr.
Weslaco, Texas 78596
(956) 619-6050
continental_plumbing@aol.com

August 18, 2023

Willacy County Regional Facility,

After repairing the water and flue pipes for the water heaters in the mechanical room, we installed a new water heater. We started checking the rest of the water heaters and found one that was continuously leaking. We believe that it rusted out from the inside due to the stored water in it since the facility closed. We do recommend that it be replaced due to it not being repairable. Thanks.

Sincerely,

Continental Plumbing Services, LLC

Eddie Vanderford - Project Manager



Aug 2017

Installed
8-3-2023
by [unclear]
Plumbing

This model is
iComm COMPATIBLE.
For info call
1-888-WATER2

DEVICE INFORMATION
SCAN THIS CODE
FOR MORE INFO
OR VISIT www.ac-smith.com

RELIEF VALVE

AC Smith

Call
A. O. Smith Technical Support
1-800-368-5888
Provide
Model and Serial Number
To
Service Address
For additional information
consult the literature or website
Responsible for the safety of
your tank. Use Careful. Use It
Right. WaterHeater.com

Energy
ENERGY

EnergyGuide
This label provides information on the energy efficiency of this product. It is important to read this information carefully before purchasing or using this product. The information on this label is based on the most recent information available at the time of printing. The information on this label is subject to change without notice. For more information, visit the EnergyGuide website at www.energyguide.com.

