

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 1 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A Yes No

Porous Media Uniform (0.72-2.0 inches).....N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 2 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Foundation: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Property Line: To Tank: _____ 8' To Drainfield: _____ 7'

Trench Depth: _____ 36" Trench Width: _____ 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): _____ SB2-8" Type: STD. GRAVELLESS No. of Feet: _____ 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: _____ N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: _____ JOSE A. GONZALEZ _____ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES _____ License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 3 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Foundation: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Property Line: To Tank: _____ 8' To Drainfield: _____ 7'

Trench Depth: _____ 36" Trench Width: _____ 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): _____ SB2-8" Type: STD. GRAVELLESS No. of Feet: _____ 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 4 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 5 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023



OSSF – Form G: Inspection Report

Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 6 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 7 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 8 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 2500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 9 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Foundation: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Property Line: To Tank: _____ 8' To Drainfield: _____ 7'

Trench Depth: _____ 36" Trench Width: _____ 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): _____ SB2-8" Type: STD. GRAVELLESS No. of Feet: _____ 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: _____ N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: _____ JOSE A. GONZALEZ _____ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES _____ License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 10 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Foundation: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Property Line: To Tank: _____ 8' To Drainfield: _____ 7'

Trench Depth: _____ 36" Trench Width: _____ 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): _____ SB2-8" Type: STD. GRAVELLESS No. of Feet: _____ 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929 _____

Owner: LA MEDIA LUNA INVESTMENTS,LLC. _____

Location: 26.255907,-98.054144,DONNA, TX 78537 _____

Legal Description: TIERRA WISCONSIN _____

Lot#: // Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3 _____
 ▪ Sq. Ft., (est.) < 2500 _____

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 12 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A..... Yes No

Porous Media Uniform (0.72-2.0 inches).....N/A..... Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 13 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Foundation: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Property Line: To Tank: _____ 8' To Drainfield: _____ 7'

Trench Depth: _____ 36" Trench Width: _____ 24'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): _____ SB2-8" Type: STD. GRAVELLESS No. of Feet: _____ 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: _____ N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: _____ JOSE A. GONZALEZ _____ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES _____ License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 14 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS, LLC.

Location: 26.255907, -98.054144, DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 15 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

- Commercial
▪ Type: _____
- Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) ≤ 2500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS, LLC.

Location: 26.255907, -98.054144, DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 14 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) ≤ 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 17 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS, LLC.

Location: 26.255907, -98.054144, DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 18 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 2500
- Other: _____
- Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928 _____

Owner: LA MEDIA LUNA INVESTMENTS,LLC. _____

Location: 26.255907,-98.054144,DONNA, TX 78537 _____

Legal Description: TIERRA WISCONSIN _____

Lot#: 19 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2500 _____

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A..... Yes No

Porous Media Uniform (0.72-2.0 inches).....N/A..... Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 20 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

- Commercial
▪ Type: _____
- Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500
- Other: _____
- Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Foundation: To Tank: _____ N/A To Drainfield: _____ N/A

Distance from Property Line: To Tank: _____ 8' To Drainfield: _____ 7'

Trench Depth: _____ 36" Trench Width: _____ 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): _____ SB2-8" Type: STD. GRAVELLESS No. of Feet: _____ 240'

Gravel Drainfield (if applicable): Natural: _____ N/A Crushed: _____ N/A Washed: _____ N/A

Amount: _____ N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: _____ JOSE A. GONZALEZ _____ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES _____ License#: OS0020831

Date of Inspection: 08/10/2023



OSSF – Form G: Inspection Report

Permit#: 54928 _____

Owner: LA MEDIA LUNA INVESTMENTS,LLC. _____

Location: 26.255907,-98.054144,DONNA, TX 78537 _____

Legal Description: TIERRA WISCONSIN _____

Lot#: 2' Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3 _____
 ▪ Sq. Ft., (est.) < 2500 _____

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 20 Block#: Section/F. Tract#:

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gal = 1,000 gal

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 2500
- Other: _____
- Vacant Lot

Drain Field: Trench: X Bed: Evapotranspiration:

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: II: X III:

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928 _____

Owner: LA MEDIA LUNA INVESTMENTS, LLC. _____

Location: 26.255907, -98.054144, DONNA, TX 78537 _____

Legal Description: TIERRA WISCONSIN _____

Lot#: 23 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

- Commercial
▪ Type: _____
- Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500
- Other: _____
- Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928 _____

Owner: LA MEDIA LUNA INVESTMENTS,LLC. _____

Location: 26.255907, -98.054144, DONNA, TX 78537 _____

Legal Description: TIERRA WISCONSIN _____

Lot#: 24 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3 _____
 ▪ Sq. Ft., (est.) < 2500 _____

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS, LLC.

Location: 26.255907, -98.054144, DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 25 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

<input type="checkbox"/> Commercial ▪ Type: _____
<input checked="" type="checkbox"/> Residential ▪ # Bedrooms: <u>3</u> ▪ Sq. Ft., (est.) < <u>2500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 24 Block#: Section/F. Tract#:

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gal = 1,000 gal

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: Evapotranspiration:

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24'

Backfill Material: Ib: II: X III:

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field: N/A Yes No

Porous Media Uniform (0.72-2.0 inches): N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928 _____

Owner: LA MEDIA LUNA INVESTMENTS, LLC. _____

Location: 26.255907, -98.054144, DONNA, TX 78537 _____

Legal Description: TIERRA WISCONSIN _____

Lot#: 27 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

<input type="checkbox"/> Commercial ▪ Type: _____
<input checked="" type="checkbox"/> Residential ▪ # Bedrooms: <u>3</u> ▪ Sq. Ft., (est.) < <u>2500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 28 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

<input type="checkbox"/> Commercial ▪ Type: _____
<input checked="" type="checkbox"/> Residential ▪ # Bedrooms: <u>3</u> ▪ Sq. Ft., (est.) <u>< 2500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS, LLC.

Location: 26.255907, -98.054144, DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 21 Block#: Section/F. Tract#:

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: Evapotranspiration:

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: II: X III:

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928

Owner: LA MEDIA LUNA INVESTMENTS, LLC.

Location: 26.255907, -98.054144, DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 30 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

<input type="checkbox"/> Commercial ▪ Type: _____
<input checked="" type="checkbox"/> Residential ▪ # Bedrooms: <u>3</u> ▪ Sq. Ft., (est.) < <u>2500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54928 _____

Owner: LA MEDIA LUNA INVESTMENTS,LLC. _____

Location: 26.255907,-98.054144,DONNA, TX 78537 _____

Legal Description: TIERRA WISCONSIN _____

Lot#: 21 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal _____

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2500 _____

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED
240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/10/2023

OSSF – Form G: Inspection Report



Permit#: 54929

Owner: LA MEDIA LUNA INVESTMENTS,LLC.

Location: 26.255907,-98.054144,DONNA, TX 78537

Legal Description: TIERRA WISCONSIN

Lot#: 32 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gal = 1,000 gal

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 8' To Drainfield: 7'

Trench Depth: 36" Trench Width: 24"

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2-8" Type: STD. GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: APPROVED

240' x 4' = 960 SQ FT INSTALLED

Inspector: JOSE G. GONZALES License#: OS0020831

Date of Inspection: 08/14/2023