



**Hidalgo County
Planning
Department**

Anthony Uresti
Director of Planning

Main Office

2818 S. Business Hwy 281
Edinburg, Texas 78542
Phone (956) 318-2840

Precinct No. 1 Substation

1900 Joe Stephens Ave. Ste. A
Weslaco, Texas 78596
Phone (956) 968-4734

Precinct No. 3 Substation

2401 N. Moorefield Road
Mission, Texas 78572
Phone (956) 205-7045

MEMORANDUM

**To: JUDGE RICHARD F. CORTEZ
COUNTY COMMISSIONER'S COURT**

From: ANTHONY URESTI, DIRECTOR OF PLANNING

Date: APRIL 30, 2024

Re: RBR NO. 5 SUBDIVISION LOTS 1-85 – PCT. 4

ON APRIL 02, 2024 THE COUNTY COMMISSIONERS COURT GRANTED FINAL APPROVAL WITH A CASH DEPOSIT FOR THE ABOVE-REFERENCED SUBDIVISION. THE CASH DEPOSIT IN THE AMOUNT OF ONE HUNDRED TWENTY SEVEN THOUSAND FIVE HUNDRED DOLLARS (\$127,500.00) WAS USED TO SECURE THE FUNDS FOR THE INSTALLATION OF EIGHTY FIVE (85) SEPTIC TANK SYSTEMS.

THE DEVELOPER IS REQUESTING THE REIMBURSEMENT OF THE CASH DEPOSIT IN THE AMOUNT OF ONE HUNDRED TWENTY SEVEN THOUSAND FIVE HUNDRED DOLLARS (\$127,500.00) WHICH REFLECTS THE INSTALLATION OF EIGHTY FIVE (85) SEPTIC TANK SYSTEMS. ATTACHED IS A LETTER FROM THE HIDALGO COUNTY HEALTH DEPARTMENT STATING THAT EIGHTY FIVE (85) SEPTIC TANKS HAVE BEEN INSTALLED, INSPECTED AND CAN BE EXPECTED TO FUNCTION SATISFACTORILY.

STAFF HAS NO OBJECTION TO THE APPROVAL FOR REIMBURSEMENT OF THE CASH DEPOSIT IN THE AMOUNT OF ONE HUNDRED TWENTY SEVEN THOUSAND FIVE HUNDRED DOLLARS (\$127,500.00) FOR THE AFOREMENTIONED IMPROVEMENT.

CASH DEPOSIT

ORIGINAL AMOUNT	\$127,500.00
REQUEST FOR 1 ST REIMBURSEMENT:	\$127,500.00
REMAINING BALANCE	\$0

***** END OF MEMORANDUM *****



**HIDALGO COUNTY
HEALTH & HUMAN SERVICES**

Ivan Melendez, MD, MBA
Health Authority/Chief Physician

Eduardo Olivarez
Chief Administrative Officer

Environmental Health Division

—MEMORANDUM—

April 17, 2024


Hidalgo County Planning Department
2818 S Bus Hwy 281
Edinburg, TX 78539

**OSSF UPDATE
RBR SUBDIVISION NO. 5
LOTS 1-85**

To whom it may concern,

Our records indicate that eighty-five (85) OSSF Systems have been installed, inspected, and approved at RBR SUBDIVISION NO. 5 (Lots 1-85). The OSSF Systems can be expected to function at a satisfactory level.

Sincerely,


Niko Ross A. Tapanan, MPH, RS
Public Health Sanitarian
TCEQ Designated Representative (#OS0035768)

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 1 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-2024

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 2 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 3 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/>	Commercial
	▪ Type: _____
<input checked="" type="checkbox"/>	Residential
	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/>	Other: _____
<input checked="" type="checkbox"/>	Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A Yes No

Porous Media Uniform (0.72-2.0 inches).....N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 4 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/>	Commercial
	▪ Type: _____
<input checked="" type="checkbox"/>	Residential
	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/>	Other: _____
<input checked="" type="checkbox"/>	Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 5 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/>	Commercial
	▪ Type: _____
<input checked="" type="checkbox"/>	Residential
	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/>	Other: _____
<input checked="" type="checkbox"/>	Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 6 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 7 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 8 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 9 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24

OSSF – Form G: Inspection Report



Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 10 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-24



OSSF – Form G: Inspection Report

Permit#: 55251

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: // Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/>	Commercial
	▪ Type: _____
<input checked="" type="checkbox"/>	Residential
	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/>	Other: _____
<input checked="" type="checkbox"/>	Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-10-2024

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 12 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-12-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 13 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-12-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 14 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-12-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 15 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 2,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-12-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 16 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290
 Owner: RBR DEVELOPMENT AND INVESTMENTS
 Location: 26.278125, -98.089624, EDINBURG, TX 78542
 Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 17 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	Type: _____
<input checked="" type="checkbox"/> Residential	# Bedrooms: <u>3</u>
	Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 18 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 19 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 20 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 21 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 22 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/>	Commercial
▪	Type: _____
<input checked="" type="checkbox"/>	Residential
▪	# Bedrooms: <u>3</u>
▪	Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/>	Other: _____
<input checked="" type="checkbox"/>	Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well:** To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290
Owner: RBR DEVELOPMENT AND INVESTMENTS
Location: 26.278125, -98.089624, EDINBURG, TX 78542
Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 23 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 24 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 25 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 26 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial ▪ Type: _____
<input checked="" type="checkbox"/> Residential ▪ # Bedrooms: <u>3</u> ▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24

OSSF – Form G: Inspection Report



Permit#: 55290
 Owner: RBR DEVELOPMENT AND INVESTMENTS
 Location: 26.278125, -98.089624, EDINBURG, TX 78542
 Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 27 Block#: _____ Section/F. Tract#: _____
 Tank Type: _____ CONCRETE
 Inside Diameter: _____ 5'
 Inside Length of Sides: _____ 5'
 Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"
 Airspace (approx.): _____ 3"
 Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____
 Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2,500
 Other: _____
 Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____
 Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A
 Distance from Foundation: To Tank: N/A To Drainfield: N/A
 Distance from Property Line: To Tank: 10' To Drainfield: 8'
 Trench Depth: 30" Trench Width: 2'
 Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A
 Amount: N/A Yards or Tons
 Gravel Generally Consistent 12" depth throughout field N/A Yes No
 Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:
 Solid Lines from House Schedule 40 with Cleanout N/A Yes No
 T's Installed at least 25% of Liquid Level Yes No
 Inlet and Outlet Flow Clearly Marked Yes No
 Manufacturer's Name, Address, & Tank Capacity Visible Yes No
 Port Holes 12" in Diameter Yes No
 Septic Tank Sturdy & Water-Tight Yes No
 Trench or Bed Bottom Essentially Level Yes No
 Perforated Pipe Generally Level throughout Field Yes No
 End Caps provided on Drainfield (if not looped) Yes No
 Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24



OSSF – Form G: Inspection Report

Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 28 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24

OSSF – Form G: Inspection Report



Permit#: 55298

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 29 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24

OSSF – Form G: Inspection Report



Permit#: 55308

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 30 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 2,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-2024

OSSF – Form G: Inspection Report



Permit#: 55308

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 31 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 2,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 32 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANAN License#: 35768

Date of Inspection: 4-17-2024

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 33 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-2024

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 34 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	Type: _____
<input checked="" type="checkbox"/> Residential	# Bedrooms: <u>3</u>
	Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A Yes No

Porous Media Uniform (0.72-2.0 inches).....N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-2024

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 35 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 36 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED


Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-17-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 37 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A Yes No

Porous Media Uniform (0.72-2.0 inches).....N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 38 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 39 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 40 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24



OSSF – Form G: Inspection Report

Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 41 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals _____

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 42 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24



OSSF – Form G: Inspection Report

Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 43 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 44 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 45 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 46 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 47 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 48 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24



OSSF – Form G: Inspection Report

Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 49 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55290

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 50 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 51 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 52 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 53 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 54 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 55 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED


Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55158
 Owner: RBR DEVELOPMENT AND INVESTMENTS
 Location: 26.278125, -98.089624, EDINBURG, TX 78542
 Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 56 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-21

OSSF – Form G: Inspection Report



Permit#: 55158

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 57 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 58 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 59 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 60 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 61 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-18-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 62 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 63 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 64 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 65 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals _____

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 66 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED


Must provide proof of connection when requesting utilities

APPROVED _____

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 67 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 68 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-21

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 69 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 70 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 71 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 3-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 72 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other:	_____
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 73 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 74 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-1-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 75 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE _____

Inside Diameter: _____ 5' _____

Inside Length of Sides: _____ 5' _____

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48" _____

Airspace (approx.): _____ 3" _____

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals _____

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: X Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: X III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 76 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 77 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 78 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 79 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 80 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 81 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 82 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 83 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>< 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

OSSF – Form G: Inspection Report



Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 84 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 1350


Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24



OSSF – Form G: Inspection Report

Permit#: 55261

Owner: RBR DEVELOPMENT AND INVESTMENTS

Location: 26.278125, -98.089624, EDINBURG, TX 78542

Legal Description: RBR NO. 5 SUBDIVISION

Lot#: 85 Block#: _____ Section/F. Tract#: _____

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 2,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 1350

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

Must provide proof of connection when requesting utilities

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 4-19-24

Acct. # - 1100-211-00-000-018-0-000
OSSF
Price: \$1500.00
Quantity: 85

Hidalgo County Planning Department

2/16/2024
11:49:18 AM

Main Office 2818 S Business Hwy 281 Edinburg, Texas 78539 Ph: 956-318-2840 Fax: 956-318-2844	Precinct No. 1 Substation 1900 Joe Stephens Ave. Ste. A Westaco, Texas 78596 Ph: 956-968-4734 Fax: 956-973-7850	Precinct No. 3 Substation 2401 N. Moorefield Rd. Mission, Texas 78572 Ph: 956-205-7045 Fax: 956-205-7049
--	---	--

RBR DEVELOPMENT & INV., LLC.


Received of

RBR NO. 5 SUBDIVISION

Subdivision

flor.sesin

Prepared by



Received by

Total Amount: \$127500.00
Method of Payment: Check
Check/M.O.#: 2057
Payment: \$127500.00
Change Due: \$0.00



Main Office
Receipt No. 033574