



**Hidalgo County  
Planning  
Department**

**Anthony Uresti**  
*Director of Planning*

**Main Office**

2818 S. Business Hwy 281  
Edinburg, Texas 78542  
Phone (956) 318-2840

**Precinct No. 1 Substation**

1900 Joe Stephens Ave. Ste. A  
Weslaco, Texas 78596  
Phone (956) 968-4734

**Precinct No. 3 Substation**

2401 N. Moorefield Road  
Mission, Texas 78572  
Phone (956) 205-7045

**MEMORANDUM**

**To: JUDGE RICHARD F. CORTEZ  
COUNTY COMMISSIONER'S COURT**

**From: ANTHONY URESTI DIRECTOR OF PLANNING**

**Date: SEPTEMBER 27, 2024**

**Re: CARMEN AVILA SUBDIVISION PHASE IV – PCT. 4**

---

ON MARCH 05, 2024, THE HIDALGO COUNTY COMMISSIONERS COURT GRANTED FINAL APPROVAL WITH FINANCIAL GUARANTEE FOR THE ABOVE REFERENCED SUBDIVISION WHICH CONSISTS OF NINETY SIX (96) SINGLE FAMILY LOTS. THE CASH DEPOSIT IN THE AMOUNT OF ONE HUNDRED FORTY FOUR THOUSAND DOLLARS (\$144,000.00) WAS USED TO SECURE THE FUNDS FOR THE INSTALLATION OF NINETY SIX (96) SEPTIC TANK SYSTEMS.

THE DEVELOPER IS REQUESTING THE FULL REIMBURSEMENT OF ONE HUNDRED FORTY FOUR THOUSAND DOLLARS (\$144,000.00) FROM THE CASH DEPOSIT WHICH REFLECTS THE INSTALLATION OF NINETY SIX (96) SINGLE FAMILY SEPTIC TANK SYSTEMS. ATTACHED IS A LETTER FROM HIDALGO COUNTY HEALTH DEPARTMENT STATING THAT NINETY SIX (96) SEPTIC TANK SYSTEMS HAVE BEEN INSTALLED, INSPECTED AND CAN BE EXPECTED TO FUNCTION SATISFACTORILY.

STAFF HAS NO OBJECTION TO THE APPROVAL FOR REIMBURSEMENT OF THE CASH DEPOSIT IN THE AMOUNT OF ONE HUNDRED FORTY FOUR THOUSAND DOLLARS (\$144,000.00) FOR THE AFOREMENTIONED IMPROVEMENT.

**CASH DEPOSIT**

ORIGINAL AMOUNT	\$144,000.00
REIMBURSEMENT REQUEST	\$144,000.00

REMAINING BALANCE AFTER APPROVAL:  
\$0

**\*\*\* END OF MEMORANDUM \*\*\***

Acct. # - 1100-211-00-000-018-0-000  
OSSF  
Price: \$1500.00  
Quantity: 96

### Hidalgo County Planning Department

2/9/2024  
9:47:53 AM

Main Office 2818 S Business Hwy 281 Edinburg, Texas 78539 Ph: 956-318-2840 Fax: 956-318-2844	Precinct No. 1 Substation 1900 Joe Stephens Ave. Ste. A Westlaco, Texas 78596 Ph: 956-968-4734 Fax: 956-973-7850	Precinct No. 3 Substation 2401 N. Moorefield Rd. Mission, Texas 78572 Ph: 956-205-7045 Fax: 956-205-7049
--	--	--

#### CARMEN AVILA SUBDIVISION PHASE 4 & 5 LLC.

Received of

#### CARMEN AVILA SUBDIVISION PHASE IV

Subdivision

**flor.sesin**

Prepared by



Received by

Total Amount: \$144000.00  
Method of Payment: Check  
Check/M.O.#: 1030  
Payment: \$144000.00  
Change Due: \$0.00



Main Office  
Receipt No. 033467

THE FACE OF THIS DOCUMENT HAS A COLORED BACKGROUND ON WHITE PAPER AND ORIGINAL DOCUMENT SECURITY SCREEN ON BACK WITH PADLOCK SECURITY ICON.

Carmen Avila Subdivision phase 4 & 5 LLC

88-2332/1149

1030

**PAY TO THE ORDER OF** Hidalgo County

DATE 02/07/24

\$ 144,000

(One hundred forty-four thousand and 00/100)

DOLLARS

Freedom Bank

MEMO Septic tank escrow CAPH 4



  
AUTHORIZED SIGNATURE

Security features included. Details on back.



**HIDALGO COUNTY  
HEALTH & HUMAN SERVICES**

*Ivan Melendez, MD, MBA*  
*Health Authority/Chief Physician*

*Eduardo Olivarez*  
*Chief Administrative Officer*

***Environmental Health Division***

**—MEMORANDUM—**

September 17, 2024

Hidalgo County Planning Department  
2818 S Bus Hwy 281  
Edinburg, TX 78539

**OSSF UPDATE  
CARMEN AVILA PH. IV SUBDIVISION  
LOTS 1-96**

To whom it may concern,

Our records indicate that ninety-six (96) OSSF Septic Systems have been installed, inspected, and approved at Carmen Avila Ph. IV Subdivision (Lots 1-96). The OSSFs can be expected to function at a satisfactory level.

Sincerely,

Niko Ross A. Tarangan, MPH, RS  
Public Health Sanitarian  
TCEQ Designated Representative (#OS0035768)

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 404 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 405 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 406 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 407 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial ▪ Type: _____
<input checked="" type="checkbox"/> Residential ▪ # Bedrooms: <u>3</u> ▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 408 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE \_\_\_\_\_

Inside Diameter: \_\_\_\_\_ 5' \_\_\_\_\_

Inside Length of Sides: \_\_\_\_\_ 5' \_\_\_\_\_

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48" \_\_\_\_\_

Airspace (approx.): \_\_\_\_\_ 3" \_\_\_\_\_

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals \_\_\_\_\_

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 409 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 410 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 5'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55528

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 411 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-28-2024

# OSSF – Form G: Inspection Report



Permit#: 55528

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 412 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-28-2024

# OSSF – Form G: Inspection Report



Permit#: 55528

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 413 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-28-2024

# OSSF – Form G: Inspection Report



Permit#: 55528

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 414 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: \_\_\_\_\_ L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-28-2024

# OSSF – Form G: Inspection Report



Permit#: 55528

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 415 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-28-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 416 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 417 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

## General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 418 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 419 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 420 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench: X Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II: X III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 421 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 422 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

**Commercial**  
▪ Type: \_\_\_\_\_

**Residential**  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

**Other:** \_\_\_\_\_

**Vacant Lot**

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 423 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 424 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 425 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 426 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 427 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

## General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 428 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55449

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 429 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-08-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 430 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 731 Block#: Section/F. Tract#:

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench: X Bed: Evapotranspiration:

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: II: X III:

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A  Yes  No

Porous Media Uniform (0.72-2.0 inches) N/A  Yes  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout N/A  Yes  No

T's Installed at least 25% of Liquid Level  Yes  No

Inlet and Outlet Flow Clearly Marked  Yes  No

Manufacturer's Name, Address, & Tank Capacity Visible  Yes  No

Port Holes 12" in Diameter  Yes  No

Septic Tank Sturdy & Water-Tight  Yes  No

Trench or Bed Bottom Essentially Level  Yes  No

Perforated Pipe Generally Level throughout Field  Yes  No

End Caps provided on Drainfield (if not looped)  Yes  No

Geo-Textile Fabric used for Permeable Soil Barrier  Yes  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 432 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level..... Yes .....  No

Inlet and Outlet Flow Clearly Marked..... Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes .....  No

Port Holes 12" in Diameter..... Yes .....  No

Septic Tank Sturdy & Water-Tight..... Yes .....  No

Trench or Bed Bottom Essentially Level..... Yes .....  No

Perforated Pipe Generally Level throughout Field..... Yes .....  No

End Caps provided on Drainfield (if not looped)..... Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 433 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 16' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 434 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level..... Yes .....  No

Inlet and Outlet Flow Clearly Marked..... Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes .....  No

Port Holes 12" in Diameter..... Yes .....  No

Septic Tank Sturdy & Water-Tight..... Yes .....  No

Trench or Bed Bottom Essentially Level..... Yes .....  No

Perforated Pipe Generally Level throughout Field..... Yes .....  No

End Caps provided on Drainfield (if not looped)..... Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 435 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 436 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 437 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level..... Yes .....  No

Inlet and Outlet Flow Clearly Marked..... Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes .....  No

Port Holes 12" in Diameter..... Yes .....  No

Septic Tank Sturdy & Water-Tight..... Yes .....  No

Trench or Bed Bottom Essentially Level..... Yes .....  No

Perforated Pipe Generally Level throughout Field..... Yes .....  No

End Caps provided on Drainfield (if not looped)..... Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes .....  No

Installer: \_\_\_\_\_ L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 438 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55489

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 439 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

## General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55490

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 440 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55490

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 441 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55490

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 442 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55490

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 443 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55490

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 444 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55490

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 445 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II: X III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55490

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 446 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level..... Yes .....  No

Inlet and Outlet Flow Clearly Marked..... Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes .....  No

Port Holes 12" in Diameter..... Yes .....  No

Septic Tank Sturdy & Water-Tight..... Yes .....  No

Trench or Bed Bottom Essentially Level..... Yes .....  No

Perforated Pipe Generally Level throughout Field..... Yes .....  No

End Caps provided on Drainfield (if not looped)..... Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-06-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 447 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 448 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 449 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 450 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial  
▪ Type: \_\_\_\_\_
- Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench: X Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II: X III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 451 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 452 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 453 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 454 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 455 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55507

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 456 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-19-2024

# OSSF – Form G: Inspection Report



Permit#: 55521

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 457 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 08-23-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 458 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE \_\_\_\_\_

Inside Diameter: \_\_\_\_\_ 5' \_\_\_\_\_

Inside Length of Sides: \_\_\_\_\_ 5' \_\_\_\_\_

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48" \_\_\_\_\_

Airspace (approx.): \_\_\_\_\_ 3" \_\_\_\_\_

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals \_\_\_\_\_

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024



# OSSF – Form G: Inspection Report

Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 459 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
 ▪ Type: \_\_\_\_\_

Residential  
 ▪ # Bedrooms: 3  
 ▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 460 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 461 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 462 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 463 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 464 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 465 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 466 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 467 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024



# OSSF – Form G: Inspection Report

Permit#: 55429

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 468 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

**General Conditions and Workmanship:**

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55429

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 469 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55429

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 470 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II: X III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55429

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 471 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE \_\_\_\_\_

Inside Diameter: \_\_\_\_\_ 5' \_\_\_\_\_

Inside Length of Sides: \_\_\_\_\_ 5' \_\_\_\_\_

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48" \_\_\_\_\_

Airspace (approx.): \_\_\_\_\_ 3" \_\_\_\_\_

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals \_\_\_\_\_

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench: X Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II: X III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55429

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 472 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55429

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 473 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55429

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 474 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
▪ Type: \_\_\_\_\_

Residential  
▪ # Bedrooms: 3  
▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench: X Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II: X III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 475 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 476 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 477 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: \_\_\_\_\_ L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55456

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 478 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field.....N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches).....N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout.....N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-12-2024

# OSSF – Form G: Inspection Report



Permit#: 55442

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 479 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial	▪ Type: _____
<input checked="" type="checkbox"/> Residential	▪ # Bedrooms: <u>3</u>
	▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____	
<input checked="" type="checkbox"/> Vacant Lot	

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55442

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 480 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_  
Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A  
Distance from Foundation: To Tank: N/A To Drainfield: N/A  
Distance from Property Line: To Tank: 10' To Drainfield: 8'  
Trench Depth: 30" Trench Width: 2'  
Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A  
Amount: N/A Yards or Tons  
Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No  
Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

General Conditions and Workmanship:  
Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No  
T's Installed at least 25% of Liquid Level .....  Yes .....  No  
Inlet and Outlet Flow Clearly Marked .....  Yes .....  No  
Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No  
Port Holes 12" in Diameter .....  Yes .....  No  
Septic Tank Sturdy & Water-Tight .....  Yes .....  No  
Trench or Bed Bottom Essentially Level .....  Yes .....  No  
Perforated Pipe Generally Level throughout Field .....  Yes .....  No  
End Caps provided on Drainfield (if not looped) .....  Yes .....  No  
Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55442

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 481 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55442

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 482 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55442

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 483 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55442

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 484 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED


MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55442

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 485 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 07-02-2024

# OSSF – Form G: Inspection Report



Permit#: 55374

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 486 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE \_\_\_\_\_

Inside Diameter: \_\_\_\_\_ 5' \_\_\_\_\_

Inside Length of Sides: \_\_\_\_\_ 5' \_\_\_\_\_

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48" \_\_\_\_\_

Airspace (approx.): \_\_\_\_\_ 3" \_\_\_\_\_

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals \_\_\_\_\_

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-10-2024

# OSSF – Form G: Inspection Report



Permit#: 55374

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 487 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE \_\_\_\_\_

Inside Diameter: \_\_\_\_\_ 5' \_\_\_\_\_

Inside Length of Sides: \_\_\_\_\_ 5' \_\_\_\_\_

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48" \_\_\_\_\_

Airspace (approx.): \_\_\_\_\_ 3" \_\_\_\_\_

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals \_\_\_\_\_

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-10-2024

# OSSF – Form G: Inspection Report



Permit#: 55354

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 488 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  X Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  X III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-03-2024



# OSSF – Form G: Inspection Report

Permit#: 55354

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 489 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
 ▪ Type: \_\_\_\_\_

Residential  
 ▪ # Bedrooms: 3  
 ▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-03-2024



# OSSF – Form G: Inspection Report

Permit#: 55354

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 490 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

Commercial  
 ▪ Type: \_\_\_\_\_

Residential  
 ▪ # Bedrooms: 3  
 ▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-03-2024

# OSSF – Form G: Inspection Report



Permit#: 55354

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 491 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-03-2024



# OSSF – Form G: Inspection Report

Permit#: 55354

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 492 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1.000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-03-2024



# OSSF – Form G: Inspection Report

Permit#: 55354

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 493 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED


MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-03-2024

# OSSF – Form G: Inspection Report



Permit#: 55354

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 494 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

Commercial  
 ▪ Type: \_\_\_\_\_

Residential  
 ▪ # Bedrooms: 3  
 ▪ Sq. Ft., (est.) < 2,500

Other: \_\_\_\_\_

Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-03-2024

# OSSF – Form G: Inspection Report



Permit#: 55374

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 495 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-10-2024

# OSSF – Form G: Inspection Report



Permit#: 55374

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 496 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-10-2024

# OSSF – Form G: Inspection Report



Permit#: 55374

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 497 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE

Inside Diameter: \_\_\_\_\_ 5'

Inside Length of Sides: \_\_\_\_\_ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48"

Airspace (approx.): \_\_\_\_\_ 3"

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-10-2024

# OSSF – Form G: Inspection Report



Permit#: 55374

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 498 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: \_\_\_\_\_ CONCRETE \_\_\_\_\_

Inside Diameter: \_\_\_\_\_ 5' \_\_\_\_\_

Inside Length of Sides: \_\_\_\_\_ 5' \_\_\_\_\_

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: \_\_\_\_\_ 48" \_\_\_\_\_

Airspace (approx.): \_\_\_\_\_ 3" \_\_\_\_\_

Gallon Cap. (approx.): \_\_\_\_\_ 2 x 500gals = 1,000gals \_\_\_\_\_

<input type="checkbox"/> Commercial
▪ Type: _____
<input checked="" type="checkbox"/> Residential
▪ # Bedrooms: <u>3</u>
▪ Sq. Ft., (est.) <u>&lt; 2,500</u>
<input type="checkbox"/> Other: _____
<input checked="" type="checkbox"/> Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from Private/Public Well: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field ..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches) ..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout ..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level .....  Yes .....  No

Inlet and Outlet Flow Clearly Marked .....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible .....  Yes .....  No

Port Holes 12" in Diameter .....  Yes .....  No

Septic Tank Sturdy & Water-Tight .....  Yes .....  No

Trench or Bed Bottom Essentially Level .....  Yes .....  No

Perforated Pipe Generally Level throughout Field .....  Yes .....  No

End Caps provided on Drainfield (if not looped) .....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier .....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-10-2024

# OSSF – Form G: Inspection Report



Permit#: 55374

Owner: VICTOR DANIEC

Location: 26.396940, -98.088967, EDINBURG, TX 78542

Legal Description: CARMEN AVILA PH. IV

Lot#: 499 Block#: \_\_\_\_\_ Section/F. Tract#: \_\_\_\_\_

Tank Type: CONCRETE

Inside Diameter: 5'

Inside Length of Sides: 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: 48"

Airspace (approx.): 3"

Gallon Cap. (approx.): 2 x 500gals = 1,000gals

- Commercial
  - Type: \_\_\_\_\_
- Residential
  - # Bedrooms: 3
  - Sq. Ft., (est.) < 2,500
- Other: \_\_\_\_\_
- Vacant Lot

Drain Field: Trench:  Bed: \_\_\_\_\_ Evapotranspiration: \_\_\_\_\_

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 10' To Drainfield: 8'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: \_\_\_\_\_ II:  III: \_\_\_\_\_

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A  Yes .....  No

Porous Media Uniform (0.72-2.0 inches)..... N/A  Yes .....  No

### General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... N/A  Yes .....  No

T's Installed at least 25% of Liquid Level.....  Yes .....  No

Inlet and Outlet Flow Clearly Marked.....  Yes .....  No

Manufacturer's Name, Address, & Tank Capacity Visible.....  Yes .....  No

Port Holes 12" in Diameter.....  Yes .....  No

Septic Tank Sturdy & Water-Tight.....  Yes .....  No

Trench or Bed Bottom Essentially Level.....  Yes .....  No

Perforated Pipe Generally Level throughout Field.....  Yes .....  No

End Caps provided on Drainfield (if not looped).....  Yes .....  No

Geo-Textile Fabric used for Permeable Soil Barrier.....  Yes .....  No

Installer: L. BAZAN License#: 36943

Remarks: 240' x 4' = 960 sq. ft. RISERS INSTALLED

MUST PROVIDE PROOF OF CONNECITON WHEN REQ. UTILITIES

APPROVED

Inspector: N. TAPANGAN License#: 35768

Date of Inspection: 05-10-2024