




# POSTAL MONEY ORDER

Serial Number  
29744104342

785570 Office U.S. Dollars and Cents

Amount  
One Thousand Dollars and 00/100 \*\*\*\*\*  
\$1000.00

Pay to Hidalgo County  
Address 9805 N. 10th St.  
McAllen, Tx. 78504  
Memo Settlement



From Joel Quirino  
Address 7720 W. mile 6 Rd.  
Mission, Tx. 78574

Clerk 04

SEE REVERSE WARNING • NEGOTIABLE ONLY IN THE U.S. AND POSSESSIONS

⑆000008002⑆

29744104342⑆




# POSTAL MONEY ORDER

Serial Number  
29744104353

785570 Office U.S. Dollars and Cents

Amount  
Five Hundred Dollars and 00/100 \*\*\*\*\*  
\$500.00

Pay to Hidalgo County  
Address 9805 N. 10th St.  
McAllen, Tx. 78504  
Memo Settlement



From Joel Quirino  
Address 7720 W. mile 6 Rd.  
Mission, Tx. 78574

Clerk 04

SEE REVERSE WARNING • NEGOTIABLE ONLY IN THE U.S. AND POSSESSIONS

⑆000008002⑆

29744104353⑆

Est ID: 310  
Serial No:  
Status: Preliminary

Date: 06.10.2024  
Time: 10:21:14

# ER Paint Shop

2420 west Montecristo rd.  
Edinburg Texas 78541  
(956)386-0008 Fax: (956)289-1939  
Email: eloytrevino2@outlook.com  
Tax Id No: 05-0548446

## ESTIMATE

Written By ER PAINT SHOP & MECHANICS

#1188

### ADMIN INFORMATION

sheriff dept

OWNER

sheriff dept

Phone:  
: 956-383-8114  
: . . .  
: . . .

#### LOSS DATA

Veh Condition:  
Type of Loss:  
Point of Impact:  
Days To Repair:

#### INSURANCE

Insured:  
Ins Co:  
Adjuster:  
Phone: . . . x  
Claim No:  
Policy No:  
Date of Loss: . . .

### VEHICLE INFORMATION

2023 FORD Explorer Police 4WD

VIN: 1FM5K8AB1PGB56155  
Colour: Clear Coat

Prod Date:  
Engine: '3.3-L V-6 DOHC 24V

Lic Plate:  
Odometer: 0

### LINE ITEM DETAILS

Line	Description	Material	Price	Quantity	Total
<b>FRONT BUMPER</b>					
1	Overhaul	Front Bumper O/H			3.5
2	Repair	Bumper Cover			3.0
3	Replace 1	Bumper Lic Plate Brkt			2.8 *
4			New 38.00		0.4
5	R&i	brush gaurd			2.5
6	Repair	brush gaurg			6.0
<b>GRILLE</b>					
7	R&i	Grille			0.8
<b>FRONT LAMPS</b>					
8	R&i	Lt Combination Lamp Assy			0.9

Continued on the Next Page. . .

Est ID: 310  
Lic No:  
Status: Preliminary

Date: No  
Time: 10:21

**ER Paint Shop**  
sheriff dept 2023 FORD Explorer Po

**ESTIMATE**

LINE ITEM DETAILS				
9	R&I	Rt Combination Lamp Assy		0.9
10	Repair	HOOD		
11		Hood Clear Coat	4.0	3.0*
Line Totals ->			38.00	22.0 8.8

Continued on the Next Page...

Est ID: 310  
Lic No:  
Status: Preliminary

Date: No  
Time: 10:21

**ER Paint Shop**  
sheriff dept 2023 FORD Explorer Po

**ESTIMATE**

		FINAL SUMMARY TOTALS				
<b>LABOR:</b>						
Body	22.0	Hrs @	68.00	Per Hour	=	1496.00
Refinish	8.8	Hrs @	68.00	Per Hour	=	598.40
Frame/Structural	0.0	Hrs @	85.00	Per Hour	=	
Mechanical	0.0	Hrs @	165.00	Per Hour	=	
<b>PARTS &amp; MATERIAL:</b>						
Parts					=	38.00
Paint Material/Supplies	8.8	Hrs @	50.00	Per Hour	=	440.00
Body Material	13.4	Hrs @	15.00	Per Hour	=	201.00
<b>OTHER CHARGES:</b>						
Hazardous Waste Removal					=	15.00
<b>SUBTOTAL</b>						= 2,788.40
Sales Tax on	0.00				=	0.00
<b>TOTAL</b>						\$ 2,788.40

**- NOTICE -**

This estimate report is based upon our visual inspection and includes only the items listed on this report for repairs. Occassionly, after repair work is started, hidden or missed damage is found and additional costs may be necessary. All parts prices subject to actual invoice. This estimate report is valid for 60 days.

I hereby authorize repairs to my vehicle for the amount of this estimate.

Signed: \_\_\_\_\_ Date: \_\_\_\_\_

(c) 2020 ABF SYSTEMS, INC.

ABF Estimating Solutions from www.abfsystems.com