



**Hidalgo County
Planning
Department**

Anthony Uresti
Director of Planning

Main Office

2818 S. Business Hwy 281
Edinburg, Texas 78542
Phone (956) 318-2840
Fax (956) 318-2844

Precinct No. 1 Substation

1900 Joe Stephens Ave. Ste. A
Weslaco, Texas 78596
Phone (956) 968-4734
Fax (956) 973-7850

Precinct No. 3 Substation

2401 N. Moorefield Road
Mission, Texas 78572
Phone (956) 205-7045
Fax (956) 205-7049

MEMORANDUM

**To: JUDGE RICHARD F. CORTEZ
COUNTY COMMISSIONER'S COURT**

From: ANTHONY URESTI DIRECTOR OF PLANNING

Date: OCTOBER 01, 2025

Re: MARAVILLAS ESTATES PHASE 4 SUBDIVISION – PCT. 1

ON APRIL 29, 2025, THE HIDALGO COUNTY COMMISSIONERS COURT GRANTED FINAL APPROVAL WITH FINANCIAL GUARANTEE FOR THE ABOVE REFERENCED SUBDIVISION WHICH CONSISTS OF EIGHTY SEVEN (87) SINGLE FAMILY LOTS. THE CASH DEPOSIT IN THE AMOUNT OF NINETY FOUR THOUSAND FIVE HUNDRED DOLLARS (\$94,500.00) WAS USED TO SECURE THE FUNDS FOR THE INSTALLATION OF SIXTY THREE (63) SEPTIC TANK SYSTEMS.

THE DEVELOPER IS REQUESTING THE FULL REIMBURSEMENT OF NINETY FOUR THOUSAND FIVE HUNDRED DOLLARS (\$94,500.00) FROM THE CASH DEPOSIT WHICH REFLECTS THE INSTALLATION OF SIXTY THREE (63) SINGLE FAMILY SEPTIC TANK SYSTEMS. ATTACHED IS A LETTER FROM HIDALGO COUNTY HEALTH DEPARTMENT STATING THAT EIGHTY SEVEN (87) SEPTIC TANK SYSTEMS HAVE BEEN INSTALLED, INSPECTED AND CAN BE EXPECTED TO FUNCTION SATISFACTORILY.

STAFF HAS NO OBJECTION TO THE APPROVAL FOR REIMBURSEMENT OF THE CASH DEPOSIT IN THE AMOUNT OF NINETY FOUR THOUSAND FIVE HUNDRED DOLLARS (\$94,500.00) FOR THE AFOREMENTIONED IMPROVEMENT.

CASH DEPOSIT

ORIGINAL AMOUNT \$ 94,500.00

FIRST REIMBURSEMENT \$ 94,500.00
REQUEST:

REMAINING BALANCE AFTER APPROVAL:
\$ 0

***** END OF MEMORANDUM *****

Acct. # - 1100-211-00-000-018-0-000
OSSF
Price: \$1500.00
Quantity: 63

Hidalgo County Planning Department

4/3/2025
11:50:12 AM

Main Office	Precinct No. 1 Substation	Precinct No. 3 Substation
2818 S Business Hwy 281 Edinburg, Texas 78539	1900 Joe Stephens Ave. Ste. A Weslaco, Texas 78596	2401 N. Moorefield Rd. Mission, Texas 78572
Ph: 956-318-2840	Ph: 956-968-4734	Ph: 956-205-7045
Fax: 956-318-2844	Fax: 956-973-7850	Fax: 956-205-7049

HANI DIORA, LLC.


Received of

MARAVILLAS ESTATES PHASE 4 SUBDIVISION

Subdivision

flor.sesin

Prepared by



Received by

Total Amount: \$94500.00
Method of Payment: Check
Check/M.O.#: 00020
Payment: \$94500.00
Change Due: \$0.00



Main Office
Receipt No. 039864

HANI DIORA LLC
612 W. Nolana Ave., Ste 570A
McAllen TX 78504
(956) 682-8024

Rio BANK
Main Banking Center
P.O. BOX 4169
McALLEN, TEXAS 78502
88-1544/1149



DATE
Apr 2, 2025


AMOUNT
**\$94,500.00

PAY

Ninety-Four Thousand Five Hundred and 00/100 Dollars

TO THE
ORDER
OF:

Hidalgo County Planning Department



AUTHORIZED SIGNATURE

⑈000020⑈ ⑆114915447⑆ 64509855⑈





Hidalgo County Health & Human Services Department

Dairen Sarmiento Rangel, M.B.A.
Director

MEMORANDUM

September 15, 2025

Hidalgo County Planning Department
2818 S. Bus. Hwy 281
Edinburg, TX 78539

OSSF UPDATE MARAVILLAS ESTATES PHASE 4 SUBDIVISION LOTS 1-87

To whom it may concern,

Our records indicate that eighty-seven (87) OSSF Septic Systems have been installed, inspected, and approved at Maravillas Estates Phase 4 Subdivision (Lots 1-87). The OSSFs can be expected to function at a satisfactory level.

Sincerely,

Alberto Flores, RS
Public Health Sanitarian
TCEQ Designated Representative (#OS0038768)

Environmental Health Division
2818 S. Bus. Hwy 281, Door 7
Edinburg, TX 78536
956-383-0111

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 1 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 2 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 3 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 4 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 5 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 6 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 7 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 8 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 9 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 10 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 11 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 12 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 13 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 14 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 15 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/11/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 16 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 17 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 18 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 19 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 20 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 21 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 22 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 23 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 24 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 25 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 26 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 27 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 28 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 29 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55788

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 30 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/26/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 31 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 32 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 33 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 34 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 35 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 36 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 37 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 38 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 39 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 40 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 55782

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 41 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 02/24/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 42 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 43 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 44 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 45 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 46 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 47 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 48 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 49 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 50 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 51 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 52 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 53 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 54 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 55 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... V/L Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 56080

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 56 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 09/12/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 57 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... V/L Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 58 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... V/L Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 59 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 60 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 61 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 62 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 63 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 64 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 65 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 66 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... V/L Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 67 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 68 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 69 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 70 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 71 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 72 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55876

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 73 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 05/05/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 74 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 75 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... V/L Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 76 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial

▪ Type: _____

Residential

▪ # Bedrooms: 3

▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 77 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 78 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 79 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 80 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

- Commercial
 - Type: _____
- Residential
 - # Bedrooms: 3
 - Sq. Ft., (est.) < 1,500
- Other: _____
- Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 81 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... V/L Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 82 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 83 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field..... N/A Yes No

Porous Media Uniform (0.72-2.0 inches)..... N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout..... V/L Yes No

T's Installed at least 25% of Liquid Level..... Yes No

Inlet and Outlet Flow Clearly Marked..... Yes No

Manufacturer's Name, Address, & Tank Capacity Visible..... Yes No

Port Holes 12" in Diameter..... Yes No

Septic Tank Sturdy & Water-Tight..... Yes No

Trench or Bed Bottom Essentially Level..... Yes No

Perforated Pipe Generally Level throughout Field..... Yes No

End Caps provided on Drainfield (if not looped)..... Yes No

Geo-Textile Fabric used for Permeable Soil Barrier..... Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 84 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 85 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
 ▪ Type: _____

Residential
 ▪ # Bedrooms: 3
 ▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 86 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025

OSSF – Form G: Inspection Report



Permit#: 55812

Owner: HANI DIORA LLC.

Location: _____

Legal Description: MARAVILLAS ESTATES PH.4

Lot#: 87 Block#: _____ Section/F. Tract#: _____

Tank Type: _____ CONCRETE

Inside Diameter: _____ 5'

Inside Length of Sides: _____ 5'

Liq. Depths or Dist. From Tank Bottom to Outlet Bottom: _____ 48"

Airspace (approx.): _____ 3"

Gallon Cap. (approx.): _____ 2 x 500gals = 1,000gals

Commercial
▪ Type: _____

Residential
▪ # Bedrooms: 3
▪ Sq. Ft., (est.) < 1,500

Other: _____

Vacant Lot

Drain Field: Trench: Bed: _____ Evapotranspiration: _____

Distance from **Private/Public Well**: To Tank: N/A To Drainfield: N/A

Distance from Foundation: To Tank: N/A To Drainfield: N/A

Distance from Property Line: To Tank: 11' To Drainfield: 9'

Trench Depth: 30" Trench Width: 2'

Backfill Material: Ib: _____ II: III: _____

Pipe: Brand (if known): SB2 - 8" Type: GRAVELLESS No. of Feet: 240'

Gravel Drainfield (if applicable): Natural: N/A Crushed: N/A Washed: N/A

Amount: N/A Yards or Tons

Gravel Generally Consistent 12" depth throughout field N/A Yes No

Porous Media Uniform (0.72-2.0 inches) N/A Yes No

General Conditions and Workmanship:

Solid Lines from House Schedule 40 with Cleanout V/L Yes No

T's Installed at least 25% of Liquid Level Yes No

Inlet and Outlet Flow Clearly Marked Yes No

Manufacturer's Name, Address, & Tank Capacity Visible Yes No

Port Holes 12" in Diameter Yes No

Septic Tank Sturdy & Water-Tight Yes No

Trench or Bed Bottom Essentially Level Yes No

Perforated Pipe Generally Level throughout Field Yes No

End Caps provided on Drainfield (if not looped) Yes No

Geo-Textile Fabric used for Permeable Soil Barrier Yes No

Installer: JOSE A. GONZALEZ License#: 35502

Remarks: 240' x 4' = 960 sq. ft.

PRE-INSTALLATION OSSF

Inspector: A. FLORES License#: 38768

Date of Inspection: 03/25/2025