

 TEDSI TBPE F-1640	TEDSI INFRASTRUCTURE GROUP <i>Consulting Engineers</i> 1201 East Expressway 83 ♦ Mission, Texas 78572 Tel: (956) 424-7898 Fax: (956) 424-7022	<h1>Status Report</h1>
	PROJECT: Trenton Roadway Improvements, From US 281(I-69C) to FM 907 (Alamo Road)	
CLIENT: Hidalgo County Precinct 4	DATE: February 9, 2026	
SUBJECT: Status Report for February 1, 2026, through February 28, 2026 (Final Report WA #1)		
FROM: Ponciano N. Longoria, P.E., CFM		

**Project Development Phase I
Work Authorization No. 1**

Project Development (Management)

Task	Status	Description
Subconsultant Contracts	Completed	Completed
AFA Development	Completed	Completed
Supplemental Agreements	Completed	Completed
City of Edinburg funding	Completed	Completed
Invoicing	Completed	Submitted, #33 and Submitting Final Invoice #34
Project Administration	Completed	Completed
DCC Meeting	Completed	June 14, 2024

Aerial and Topographic Surveying Services (CobbFendley)

Task	% Complete	Status
Flight planning	100%	Completed
Topographic planning	100%	Completed
Control Planning	100%	Completed
QA/QC of above tasks	100%	Completed

Schematic

Task	% Complete	Status
Survey research TxDOT R/W	100%	Completed
Survey research and plot Subdivisions	100%	Completed
Deed research	100%	Completed
Field Survey planning	100%	Completed

Future Task(s)

Task	% Complete	Status
Set project primary control points	100%	Completed
Set control points for Aerial LiDAR	100%	Completed
Aerial Lidar Flight & ground topo collection of data and processing	100%	Completed
Field Survey right-of-way	100%	Completed
Office processing right-of-way strip maps	100%	Completed

Environmental Services (GDJ Engineering)

Task	% Complete	Status
Environmental Document	100%	Completed
Public Involvement (Meeting)	100%	Completed
Archeological & Historical Research	100%	Completed
Public Involvement (Hearing)	100%	Completed
Environmental Clearance	100%	Completed
Project Management/Coordination	100%	Completed

Geotechnical Services (Millennium Engineering Group)

Task	% Complete	Status
Laying out needed drilling & plan view of bore locations, PM/Sr. Engineer	100%	Completed
Project site visits	100%	Completed
Drilling Coordination	100%	Completed
Drilling Activities	100%	Completed
Lab Testing	100%	Completed
Engineering Analysis	100%	Completed
Report Development	100%	Completed
Engineering Review	100%	Completed
Draft Report Review by team	100%	Completed
Final Engineering Review and Report Finalization	100%	Completed

Schematic

Task	% Complete	Status
Development of Schematic	100%	Completed.
Hydrological Map (H&H Study)	100%	Completed.
Bridge Layout (Scour)	100%	Completed.
Public Involvement (Meeting)	100%	Completed.
Utility Coordination	100%	Completed
Public Involvement (Hearing)	100%	Completed
Traffic Signal Warrant Studies	100%	Completed
Traffic Level of Service Analyses	100%	Completed
Traffic Projections	100%	TXDOT Approved. Completed
Traffic Movement Counts	100%	Completed.