



Pharr, Texas 78577
San Benito, Texas 78556
Laredo, Texas 78041

INVOICE
Invoice Date: 07/31/2026
Invoice No: 26-07-0118

Client Address: Hidalgo County Precinct 3

724 Breyfogle Road

Mission, TX. 78574 USA

Account No.: HCP32022
Project No: 01-25-19104
Project Desc.: La Mansion Health Clinic

La Mansion Health Clinic | ARPA-23-340-330
PO. 26200686
Acct. # 1290-41-115-000-0000-507300

===== Invoice Detail by Report =====

Report No.	Sampled	Qty	Billing Code	Unit Type	Unit Rate	Extension
44968-1	07/24/2026	1.00	C300 - Air Content (Pressure)	Each	\$25.00	\$25.00
44968-1	07/24/2026	4.00	C303 - Concrete Specimen (Compression)	Each	\$16.00	\$64.00
44968-1	07/24/2026	2.00	M500-1 - Vehicle Trip Charge (Concrete)	Each	\$55.00	\$110.00
44968-1	07/24/2026	1.00	M501 - Clerical	hourly	\$78.00	\$78.00
44968-1	07/24/2026	1.00	M510 - Project Management (hourly)	Hour	\$105.00	\$105.00
44968-1	07/24/2026	2.00	M520 - Test Report (each)	Report	\$40.00	\$80.00
44968-1	07/24/2026	1.00	P101 - Project Engineer (hourly)	Hour	\$180.00	\$180.00
44968-1	07/24/2026	9.00	T704 - Concrete Engineering Technician	Hour	\$90.00	\$810.00
Client PO Nbr: 876819						
Report Number 44968-1 for a Subtotal of:						\$1,452.00
Total for this Invoice:						\$1,452.00

APPROVED
By Jesse Ramos at 8:15 am, Aug 19, 2026

REMIT TO: Millennium Engineers Group, Inc.
PO BOX 4569
Edinburg, Texas 78540

Net 30 Days



Area Offices

5804 N. Gumwood Ave.	Pharr, Texas 78577	956-702-8500
30745 E. Exp 83	San Benito, Texas 78586	956-300-2500
5918 McPherson Rd., Ste. 5	Laredo, Texas 78041	956-552-8200

Report On: Air Content & Slump

Lab No: 44968-1

Report No: 44968-1

Project No: 01-25-19104

Acct. No.: HCP32022

Page 1 of 1

Client: Hidalgo County Precinct 3
724 Breyfogle Road
Mission, TX 78574

Project: La Mansion Health Clinic

Report Date: 07/25/2026

Sample Date: 07/24/2026

Sampled By: Perez, Javier

By Order Of: Darrell Amador

Client PO: 876819

Field ID: 01-25-19104

Location: Transformer Pad

Material: Set# 8=4(4x8) Cylinders

Spec Nbr	Sampled At	Truck No	Total Yards	Ticket No	Water Added	Mix Code	Time Sampled	Amb Temp (°F)	Mix Temp (°F)	Slump (In.)	Air %
1	Truck	10	5	22949	No		09:12 am	85	87	6.00	2.00

Placement Location: Tranformer Pad on NWC, 80' NW og Bldg

Date Tested: 07/24/2026

Source: BH Ready Mix LLC.

Plant: 01

Remarks: On 07/25/2026, a representative of Millennium Engineers Group, Inc. was dispatched to the project site to pick up the specimens cast on the previous day. The specimens were transported to the laboratory where they were stripped from their forms, properly labeled, and placed in curing tanks in preparation for compressive strength testing intervals of 7 and 28 days.

Test Method (As Applicable): Unless noted, concrete was sampled and tested in accordance with ASTM C172, C143, C231, C1064, C1231/C617, C1054 and C138. Compressive strength tests per ASTM C39, C31.

Respectfully Submitted,
Millennium Engineers Group, Inc.


Juan Borjon, P.E.

