

Gregory Lane and Chantry Drive

(Curb Ramp, Spandrel, and Cross Gutter-Removal and Replacement)



Gregory Ln and Chantry Dr – Pre-Construction Condition
(from Google Earth, March 2019), facing North West



Gregory Ln and Chantry Dr – Concrete Demolition,
facing South



Gregory Ln and Chantry Dr – Paving Preparation, facing North



Gregory Ln and Chantry Dr – Completed Curb Ramp, Spandrel, Cross Gutter, Asphalt (Gregory Ln), and Slurry Seal (Chantry Dr)

Gregory Lane

(Asphalt Milling and Paving)



Gregory Ln – Pre-Construction Condition (from Google Earth, December 2020), facing North East



Gregory Ln – Milled Asphalt Surface, facing NW

Gregory Lane

(Asphalt Milling and Paving)



Gregory Ln – Placing Asphalt, facing East



Gregory Ln at Dexford Dr – Final Concrete, Striping, Cross Gutter and Spandrels, facing East

Galen Dr, Berkley Dr. and Kinley St. Crack Seal and Slurry Seal Resurfacing



Crack Seal (Typical)



Kinley St – Slurry Seal Application, facing North

Galen Dr, Berkley Av. and Kinley St

Crack Seal and Slurry Seal Resurfacing



Berkley Av – Completed Slurry Seal, facing East



Galen Dr – Slurry Seal Application, facing North East

Speed Lumps and Striping



Painted Speed Lumps (typical)



Dexford Dr and Morris Ave - Set-to-Grade Covers (typical) and Painted Crosswalks, facing NE