

Cummins, Kandee

From: Arocho, Andres
Sent: Friday, June 12, 2026 10:09 AM
To: Cummins, Kandee
Subject: Fw: 3326 camden

Andres Arocho

Housing Inspector Supervisor
City of Lorain
200 West Erie Ave – 5th Floor
(440) 204 – 2301 - Office
(440) 752 – 6497 - Cell
Andres_Arocho@cityoflorain.org



From: William Lundberg <wrlundberg@live.com>
Sent: Thursday, June 11, 2026 4:11 PM
To: Arocho, Andres <Andres_Arocho@cityoflorain.org>
Subject: 3326 camden

Warning: Unusual link

This message contains an unusual link, which may lead to a malicious site. Confirm the message is safe before clicking any links.

Tore off front concrete steps that were un repairable. Installed gas lines and got gas turned on. Textured all the ceilings in entire home. Installed all lights in basement and throughout the house
[1000011696.jpg](#)
[1000011695.jpg](#) [1000011676.jpg](#) [1000011697.jpg](#) [1000011675.jpg](#) [1000011689.jpg](#) [1000011678.jpg](#)
[1000011677.jpg](#) [1000011679.jpg](#) [1000011690.jpg](#) [1000011692.jpg](#) [1000011681.jpg](#) [1000011691.jpg](#)
[1000011680.jpg](#) [1000011694.jpg](#) [1000011693.jpg](#)

Sent via the Samsung Galaxy S24 Ultra, an AT&T 5G smartphone
Get [Outlook for Android](#)



gas line installed



installed lights in basement



installed lights in basement



gas line installed



gas line installed



gas line installed



gas line installed




living room textured ceiling
and installed lights



A photograph of a kitchen during renovation. The ceiling is a white, heavily textured popcorn finish. Three recessed ceiling lights are installed, with two of them turned on, casting a bright glow. A white door with a semi-circular window is on the left. The back wall features a window with a gold frame, and the lower portion of the wall is painted blue. A black metal shelving unit on the right holds various items, including a roll of paper towels and a red bucket. A blue Kobalt power tool is on the floor in the foreground.


textured ceiling and installed
lights kitchen



front bedroom
textured ceiling and installed
lights




back bedroom
textured ceiling and installed
lights

A photograph of a hallway under renovation. The ceiling is a light-colored, textured material. Several round pendant lights are suspended from the ceiling. The walls are white, and a door is visible on the right. The floor is concrete, and there are some cables and a piece of plywood on the floor. The hallway leads to a room with a window and a door leading outside.

1st floor hall textured ceiling
and installed lights



A photograph of an upstairs hallway during a renovation project. The walls are white, and the ceiling has a textured finish. Two circular light fixtures are installed on the ceiling. The floor is made of wooden planks and is covered with dust and debris. A doorway at the end of the hallway leads to another room with a window and some construction equipment. On the right side of the hallway, there are two stacked buckets of paint, one green and one white. The text "upstairs hall. textured ceiling and installed lights" is overlaid at the bottom of the image.

upstairs hall.
textured ceiling and installed
lights