

Photo taken August 2023. This photo shows the attempted corrections by the property owner which have brought the property into a more deteriorated state.





Photo above taken in July Of 2021. Shows the homes conditions deteriorating. Where Code Enforcement began conversations with property owner and owners agent on either repairing, selling or removing structure.

Photo taken June 2023, showing roof of garage collapsing.





Photos taken August 2022 from sidewalk in front of home through front window opening.



Photos Taken in October 2020 By Building Inspections Department

