

Front Door / Windows / Soffits / West Exposure (repaired)



Window Fixed / Windows Painted / Soffits (repaired)



Inside Facing E (Cleaned)



Coatroom (Cleaned)

