

Pergola and Shelter Roof Replacement – Emerald Pond Park



Archive pergola photo from time of installation (early 1990's)



View from 'front' with center fountain (2017)



'Interior' views demonstrating column tilt from decayed base ↕





Pergola area existing conditions (June 2018) ↓





36' Hexagonal Shelter at Emerald Pond Park



Shingle conditions (June 2018)