

Location	Condition	Name
109 E SUMMIT ST 109 E SUMMIT ST #1/2 SOUTH ROSWELL Block 53 Lot E 50' W 220' S 140'	Dilapidated/ Deterioration Open To Public, Inadequate Maintenance	GEORGE VIGIL; IDA M VIGIL 305 THREE CROSS DR ROSWELL, NM 88201
1600 N UNION AVE YUCCA Block 1 Lot 10 Quarter SW S 29 T 10S R 24E (ALL STRUCTURES)	Dilapidated/ Deterioration Open To Public, Inadequate Maintenance	CATHERINE L DUNWOODY 1600 N UNION AVE ROSWELL, NM 88201
2311 SHARTELLE AVE ROGERS Block 2 Lot 18 Quarter NW S 28 T 10S R 24E (ALL STRUCTURES)	Dilapidated/ Deterioration Open To Public, Inadequate Maintenance	RAMON SANCHEZ GRADO 2311 SHARTELLE AVE ROSWELL, NM 88201
1703 N DELAWARE AVE CRESCENT HEIGHTS Block 3 Lot 11 Quarter SW S 29 T 10S R 24E	Dilapidated/ Deterioration Open To Public, Inadequate Maintenance	GARCIA, VIRGINIA C/O JACOB LARA 6577 WILLIAMSBURG PL STOCKTON, CA 95207

109 E SUMMIT ST
109 E SUMMIT ST #1/2



1600 N UNION AVE



2311 SHARTELLE AVE



1703 N DELAWARE AVE

