

Ceda-Tex Svcs INC.

500 Brushy Creek Road
Suite 306
Cedar Park, Texas 78613
512-339-0155

Estimate

Date	Estimate #
8/14/2015	2033

Name / Address
Williamson County Facilities Maintenance 3101 SE Inner Loop Georgetown, TX 78626 Dale Butler

			Project
Description	Qty	Rate	Total
Room 111 CSI #1 Labor and Material to: Cut opening, Remove Grid and tiles Frame walls, Sheetrock walls, Install Doors Frames, Doors /Hardware Patch wall above ceiling New ceiling system Labor and material		7,684.80 7,535.00	7,684.80 7,535.00
Room 112 CSI #2 Labor and Material to: Demo wall and Ceiling tiles Frame walls, Sheetrock walls, Install Doors Frames and Door/Hardware Repair ceiling grid and Tiles		8,984.80	8,984.80
Thank you for your business.		Total	\$24,204.60