

DB Dale Butler
RE: Grease Trap Leak

To Melissa Gurka

The Jail Kitchen primary grease trap tank is corroded and leaking in multiple areas. It is necessary to replace the tank to prevent further leakage as it cannot sufficiently be repaired.

Dale Butler

Facilities Director Williamson County 3101 SE Inner Loop Georgetown, TX 78626 512-943-1609

NOTICE OF CONFIDENTIALITY: The information in this communication is confidential and intended only for the exclusive use of the addressee. The copying, distribution, or other use of this communication by the addressee or any other person or entity is prohibited. If you have received this communication by mistake, please notify the sender immediately and destroy all forms of this communication.

From: Melissa Gurka

Sent: Tuesday, July 24, 2018 2:06 PM To: Dale Butler <<u>dbutler@wilco.org</u>> Subject: RE: Grease Trap Leak

Dale,

Please provide justification for the agenda item back up.

Thank you!

Melissa Gurka

Purchasing Specialist II

Williamson County Purchasing Department

901 South Austin Ave. Georgetown, TX 78626 Direct Line: (512) 943-3860

Fax: (512) 943-1575

"A true professional not only follows but loves the processes, policies and principles set by his profession."

- Amit Kalantri