

# Benjamin Benavides BB Fitness Repair sent you an estimate

Please let me know if you approve or have any questions. If Approved a payment of 50% down will need to be paid for parts orders.

#### Customer

Williamson County Emergency Services Damaris M. damaris.morales@wilco.org +1 (512) 422-4363 911 Tracy Chambers Ln Georgetown , Texas 78626

### Estimate #000695

June 14, 2023

Hide full details ^

## **BB Fitness Repair repair bid**

## **Annual Fitness Center Maintenance**

\$360.00

Test operation of equipment, inspect wear items, lubricate and tension walking surfaces of treadmills, tighten loose hardware, lubricate guide rods on weight machine, tighten pedals and cranks for ellipticals and bikes. Provide customer with status of equipment after the visit.

## **Anticipated Additional Repairs**

\$440.00

Up to a \$440 credit toward any parts or additional service needed for repairs in the fitness center.

Subtotal \$800.00

Total \$800.00

## Benjamin Benavides BB Fitness Repair

fitnesssvc@austin.rr.com +1 (512) 759-1118

© 2023 Block, Inc. All rights reserved.

Square Privacy Policy | Security

Square