

ATT. H

SITE PHOTOS



Generator installed without permits (3.20.25)



Generator installed without permits (opposite side) (3.20.25)



Debris pile from greenhouses (11.26.24)



Inside damaged greenhouse (3.20.25)



Damaged greenhouse (3.20.25)



Damaged greenhouses and debris (3.20.25)



Site conditions in 2022 (submitted by applicant as part of application submittal)



Site conditions in 2022 (submitted by applicant as part of application submittal)



View inside typical greenhouse in 2022 (submitted by applicant as part of application)